

E83-10260  
15-236-1019-1575  
NASA-CR-170525

SEPT 1982

# THEMATIC MAPPER

THEMATIC MAPPER

THEMATIC MAPPER

Made available under NASA sponsorship  
in the interest of early and wide dissemination of Earth Resources Survey  
Program information and without liability  
for the use of the information made for



(E83-10260) THEMATIC MAPPER FLIGHT MODEL  
PRESHIPMENT REVIEW DATA PACKAGE, VOLUME 2,  
PART C: SUBSYSTEM DATA Final Report (Santa  
Barbara Research Center) 199 p  
HC A09/MF A01

N83-26129

Unclas  
00260

CSCL 14B G3/43

THEMATIC MAPPER

Prepared for  
GODDARD SPACE FLIGHT CENTER  
Greenbelt, Maryland 20771  
CONTRACT NAS 5-24200

FLIGHT MODEL  
PRESHIPMENT REVIEW  
DATA PACKAGE  
VOLUME II - SUBSYSTEM DATA  
PART C

Article IV - 3A

**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP



BEST AVAILABLE COPY



Prepared for  
GODDARD SPACE FLIGHT CENTER  
Greenbelt, Maryland 20771  
CONTRACT NAS 5-24200

SEPT 1982

FLIGHT MODE!  
PRESHIPMENT REVIEW  
DATA PACKAGE  
VOLUME II - SUBSYSTEM DATA  
PART C

Article IV - 3A

**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP

Hughes Ref No. D4598 •



ORIGINAL PAGE IS  
OF POOR QUALITY

THEMATIC MAPPER  
FLIGHT MODEL  
PRESHIPMENT REVIEW  
VOLUME II  
SUBSYSTEMS  
TABLE OF CONTENTS

	<u>Section</u>
1.0 INTRODUCTION	1.0
2.0 SUBSYSTEMS ACCEPTANCE DATA	
Multiplexer Assembly	2.1
Multiplexer Summarized Performance	2.1.1
Multiplexer Acceptance Data	2.1.2
Scan Mirror Assembly	2.2
Scan Mirror Summary Performance	2.2.1
Scan Mirror Acceptance Data	2.2.2
Power Supply Assembly	2.3
Power Supply Summarized Performance	2.3.1
Power Supply Acceptance Data	2.3.2
Mainframe/Top Mechanical Assembly	2.4
Mainframe/Top Mechanical Summarized Performance	2.4.1
Mainframe/Top Mechanical Acceptance Data	2.4.2
Aft Optics Assembly	2.5
Aft Optics Summarized Performance	2.5.1
Aft Optics Acceptance Data	2.5.2
Focal Plane Assembly	2.6
Focal Plane Summarized Performance	2.6.1
Focal Plane Acceptance Data	2.6.2
Radiative Cooler	2.7
Radiative Cooler Summarized Performance	2.7.1
Radiative Cooler Acceptance Data	2.7.2

ORIGINAL PAGE IS  
OF POOR QUALITY

THEMATIC MAPPER  
FLIGHT MODEL  
PRE SHIPMENT REVIEW  
VOLUME II  
SUBSYSTEMS

TABLE OF CONTENTS  
(Continued...)

	<u>Section</u>
Radiative Cooler Door Assembly	2.8
Radiative Cooler Door Summarized Performance	2.8.1
Radiative Cooler Door Acceptance Data	2.8.2
Top Optical Assembly	2.9
Top Optical Summarized Performance	2.9.1
Top Optical Acceptance Data	2.9.2
Telescope Assembly	2.10
Telescope Summarized Performance	2.10.1
Telescope Acceptance Data	2.10.2
Relay Optics	2.11
Relay Summarized Performance	2.11.1
Relay Acceptance Data	2.11.2
Electronics Module	2.12
Electronics Summarized Performance	2.12.1
Electronics Acceptance Data	2.12.2
Cable Harness	2.13
Cable Harness Summarized Performance	2.13.1
Cable Harness Acceptance Data	2.13.2



ORIGINAL PAGE IS  
OF POOR QUALITY

## 2.0 Subsystems Acceptance Data

Each of the major subsystems of the Flight Model Thematic Mapper was reviewed as an entity prior to integration into the system. The intent of this section is to present for each major subsystem, acceptance data for the subsystem (test results); reference lists of the configuration status; and reference lists of Non-Conforming Material Reports, Failure Reports (with copies), and Requests for Deviation/Waiver (with copies).

The acceptance data for each subsystem (where applicable) is contained in the Appendix to this report, as referenced in the first subsection for each subsystem.

The second subsection for each subsystem contains a tabular summary of the "as designed" and "as built" configuration lists, showing all applicable drawings, specifications, or standards. (An "as built" configuration list for the total system is included in Volume I and is also included herein immediately following this page). This is followed by a listing of all items against the subsystem, with copies of NCRM's, RT's, and RD/W's.

SUMMARY  
AS-BUILT CONFIGURATION LIST  
TM FLIGHT S/N 003

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	51065	THEMATIC MAPPER ASSY	J 4257A 4487A 4557A 4573A 4643A 4658A D143R1 D144 D146 D148 D155 D158 D161 D162 D163 D164 D165 W166 W169 W170 W171R1 W173	J 4257A 4487A 4557A 4573A 4643A 4658A D143R1 D144 D146 D148 D155 D158 D161 D162 D163 D164 D165 W166 W169 W170 W171R1 W173	J 4257A 4487A 4557A 4573A 4643A 4658A D143R1 D144 D146 D148 D155 D158 D161 D162 D163 D164 D165 W166 W169 W170 W171R1 W173	003
2	50840	MAIN FRAME ASSY	E	E	E	003
2	52347	ELECTRONICS MODULE ASSY	D 4588A	B 4091A 4113A 4242A 4293A	B 4091A 4113A 4242A 4293A	201

ORIGINAL PAGE IS  
OF POOR QUALITY

THD LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUM
3	3533003-100	MULTIPLEXER ASSY	C 43009 43074 65661 65662 W124 W125	C 43074 65661 65662 W124 W125	C 43009 43074 65661 65662 W124 W125	003
3	50869	POWER SUPPLY ASSY	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	D 2015A 2039A 4347A D030 D068 W074 W092 W093 W101	004
3	52348	CABLE ROUTING ASSY	F 3844A	F 3844A	F 3844A	005
2	52532	OPTICAL ASSY	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	F 3174A 4100A 4187A 4266A 4488A 4559A 4656A D-151 D-154 W-148	003
3	51512	AFT OPTICS ASSY	E 3646A 3925A 3959A 4585A	D 3646A 3896A 3925A 3959A 4134A	D 3646A 3896A 3925A 3959A 4134A	001

ORIGINAL PAGE IS  
OF POOR QUALITY



IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
4	50795	PRIME FOCAL PLANE ASSY	J W126	H 3934A 3963A 3982A W126	H 3934A 3968A 3982A W126	201
3	51200	RADIATIVE COOLER ASSY	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	E 3922A 4201A 4216A 4269A SB-W032 W144 W147 W149 W151	003
4	50973	COLD FOCAL PLANE ASSY	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	B 2870A 3895A 4173A SB-D004 W102R1 W109 W111 W134 W135	201
3	51337	TELESCOPE ASSY	D 3866A 3917A W129 W136	D 3866A 3917A W129 W136	D 3866A 3917A W129 W136	002

ORIGINAL PAGE IS  
OF POOR QUALITY

TND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	52534	RELAY OPTICS ASSY	D 1145A 4097A	D 1145A 4097A	D 1145A 4097A	003
2	3533002-100	SCAN MIRROR ASSY	E	D 13121 13122 64358 64363 64369 64374 W020	D 13121 13122 64358 64363 64369 64374 W020	004

ORIGINAL PAGE IS  
OF POOR QUALITY

2.11

ORIGINAL PAGE IS  
OF POOR QUALITY

SECTION 2.11  
RELAY OPTICS



2.11.1

ORIGINAL PAGE IS  
OF POOR QUALITY

2.11.1 Relay Optics

2.11.1.1

No performance data was taken at the subsystem level on this subsystem.

2.11.2

ORIGINAL PAGE IS  
OF POOR QUALITY

2.11.2

Acceptance Data

2.11.2.1

ORIGINAL PAGE IS  
OF POOR QUALITY

2.11.2.1

Configuration Lists



## AS-BUILT CONFIGURATION LIST

RELAY OPTICS ASSY

P/N 52534 S/N 003, FLIGHT

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPY. REVISION	AS-BUILT REVISION	SERIAL NUMBER
1	52534	RELAY OPTICS ASSY	D + 1145A 4097A	D + 1145A 4097A	D + 1145A 4097A	003
2	50845	RELAY OPTICS BASE	C	C	C	003
2	50846	RELAY OPTICS HOUSING	D	D	D	003
2	51339	FOLDING MIRROR ASSY	A	A	A	003
3	50857	MIRROR, FOLDING	B	B	B	005
2	51340	SPHERICAL MIRROR ASSY	A	A	A	003
3	50855	MIRROR, SPHERICAL RELAY	B	B	B	005
2	51342	TRANSLATOR, INCHWORM	B + 9721	B + 9721	B + 9721	5426 5428 5436
2	53412	THERMISTOR ASSY	B + 1120A 3801A	B + 1120A 3801A	B + 1120A 3801A	202
2	53414	TRANSFORMER ASSY	A	A	A	204 205 206
2	53744	ELECTRONIC ASSY, RIGHT BANK- IPS	A + 9552 9710 2924A 3817A	A + 9552 9710 2924A 3817A	A + 9552 9710 2924A 3817A	201
2	53753	ELECTRONIC ASSY, LEFT BANK- IPS	B + 3810A	A + 9551 1842A 2949A 3810A	A + 9551 1842A 2949A 3810A	201

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52534


D L	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPY. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	53749	ELEX ASSY-OUTPUT ASSY-IPS	C + 3808A	C + 3808A	C + 3808A	201 202 203
	52024-1	PWB ASSY-IPS	B	A + 7579 8385 8669 8964 9040	A + 7579 8385 8669 8964 9040	107 108 109 201 205 209
	52024-2	PWB ASSY-IPS	B	A + 7579 8385 8669 8964 9040	A + 7579 8385 8669 8964 9040	102 104 105
	52029	PWB ASSY-IPS	B	B	B	104 202 203
	53746	ELEX ASSY-OUTPUT PWB-IPS	A + 9597 9682 1706A	A + 9597 9682 1706A	A + 9597 9682 1706A	102 201 203
	53757	ELEX ASSY-REGULATOR MODULE	B + 3916A 4116A	A + 9277 9865 1289A 2086A 2102A 3916A 4116A	A + 9277 9865 1289A 2086A 2102A 3916A 4116A	201
	53754	ELEX ASSY-100V REGULATOR	A + 9862 1705A D039R1	A + 9862 1705A D039R1	A + 9862 1705A D039R1	201

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52534

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
4	52041	PWB ASSY, XFMR-MOUNTING	B	A + 8673 9256 9731 9828 1704A 1717A	A + 8673 9256 9731 9828 1704A 1717A	205
5	50875	CHOKE	B	A + 8443 1356A	A + 8443 1356A	F104

 3-25-82  
Quality Assurance

 3-25-82  
Configuration Management

ORIGINAL PAGE IS  
OF POOR QUALITY



ORIGINAL PAGE IS  
OF POOR QUALITY

Listing of Liens

RELAY OPTICS

P/N 52534

FLIGHT

ORIGINAL PAGE IS  
OF POOR QUALITY

Failure Reports Number

<u>Open</u>	<u>Closed</u>
	F0553
	F0555
	F1669
	F1744
	F1747
	F1748

Deviation

Waivers

--	--

ORIGINAL PAGE IS  
OF POOR QUALITY

RELAY OPTICS

P/N 52534

FLIGHT  
Failure Report  
No.

PROTOFLIGHT  
Failure Report  
No.

ENGINEER  
Failure Report  
No.

Open	Closed	Open	Closed	Open	Closed
	F0553		F0584		F0511
	F0555		F1708		F0514
	F1669		F1710		F0519
	F1744		F1711		F0520
	F1747		F1762		F0526
	F1748		F1763		F1731
			S8011		
			S8046		

ORIGINAL PAGE IS  
OF POOR QUALITY

HUGHES

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
FAILURE REPORT

F 0553

1. PROGRAM NAME AND NUMBER <b>TM</b>		2. QLA	3. MODEL <b>F-1</b>	4. TIME OBSERVED <b>16:00</b>	5. DATE OBSERVED <b>2 25 82</b>
6. HARDWARE LEVEL HARDWARE FAILURE HARDWARE OBSERVED		<input type="checkbox"/> AIRCRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	SN
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<b>RELAY OPTICS ASSY</b>		<b>52534</b>	<b>003</b>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input type="checkbox"/> UNPROCESSED <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> ALTITUDE <input type="checkbox"/> HUMIDITY <input type="checkbox"/> OTHER		<input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <b>INCHWORM NO. 2 COMMAND ON TEST BOX (USING FLIGHT IPS) YIELDS NO MOTION IN "DOWN" (RETRACT) DIRECTION. R.O. MOUNTED ON DUMMY A.D. PLATE, WITH .070 SHIP TO "RELAX" SPHERICAL MIRROR DIAPHRAGM</b>					
15. TEST PROCEDURE <b>SEE FR 0555</b>		16. ORIGINATOR <b>W. B. B...</b>		17. DATE <b>22-35</b>	18. CONTINUATION SHEET USED <b>2-298</b>
19. VERIFICATION AND FAILURE ANALYSIS <b>FOUND MISSING WIRE IN TEST CABLE - L3</b> <b>MISSING FROM CABLE CONNECTING BREAKOUT BOX TO WEERSAUER</b>					
20. FOLLOWING REMEDIAL ACTION REQUIRED <b>L3 WIRE INSTALLED AS REQUIRED. UNIT WAS IN TEST CONFIGURATION NO OVERSTRESS TO POWER SUPPLY WAS EXPERIENCED</b>					
21. AUTHORIZED BY <b>W. B. B...</b>		22. DATE <b>22-35</b>		23. CONTINUATION SHEET USED <b>2-298</b>	
24. REMEDIAL ACTION TAKEN <b>L3 WIRE INSTALLED.</b>					
25. LIST ALL PARTS REPLACED					
26. WORK ORDER <b>W. B. B...</b>					
27. TESTED BY <b>W. B. B...</b>					
28. CAUSE AND CORRECTIVE ACTION <b>WORKMANSHIP AND INSPECTION DISCREPANCY</b> <b>ALL PERSONNEL INVOLVED HAVE BEEN ADVISED OF PROBLEM AND CAUTIONED TO CHECK CABLES OF TEST EQUIPMENT FOR PROPER INPUT AND OUTPUT CONNECTIONS.</b> <b>CAUSED BY ENGINEERING ERROR. ENGINEER REQUESTED A SPECIAL TEST CABLE BE</b>					
29. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP. <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DESTRUCTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
30. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
31. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
32. RESPONSIBLE ENGINEER <b>W. B. B...</b>		33. DATE <b>22-35</b>		34. SPACECRAFT SYSTEM ENGR. <b>W. B. B...</b>	
35. RELIABILITY <b>W. B. B...</b>		36. DATE <b>22-35</b>		37. CUSTOMER OR SUPPLIER <b>W. B. B...</b>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT  
CONTINUATION SHEET

FR SERIAL NO.

FD553

CONTINUATION SHEET LETTER\*

A

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

☒ IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED ☐

30 FABRICATED FOR THIS TEST. HE MARKED UP A COPY  
OF THE SCHEMATIC DRAWING TO SHOW LEADS  
REQUIRED FOR THIS TEST. HE THOUGHT THE TWO  
+5V LINES, K3 AND L3 WERE REDUNDANT, THEREFORE  
HE DID NOT REQUEST L3 BE WIRED IN. THE ENGINEER  
INVOLVED IN THIS DISCREPANCY IS AWARE OF THE  
ERROR. HE WILL DISPLAY MORE CAUTION IN THE FUTURE.

ORIGINAL PAGE IS  
OF POOR QUALITY

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F** 0555

1. PROGRAM NAME AND NUMBER <b>TM</b>		2. OLA	3. MODEL <b>F-1</b>	4. TIME OBSERVED <b>17:30</b>	5. DATE OBSERVED <b>NOV 13 82</b>
6. HAZARD LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. OVERSYSTEM		NAME		PART NUMBER	S/N
8. UNIT <b>RELAY OPTICS ASSY</b>				<b>52534</b>	<b>003</b>
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN PROGRESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ACCELERATION <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> VIBRATION <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> KRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>INCHWORM NO. 2 COMMAND ON TEST BOX YIELDS LOW MV READINGS PER STEP DURING FIRST STEPS IN EITHER DIRECTION. SUBSEQUENT STEPS IN "DOWN" DIRECTION ARE SMALL, APPROX 1 TO 2 MV.</b>					
15. TEST PROCEDURE		16. ORIGINATOR <b>W. Balinski</b>	17. DATE <b>12-35 12-13-82</b>	18. CONTINUATION SHEET USED	
19. VERIFICATION AND FAILURE ANALYSIS <b>SUBSEQUENT OPERATION IN RETRACT ("DOWN") DIRECTION NEARER TO OPTICAL ALIGNMENT POSITION YIELDS LITTLE OR NO MOVEMENT. LVDT CLAMP LOOSENING SHOWN PROBLEM TO BE INDEPENDANT OF LVDT ALIGNMENT.</b>					
20. FOLLOWING REWORK/RETEST REQUIRED <b>L3 WIRE TO BE INSTALLED IN TEST CABLE UNIT WAS IN TEST CONFIGURATION. NO OVERSTRESS TO POWER SUPPLY WAS EXPERIENCED.</b>					
21. AUTHORIZATION <b>W. Balinski</b>		22. DATE <b>22-35 1</b>	23. CONTINUATION SHEET USED		
24. CAUSE AND CORRECTIVE ACTION <b>L3 WIRE INSTALLED AS REQUIRED.</b>					
25. CAUSE AND CORRECTIVE ACTION <b>ENGINEER REQUESTED A SPECIAL TEST CABLE BE FABRICATED FOR THIS TEST. HE MARKED UP A COPY OF SCHEMATIC TO SHOW LEADS REQUIRED FOR THIS TEST. HE THOUGHT K3 AND L3 WERE REDUNDANT BOTH ARE +5V LINES, THEREFORE HE DID NOT REQUEST L3 BE WIRED IN. THE ENGINEER INVOLVED IS AWARE OF THE DISCREPANCY AND WILL BE MORE CAUTIOUS.</b>					
26. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIP. <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
27. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
28. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
29. RESPONSIBLE ENGINEER <b>W. Balinski</b>		30. DATE <b>12-35 3-12-82</b>	31. SPACECRAFT SYSTEM ENGR. <b>J. Campbell</b>		
32. RELIABILITY <b>W. Balinski</b>		33. DATE <b>51-41 3-12-82</b>	34. CUSTOMER OR SUPPLIER <b>W. Balinski</b>		

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**  
HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F 1669**

1. PROGRAM NAME AND NUMBER <b>THEMATIC MAP</b>		2. GLA <b>DESIGN</b>	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>0900</b>	5. DATE OBSERVED <b>FEB 3 82</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>RELAY OPTICS</b> <b>52534</b> <b>3</b> <b>SBRL</b>					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <b>PRE</b> <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> SPECIAL - VACUUM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <b>ROOM</b> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MRS. AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>LEFT BANK LVDT DOES NOT REVERSE</b> <b>RIGHT BANK DOES NOT RESPOND</b>					
15. TEST PROCEDURE <b>JTR FL-003 PARA 16</b> 16. ORIGINATOR <b>L. CRISS</b> 17. CONTINUATION SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS <b>ELECTRICAL TRAILER SHOOTING SHOWS OPEN WIRE IN P2 OF FLIGHT CABLE AND WIRE WAS MISSING IN WEARSAVER CABLE. UNIT WAS IN TEST CONFIGURATION. NO OVERSTRESS OF PARTS OCCURRED.</b>					
19. FOLLOWING REPAIR/RETEST REQUIRED <b>REPAIR FLIGHT CABLE AND WEARSAVER. RETEST RELAY OPTICS, INCHWORM &amp; LVDT</b>					
20. AUTHORIZATION <b>W. Balinski</b> 21. DATE <b>22-35 82-3-8</b> 22. CONTINUATION SHEET USED					
23. REWORK/RETEST ACTION TAKEN <b>REPAIRED FLIGHT CABLE AND WEARSAVER. RETEST SUCCESSFULLY.</b>					
24. LIST ALL PARTS REPLACED PART NUMBER CMT SYN PART LOT NO. DATE CODE WFO PROBABLE DEFECT ANALYSIS NO.					
25. REWORK BY ORG DATE 26. RETESTED BY ORG DATE 27. CONTINUATION SHEET USED					
28. CAUSE AND CORRECTIVE ACTION <b>POOR WORKMANSHIP CAUSED OPENS. ONE DISCREPANCY WAS AN OPEN AT H2 IN CONNECTOR P2, THE OTHER WAS A MISSING WIRE IN WEAR SAVER.</b>					
29. PRE CLOSURE <b>ASSEMBLY TECHNICIANS AND QUALITY CONTROL PERSONNEL WERE ADVISED OF THE DISCREPANCIES AND CAUTIONED TO PREVENT THEIR REOCCURRENCE.</b>					
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
32. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY <input type="checkbox"/> INDUCED					
33. RESPONSIBLE ENGINEER <b>W. Balinski</b> 34. SPACECRAFT SYSTEM ENGR <b>L. Criss</b> 35. DATE <b>22-41 82-3-9</b>					
36. RELIABILITY <b>2</b> 37. DATE <b>151-41 82-8-82</b> 38. CUSTOMER SUPPLIER <b>SA</b>					

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS  
OF POOR QUALITY  
SPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**F1744  
MO 9 DA 29 YR 80

ORIGINATOR	1. PROGRAM NAME AND NUMBER T.M. PL1162		2. GLA V011		3. MODEL F1		4. TIME OBSERVED		5. DATE OBSERVED MO 9 DA 29 YR 80					
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART													
	EQUIPMENT IDENTIFICATION:													
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER					
	8. UNIT													
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		INPS		53757		201		SBRC					
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD													
	11. OTHER		X4PR		52041									
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS													
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> ENC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION													
14. DESCRIPTION OF FAILURE TRANSFORMER (T1) MEASURES OPEN AT SECONDARY CIRCUIT.														
ENGINEERING EVALUATION	15. TEST PROCEDURE 16796		16. ORIGINATOR J. KOPAK		17. CONTINUATION SHEET USED									
	18. VERIFICATION AND FAILURE ANALYSIS TRANSFORMER WAS FOUND TO BE DEFECTIVE PRIOR TO APPLICATION OF POWER.													
	19. FAILED ITEM NAME AND PART NUMBER 52041 (T1)													
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE REPLACE T1 (52041 S/N 202) & RETEST PCL 16796 NOTE: TRANSFORMER P/5094 WAS REMOVED & REPLACED BY PRINTED WIRING BOARD P/N 52041.													
	21. AUTHORIZATION		ORG		DATE									
	22. REWORK/RETEST ACTION TAKEN		TRANSFORMER REPLACED & RETEST REQUIRED. SEE ATTACHED DATA.											
	23. LIST ALL PARTS REPLACED													
	PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUMBER	
	50940		T1											
	MANUFACTURING AND TEST	27. REWORK BY		ORG		DATE		28. RETESTED BY		ORG		DATE		29. CONTINUATION SHEET USED
30. CAUSE AND CORRECTIVE ACTION UNKNOWN. PART LOST BY RELIABILITY. CONTROL OF REMOVED PARTS HAS BEEN CHANGED. PARTS ARE NOW SENT TO MRR ON A NON-CONFORMING MATERIAL REPORT AND DISPOSITIONED AS NECESSARY. PARTS REQUIRING FAILURE ANALYSIS WILL BE SENT TO THE PARTS BOARD ON A 778 FORM (REIT) AND A SHIPPER TO MAINTAIN.														
31. FAB CLOSURE														
32. CONTINUATION SHEET USED														
33. FAILURE CLASSIFICATION														
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		35. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		36. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		37. WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		38. UNKNOWN		DEFECT CODE				
39. FAILURE TYPE		40. UNKNOWN NO FAILURE		41. FAILURE CLASSIFICATION CRITICAL MAJOR		42. MINOR SAFETY		43. SPACECRAFT SYSTEM ENGINEER		44. POWER OR SUPPLIER				
45. RESPONSIBLE ENGINEER		46. DATE		47. DATE		48. DATE		49. DATE		50. DATE		51. DATE		
52. RELIABILITY		53. DATE		54. DATE		55. DATE		56. DATE		57. DATE		58. DATE		
59. DATE														



ORIGINAL PAGE IS  
OF POOR QUALITY

SECTION 2.12  
ELECTRONICS MODULE

ORIGINAL PAGE IS  
OF POOR QUALITY

2.12.1

Section 2.12.2

Electronics Module

Performance Data

The acceptance performance (test) data for the Electronic  
Module is contained in Appendix E of this report  
(Vol. IV, part E).

2.12.2

ORIGINAL PAGE IS  
OF POOR QUALITY

2.12.2  
Acceptance Data

2.12.2.1

ORIGINAL PAGE 13  
OF POOR QUALITY

2.12.2.1  
Configuration Lists

## AS-BUILT CONFIGURATION LIST

ELECTRONICS MODULE ASSY REV 2  
52347 S/N 201

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
2	52347	ELECTRONICS MODULE	D 4588A	B	B	201
				4293A	4293A	
				4242A	4242A	
				4091A	4091A	
				4113A	4113A	
3	3533003-100	MULTIPLEXER ASSY	C	C	C	003
			R43009	43074	43009	
			43074	65661	43074	
			65661	65662	65661	
			65662	W124	65662	
			W124	W125	W124	
			W125		W125	
3	50869	POWER, SUPPLY ASSY	D	D	D	004
			2015A	2015A	2015A	
			2039A	2039A	2039A	
			D030	D030	D030	
			D068	D068	D068	
			W074	W074	W074	
			W092	W092	W092	
			W093	W093	W093	
			W101	W101	W101	
3	50900	PWB ASSY, SERIAL MAGNITUDE COMMAND	C	C	C	002
			3716A	3716A	3716A	
			D046	D046	D046	
			W060R1	W060R1	W060R1	
			W097	W097	W097	

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52347

Shr 2

D I	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEP. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	50904-1	PWB ASSY, POSTAMP BAND #1	G	G	G	101
		NOTE: Configuration will conform to "As Built" pending incorporation of EO 3142A	4072A	4072A	4072A	
			D045	D045	D045	
			D090	D090	D090	
			D105	D105	D105	
			W017	W017	W017	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
			W167	W167	W167	
	50904-2	PWB ASSY, POSTAMP BAND #2	G	G	G	201
		NOTE: Configuration will conform to "As Built" pending incorporation of EO 3142A	4072A	4072A	4072A	
			D045	D045	D045	
			D090	D090	D090	
			D105	D105	D105	
			W017	W017	W017	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
	50904-3	PWB ASSY, POSTAMP BAND #3	G	G	G	201
		NOTE: Configuration will conform to "As Built" pending incorporation of EO 3142A	4072A	4072A	4072A	
			D045	D045	D045	
			D090	D090	D090	
			D105	D105	D105	
			D135	D135	D135	
			W017	W017	W017	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
	50904-4	PWB ASSY, POSTAMP BAND #4	G	G	G	201
		NOTE: Configuration will conform to "As Built" pending incorporation of EO 3142A	4072A	4072A	4072A	
			D045	D045	D045	
			D090	D090	D090	
			D105	D105	D105	
			W017	W017	W017	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
			W120	W120	W120	

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52347

S 3

ID /L	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
	50908-1	PWB ASSY, POSTAMP BAND #5	D 3567A D090 W018 W060R1 W097	D 3567A D090 W018 W060R1 W097	D 3567A D090 W018 W060R1 W097	201
	50908-2	PWB ASSY, POSTAMP BAND #7	D 3567A D090 W018 W060R1 W097	D 3567A D090 W018 W060R1 W097	D 3567A D090 W018 W060R1 W097	201
	50912	PWB ASSY, POSTAMP BAND #6	E D091 D094 D136 W060R1 W097	E D091 D094 D136 W060R1 W097	E D091 D094 D136 W060R1 W097	201
	50916	PWB ASSY CALIB. SHUTTER MAIN	F D080 D104R1 D109R1 D111 D116 D117 W035 W060R1 W097	F D080 D104R1 D109R1 D111 D116 D117 W035 W060R1 W097	F D080 D104R1 D109R1 D111 D116 D117 W035 W060R1 W097	201

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52347

Sheet 4

ID	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	50920	PWB ASSY, TEMP CONTROL	D 3717A 4290A D054 D077 D093 D101 D116 W012 W060R1 W097	C 3457A 4290A D054 D077 D093 D101 D116 W012 W060R1 W097	C 3457A 4290A D054 D077 D093 D101 D116 W012 W060R1 W097	101
3	50926	PWB ASSY, CALIB LAMP AND INCHWORM DRIVERS	E D044 D088R1 D115 SB-W031 W060R1 W097	E D044 D088R1 D115 SB-W031 W060R1 W097	E D044 D088R1 D115 SB-W031 W060R1 W097	201
	50942	TEMPERATURE CONTROL	G 4343A 4565A D150	F 3740A 3763A 3809A 3819A 4343A 4565A D150	F 3740A 3763A 3809A 3819A 4343A 4565A D150	202
	50948	PWB ASSY, VERIFICATION REGISTER	E 3218A 3718A 3836A D079 D114 D131 W022 W060R1 W097	E 3218A 3718A 3836A D079 D114 D131 W022 W060R1 W097	E 3218A 3718A 3836A D079 D114 D131 W022 W060R1 W097	201

ORIGINAL PAGE IS  
OF POOR QUALITY



PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPY. REVISION	AS-BUILT REVISION	SERIAL NUMBER
51398	CALIB. SHUTTER BACKUP	E 4031A 4452A D056 D108R1 D116 D133 D137 D147 D153 SB-W033 W060R1 W097	E 4031A 4452A D056 D108R1 D116 D133 D137 D147 D153 SB-W033 W060R1 W097	E 4031A 4452A D056 D108R1 D116 D133 D137 D147 D153 SB-W033 W060R1 W097	101
51402	PWB ASSY, TELEMETRY SCALING FUSELINK	D 3685A 3691A 3710A 4288A D058R1 D072 D112 D116 D125 W013 W027 W060R1 W097	D 3685A 3691A 3710A 4288A D058R1 D072 D112 D116 D125 W013 W027 W060R1 W097	D 3685A 3691A 3710A 4288A D058R1 D072 D112 D116 D125 W013 W027 W060R1 W097	201  ORIGINAL PAGE IS OF POOR QUALITY
51795	PWB ASSY MACRO DISCRETE	F 3720A 3835A D065 D113R1 D130 W060R1 W097	F 3720A 3835A D065 D113R1 D130 W060R1 W097	F 3720A 3835A D065 D113R1 D130 W060R1 W097	102 & 202

P/N 52347

Sh 6

ND VL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
I	51813	MACRO DISCRETE	C	C	C	201
			3705A	3705A	3705A	
			D078	D078	D078	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
I	52250-1	PWB ASSY, SCAN LINE CORRECTOR	C	C	C	
			1080A	1080A	1080A	
			1638A	1638A	1638A	
			2671A	2671A	2671A	
			3272A	3272A	3272A	
			3712A	3712A	3712A	
			W011	W011	W011	
			D116	D116	D116	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
I	52250-2	PWB ASSY, SCAN LINE CORRECTOR	C	C	C	
			1080A	1080A	1080A	
			1638A	1638A	1638A	
			2671A	2671A	2671A	
			3272A	3272A	3272A	
			3712A	3712A	3712A	
			W011	W011	W011	
			D116	D116	D116	
			W060R1	W060R1	W060R1	
			W097	W097	W097	
I	52348	CABLE RTG ASSY	F	F	F	005
			3844A	3844A	3844A	

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52347

Sh 7



IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	52360	COVER, TOP	B 1620A 1854A 1877A	B 1620A 1854A 1877A	B 1620A 1854A 1877A	
3	52362	COVER, BOTTOM	B 1855A 1884A	B 1855A 1884A	B 1855A 1884A	
3	52363	COVER, BOTTOM FRONT	B 1621A 1856A 1878A	B 1621A 1856A 1878A	B 1621A 1856A 1878A	
3	52797	PWB ASSY AUX CIRCUIT BOARD	C 3711A W014 W060R1 W097	C 3711A W014 W060R1 W097	C 3711A W014 W060R1 W097	201
3	53393	COVER FRONT	A 1879A	A 1879A	A 1879A	
3	53877	PWB ASSY, MOTOR DRIVER COOLER DOOR	B 3706A D037 D098 D100 D116 W019 W060R1 W097 4456A	B 3706A D037 D098 D100 D116 W019 W060R1 W097 4456A	B 3706A D037 D098 D100 D116 W019 W060R1 W097 4456A	101

ORIGINAL PAGE IS  
OF POOR QUALITY

P/N 52347

She. 8

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
3	16268	PROCESS SPEC, SURFACE MTD COMPONENTS	A	A	A	
			2216A	2216A	2216A	
			2940A	2940A	2940A	
			3080A	3080A	3080A	
			3283A	3283A	3283A	
3	16704	ACCEPTANCE TEST, PROCEDURE FOR ELECTRONICS MODULES	C	C	C	
			3987A	3987A	3987A	
			4059A	4059A	4059A	
			4089A	4089A	4089A	
			4159A	4159A	4159A	
			4180A	4180A	4180A	

  
R. A. Groves, CDMO  
W. D. Adams, QualityORIGINAL PAGE IS  
OF POOR QUALITY

2.12.2.2

ORIGINAL PAGE 18  
OF POOR QUALITY

Listing of Liens

ELECTRONIC MODULE

P/N 52347

FLIGHT

ORIGINAL PAGE IS  
OF POOR QUALITY

Failure Reports Number

Open	Closed	Closed
S8021	F0606	S8315
	F0622	S8316
	F1666	S8320
	F1667	S8321
	F1668	S8325
	F1761	S8326
	F1769	S8327
	F1774	S8329
	F1776	S8343
	F1781	S8363
	F1783	S8364
	F2722	S8365
	F2723	S8367
	F2724	S8368
	S8049	S8372
	S8050	S8384
	S8051	S8390
	S8107	S8407
	S8108	S8446
	S8109	S8447
	S8110	S8456
	S8112	S8460
	S8125	S8464
	S8126	
	S8133	
	S8139	
	S8180	
	S8283	
	S8309	
	S8310	
	S8311	
	S8312	
	S8313	
	S8314	

Deviations

Waivers

D-125	
D-129	
D-130	
D-131	
D-133	
D-135	
D-136	
D-137	
D-147	
D-150	
D-159	

ORIGINAL PAGE IS  
OF POOR QUALITY

ELECTRONIC MODULE

P/N 52347

FLIGHT			PROTOFLIGHT		ENGINEER	
Failure Report No.			Failure Report No.		Failure Report No.	
Open	Closed		Open	Closed	Open	Closed
S8021	F0606	S8326		F0551	F2707	F0501
	F0622	S8327		F0582	F2708	F0509
	F1666	S8329		F0584	F2720	F0515
	F1667	S8343		F0590	F2738	F0516
	F1668	S8363		F0601	F2741	F0534
	F1761	S8364		F0621	F2758	F0539
	F1769	S8365		F1703	F2759	F0542
	F1774	S8367		F1709	F2760	F0548
	F1776	S8368		F1712	F5175	?F0549
	F1781	S8384		F1713	F5183	F0563
	F1783	S8390		F1715	F5189	F0564
	F2722	S8407		F1719	S8012	F0593
	F2723	S8446		F1773	S8024	F1720
	F2724	S8447		F1777	S8044	F2646
		S8456		F1778	S8045	F2692
	S8049	S8460		F1779	S8047	F2743
	S8050	S8464		F1789	S8069	F2744
	S8051			F1796	S8073	F2750
	S8107			F1797	S8074	F2752
	S8108			F2362	S8466	F2754
	S8109			F2363		F2756
	S8110			F2391		F2797
	S8112			F2393		
	S8125			F2394		
	S8126			F2633		
	S8133			F2634		
	S8139			F2638		
	S8180			F2640		
	S8283			F2671		
	S8309			F2686		
	S8310			F2693		
	S8311			F2694		
	S8312			F2695		
	S8313			F2698		
	S8314			F2699		
	S8315			F2700		
	S8316			F2701		
	S8320			F2702		
	S8321			F2703		
	S8325			F2705		
				F2706		

ORIGINAL PAGE IS  
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center (Hughes Aircraft Co) 75 Coromarr Drive, Goleta, CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER 3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
4. DESIGNATION FOR DEVIATION/WAIVER a. MODEL/TYPE PF & F1 b. MFR. CODE 11323 c. SYS. DESIG. TM d. DEV/WAIVER NO. D125				5. BASE LINE AFFECTED <input type="checkbox"/> FUNC. TIONAL <input type="checkbox"/> ALLO. CATED <input type="checkbox"/> PROD. UCT		6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN a. SYSTEM b. ITEM c. TEST PLAN				8. DRAWINGS AFFECTED a. MFR. CODE b. SPEC./DOC. NO. c. SON d. MFR. CODE e. NUMBER f. REV. g. NOR. NO. 11323 51402 D 35704			
9. TITLE OF DEVIATION/WAIVER LAMP SEQUENCER PWB ALTERNATE WIRING						10. CONTRACT NO. & LINE ITEM NAS 5-24200	
11. CONFIGURATION TYPE NOMENCLATURE Electronic Module Assembly				12. CD NO. II 13. DEFECT NO. 14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL			
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED PWB TLMY Scaling, Fuse-		16. PART NO. OR TYPE DESIG. 51402-D		17. LOT NO. 002/008		18. QTY 2	
19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				20. EFFECT ON COST/PRICE link, Lamp Seq.			
21. EFFECT ON DELIVERY SCHEDULE 5 Month Schedule Impact if disapproved.				22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.			

23. DESCRIPTION OF DEVIATION/WAIVER

Request authorization to add Resistor and alternate wiring (jumpers) to accommodate circuit design changes.

24. NEED FOR DEVIATION/WAIVER

Redesign and reprourement of electronic circuit boards would be required in order to eliminate alternate wiring and addition of resistor. Minimum 5 months' schedule slip and considerable cost would be involved. Redesign is not considered cost effective at this time.

REA <u>L. Evans</u> SYS ENGR <u>J. H. Engel</u>		RE <u>[Signature]</u> QA <u>[Signature]</u> PE <u>[Signature]</u> CMO <u>[Signature]</u>	
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 S/N 002 & SUBSO		26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE Minor - System Engineering Major/Critical - Program Manager	
27. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED		28. APPROVED <input type="checkbox"/> DISAPPROVED <input type="checkbox"/>	
29. GOVERNMENT ACTIVITY NASS CSFC		SIGNATURE <u>[Signature]</u> DATE <u>9/1/81</u>	
DD FORM 1694			



ORIGINAL PAGE IS  
OF POOR QUALITY

Program Instruction 810

REQUEST FOR DEVIATION/VAIVER  
SEE MIL-STD-883C FOR INSTRUCTIONS

DATE PREPARED  
11/05/81

PROCESSING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Dr. Goleta, CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> VAIVER	
3. DESIGNATION FOR DEVIATION/VAIVER a. MODEL TYPE: Flight b. WFR. CODE: 11323 c. SYS. DESIG.: TM d. DEV. NO.: D-129				4. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
5. BASE LINE AFFECTED a. FUNCTIONAL <input type="checkbox"/> b. ALLOCATED <input type="checkbox"/> c. MODIFIED <input checked="" type="checkbox"/> d. YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>				6. OTHER SYSTEMS/COMPONENTS AFFECTED a. YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
7. SPECIFICATIONS AFFECTED-TEST PLAN a. WFR. CODE: b. SPEC. DOC. NO.: 52934-A c. SON: d. WFR. CODE: e. REVISION: f. WFR. NO.:				8. DRAWINGS AFFECTED a. WFR. CODE: b. REVISION: c. WFR. NO.:	
9. TITLE OF DEVIATION/VAIVER Use of alternate terminal assembly.				10. CONTRACT NO.: NAS5-24200	
11. IDENTIFICATION OF ITEM NOMENCLATURE Board Capacitor and Relay Assy.				12. DD NO.: 13. EFFECT: 14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRIT. CA.	
15. NAME OF PART OR SUB-ASSEMBLY AFFECTED Terminal STUD, Insulated E25-E29				16. PART NO. OR TYPE DESIG.: 17. LOT NO.: 18. QTY: 5	
19. EFFECT ON COST/PRICE None				20. EFFECT ON DELIVERY SCHEDULE 5 month schedule slip if dev. not approved.	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				22. EFFECT ON DELIVERY SCHEDULE 5 month schedule slip if dev. not approved.	
23. DESCRIPTION OF DEVIATION/VAIVER Request usage of Qty. 5 53413 bond on type terminals in place of Qty. 5 54310 terminals for designated E25 to E29 on EO 2853A of 52934-A assembly.					
24. NEED FOR DEVIATION/VAIVER 54310 terminals are unavailable in SBRC or HAC stores. Outside procurement estimated at 3 months. Thematic Mapper schedule slip of 3 months will result if alternate terminal usage is not approved. Note: P/N 53413 is not on the TM Approved Parts and Materials List, however they are on the MES Approved Parts and Materials List.					
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY					
26. APPROVAL/RECOMMENDATION a. APPROVAL: <input checked="" type="checkbox"/> b. DISAPPROVAL: <input type="checkbox"/> c. RECOMMENDED: <input type="checkbox"/> d. APPROVED: <input checked="" type="checkbox"/> e. DISAPPROVED: <input type="checkbox"/> f. SIGNATURE: g. DATE: h. SIGNATURE: i. DATE:					

DD FORM 1694

ORIGINAL PAGE IS  
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER  
SEE MIL-STD-883A FOR INSTRUCTIONS

PROCESS INSTRUCTIONS 010

DATE PREPARED

11/05/81

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Dr. Goleta, CA 93117				2. X DEVIATION <input checked="" type="checkbox"/> WAIVER <input type="checkbox"/>	
3. DESIGNATION FOR DEVIATION/WAIVER Plt. 11323 TM D-130				4. Y WINDS <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL <input type="checkbox"/>	
5. BASE LINE EFFECTS <input type="checkbox"/> FUNK. <input type="checkbox"/> ALLG. <input checked="" type="checkbox"/> PROD. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				6. OTHER SYSTEM/COMPONENTS AFFECTED	
7. SPECIFICATIONS AFFECTED-TEST PLAN WDR CODE SPEC. DOC. NO. SN				8. DRAWINGS AFFECTED WDR CODE NUMBER REV. NO. NO.	
9. SYSTEM				10. TEST PLAN	
11. EFFECT ON DELIVERY SCHEDULE Alternate component placement (non contact to board)				12. CONTRACT NO. & LINE NO. NAS5-24200	
13. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				14. EFFECT ON DELIVERY SCHEDULE	
15. DESCRIPTION OF DEVIATION/WAIVER Thematic Mapper Assy. Printed wiring board assy. Macro discrete Com. #1 51795-E				16. EFFECT ON DELIVERY SCHEDULE	
17. LOT NO. 18. J F				19. RECORDING DEVIATION/WAIVER <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
20. EFFECT ON DELIVERY SCHEDULE				21. EFFECT ON DELIVERY SCHEDULE	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				23. DESCRIPTION OF DEVIATION/WAIVER	

Need to be able to mount components off the board surface as shown on drawing. Support bonding shall be used to secure part. Does not meet requirements of Para. 3A503 of Spec NHB 5300.4 (3A).

24. NEED FOR DEVIATION/WAIVER

Circuit changes required from RCR05 to RNN55 resistors after the circuit boards were procured. As a result, pad spacing is too close in some cases to mount the component on the board surface and still meet lead minimum bend radius.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY		26. APPROVAL, DISAPPROVAL APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED <input type="checkbox"/>	
27. SIGNATURE J. A. Sanad		28. SIGNATURE J. L. Escal	
29. SIGNATURE J. L. Escal		30. SIGNATURE J. L. Escal	
31. SIGNATURE J. L. Escal		32. SIGNATURE J. L. Escal	
33. SIGNATURE J. L. Escal		34. SIGNATURE J. L. Escal	
35. SIGNATURE J. L. Escal		36. SIGNATURE J. L. Escal	
37. SIGNATURE J. L. Escal		38. SIGNATURE J. L. Escal	
39. SIGNATURE J. L. Escal		40. SIGNATURE J. L. Escal	
41. SIGNATURE J. L. Escal		42. SIGNATURE J. L. Escal	
43. SIGNATURE J. L. Escal		44. SIGNATURE J. L. Escal	
45. SIGNATURE J. L. Escal		46. SIGNATURE J. L. Escal	
47. SIGNATURE J. L. Escal		48. SIGNATURE J. L. Escal	
49. SIGNATURE J. L. Escal		50. SIGNATURE J. L. Escal	
51. SIGNATURE J. L. Escal		52. SIGNATURE J. L. Escal	
53. SIGNATURE J. L. Escal		54. SIGNATURE J. L. Escal	
55. SIGNATURE J. L. Escal		56. SIGNATURE J. L. Escal	
57. SIGNATURE J. L. Escal		58. SIGNATURE J. L. Escal	
59. SIGNATURE J. L. Escal		60. SIGNATURE J. L. Escal	
61. SIGNATURE J. L. Escal		62. SIGNATURE J. L. Escal	
63. SIGNATURE J. L. Escal		64. SIGNATURE J. L. Escal	
65. SIGNATURE J. L. Escal		66. SIGNATURE J. L. Escal	
67. SIGNATURE J. L. Escal		68. SIGNATURE J. L. Escal	
69. SIGNATURE J. L. Escal		70. SIGNATURE J. L. Escal	
71. SIGNATURE J. L. Escal		72. SIGNATURE J. L. Escal	
73. SIGNATURE J. L. Escal		74. SIGNATURE J. L. Escal	
75. SIGNATURE J. L. Escal		76. SIGNATURE J. L. Escal	
77. SIGNATURE J. L. Escal		78. SIGNATURE J. L. Escal	
79. SIGNATURE J. L. Escal		80. SIGNATURE J. L. Escal	
81. SIGNATURE J. L. Escal		82. SIGNATURE J. L. Escal	
83. SIGNATURE J. L. Escal		84. SIGNATURE J. L. Escal	
85. SIGNATURE J. L. Escal		86. SIGNATURE J. L. Escal	
87. SIGNATURE J. L. Escal		88. SIGNATURE J. L. Escal	
89. SIGNATURE J. L. Escal		90. SIGNATURE J. L. Escal	
91. SIGNATURE J. L. Escal		92. SIGNATURE J. L. Escal	
93. SIGNATURE J. L. Escal		94. SIGNATURE J. L. Escal	
95. SIGNATURE J. L. Escal		96. SIGNATURE J. L. Escal	
97. SIGNATURE J. L. Escal		98. SIGNATURE J. L. Escal	
99. SIGNATURE J. L. Escal		100. SIGNATURE J. L. Escal	

DD FORM 1694

ORIGINAL PAGE IS  
OF POOR QUALITY

STANDARD INSTRUCTION 010

REQUEST FOR DEVIATION/WAIVER  
SEE 412-370-40 2A 41 FOR INSTRUCTIONS

DATE PREPARED

11/05/81

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromarr Dr. Goleta, CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
3. DESIGNATION FOR DEVIATION/WAIVER				4. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
5. MODEL/TYPE Flt.	6. MFR. CODE 11323	7. SYS. DESIG. TM	8. DEV. NUMBER D-131	9. <input type="checkbox"/> FUNC. TIONAL <input type="checkbox"/> ALLO. CATED	10. <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
11. SPECIFICATIONS AFFECTED-TEST PLAN				12. DRAWINGS AFFECTED	
13. MFR. CODE 11323				14. REV. I E	
15. MFR. CODE 50948				16. REV. I EO 3630A	
17. MFR. CODE 50948-E				18. REV. I E	
19. EFFECT ON COST/PRICE				20. EFFECT ON DELIVERY SCHEDULE	
21. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.				22. DESCRIPTION OF DEVIATION/WAIVER	
Alternate component placement (no contact with board). Thematic Mapper Assy. Printed wiring board assy. verification resistor					

Need to be able to mount components off the board surface as shown on drawing. Support bonding shall be used to secure part. Does not meet requirements for Para. 3A503 of Spec NHB 5300.4 (3A).

23. NEED FOR DEVIATION/WAIVER

Circuit changes required changes from RCR05 to RNN55 resistors after the circuit boards were procured. As a result, pad spacing is too close in some cases to mount the component on the board surface and still meet lead minimum bend radius.

24. PREPARED BY CA Enrich	25. SYS ENGR JH Enrich	26. QA JH Enrich	27. PE JH Enrich
28. PROJECT OR EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 ONLY		29. CMO JH Enrich	
30. APPROVAL, DISAPPROVAL APPROVAL RECOMMENDED		31. APPROVED DISAPPROVED	
32. GOVERNMENT ACTIVITY DD FORM 1694		33. SIGNATURE JH Enrich	

ORIGINAL PAGE IS  
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

4 JANUARY 1982

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER 75 COROMAR DR. GOLETA, CA. 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE F1	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. D-133	<input checked="" type="checkbox"/> PURCH. TIONAL	<input type="checkbox"/> ALLO- CATED
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
9. SYSTEM				10. CONTRACT NO. & LINE ITEM	
				NAS 5-24200 #32	
11. CONFIGURATION ITEM NOMENCLATURE Electronics Module Assembly				12. CD NO. II	
13. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Cal Shutter Back (A7)				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. PART NO. OR TYPE DESIG. 51398-E				16. QTY 1	
17. EFFECT ON COST/PRICE				18. DEGRADING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
19. EFFECT ON DELIVERY SCHEDULE 5 months schedule impact if disapproved					
20. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					
21. DESCRIPTION OF DEVIATION/WAIVER Alternate wiring (trace cuts, jumper wires and added parts) incorporated on assembly drawing to accommodate circuit design changes. Sec. 51398 assembly drawing and referenced SP80165 alternate wiring process specification attached. SEE EOs: EO 2992A 3072A Ref: W033 per EO 8703 D056 per EO 1084A D108R1					
22. NEED FOR DEVIATION/WAIVER Redesign and re-procurement of electronic circuit boards would be required in order to eliminate alternate wiring. Minimum 5 months schedule slip and considerable costs would be involved. Redesign is not considered cost effective at this time.					

23. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 only		RE: <u>James 1/4/82</u>	
		QA: <u>WMO 1/6/82</u>	
		PE: <u>James 1/7/82</u>	
24. SIGNATURE AND DATE <u>J. L. Engel</u> 17 Jan 82		25. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
26. GOVERNMENT ACTIVITY NASA GSFC		27. SIGNATURE AND DATE <u>Robert B. Lott</u> 1/2/82	
DD FORM 1694			

Program Instruction 010

**REQUEST FOR DEVIATION/WAIVER**  
**(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)**

DATE PREPARED

1. PROCURING ACTIVITY NO.

8 January 82

1. ORIGINATOR NAME AND ADDRESS <b>SANTA BARBARA RESEARCH CENTER (HUGHES AIRCRAFT) 75 Coromar Drive, Goleta, CA 93117</b>				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE <b>F</b>	b. MFR. CODE <b>11323</b>	c. SYS. DESIG. <b>TM</b>	d. DEV/WAIVER NO. <b>D-135</b>	<input type="checkbox"/> FUNDAMENTAL <input type="checkbox"/> ALLOCATED <input type="checkbox"/> PRODUCE <input type="checkbox"/> YES <input type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
a. SYSTEM b. ITEM c. TEST PLAN				a. MFR. CODE b. REV. c. NDR. NO.	
a. SYSTEM b. ITEM c. TEST PLAN				a. MFR. CODE b. REV. c. NDR. NO.	
9. TITLE OF DEVIATION/WAIVER <b>Alternate Wiring</b>				10. CONTRACT NO. & LINE ITEM <b>NAS 5-24200</b>	
11. CONFIGURATION ITEM NOMENCLATURE <b>Electronics Module Assembly</b>				12. CD NO. <b>II</b>	
13. NAME OF PART OR LOWEST ASSEMBLY AFFECTED <b>PWB Assy Post Amp Bands 1-4</b>				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. PART NO. OR TYPE DESIG. <b>50904-3</b>				16. LOT NO. <b>-1-</b>	
17. EFFECT ON COST/PRICE				18. RECURRING DEVIATION/WAIVER <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
19. EFFECT ON DELIVERY SCHEDULE <b>5 Month Schedule Impact if disapproved</b>					
20. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					
21. DESCRIPTION OF DEVIATION/WAIVER  <b>Alternate wiring (added wires) to PWB assembly. Adding jumpers between R70B-U4P33, R73B-U7P56, R79A-U12P47 per SP80165, Procedure B, using item 32 of 50904.</b>					
22. NEED FOR DEVIATION/WAIVER  <b>Redesign and reprourement of electronic circuit boards would be required in order to eliminate alternate wiring. Minimum 5 months schedule slip and considerable cost would be involved. Redesign is not considered cost effective at this time.</b>					
23. APPROVAL/RECOMMENDATION  REA <i>[Signature]</i> <b>SYS ENGR</b> <i>[Signature]</i> PE <i>[Signature]</i>					
24. PRODUCTION EFFECTIVITY BY SERIAL NUMBER					
25. AUTHORIZING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i>					
26. APPROVAL/RECOMMENDATION  <input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> DISAPPROVED SIGNATURE <i>[Signature]</i> DATE <b>4/9/82</b>					

DD FORM 1694  
DEC 68

ORIGINAL PAGE IS  
OF POOR QUALITY

MATERIAL REVIEW  
CONTROL ORDER

M R C O

4	1	2	4	7	4	R
W	/	A	✓	0	1	2

PART NO. 509045 REVISION F

PART NAME POSTAL P PLUG BAND 3

QUANTITY 1 S/N 201

ROUTE TO: \_\_\_\_\_

P.O. MASTER CLEARED 10/2

OPR NO.	INSTRUCTIONS	DATE	QTY ACC	QTY SUS	INSP OPER	COMMENTS
2274	100) INSTALL 30 AWG TYPED M (J-W-1177) WIRE FROM R79 (A SIDE) PAD TO U12 PAD AT PIN 47 PER SP 80165. PER _____					
	2) INSTALL 30 AWG TYPED M (J-W-1177) WIRE FROM R73 (B SIDE) PAD TO U17 PAD AT PIN 52 PER SP 80165. PER _____					
	3) INSTALL 30 AWG TYPED M (J-W-1177) WIRE FROM R70 (B SIDE) PAD TO U14 PAD AT PIN 33 PER SP 80165 PER _____					
LAST	RETURN THIS CARD TO MATERIAL REVIEW FOR RECORD CLEARANCE.					
OPR						

SB 0344-B-1 FEB 75

QA APPROVAL [Signature] DATE \_\_\_\_\_

ENG APPROVAL [Signature] DATE \_\_\_\_\_

ORIGINAL PAGE IS  
OF POOR QUALITY

MATERIAL REVIEW  
CONTROL ORDER

M R C O

4	1	2	4	7	4	R
W	/	A	✓	0	1	2


CONTINUATION SHEET

PAGE 2 OF 2

OPR NO.	INSTRUCTIONS	DATE	QTY ACC	QTY SUS	INSP OPER	COMMENTS
11-10-11-11						
	4) When RECEIVING					
	ST-AS 1, 2 & 3, RETURN					
	WORKSHEET ATTACHED					
	TO MRCO					
5-10-200	INSPECT - Pu# 100					
	Per SP 80165 & WORKSHEET					
AF 300	MCT					
400	Return to MCB					
LAST	RETURN THIS CARD TO					
CPR	MATERIAL REVIEW FOR					
	RECORD CLEARANCE.					

ORIGINAL PAGE IS  
OF POOR QUALITY

PRKSL & L. R. HURIT 42474 213





ORIGINAL PAGE IS  
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-460 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

13 January, 1982

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER 75 Coromar Drive, Goleta, CA 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
a. MODEL/TYPE F1	b. MFR. CODE 11323	c. SYS. DESIG. TM	d. DEV/WAIVER NO. D136	<input type="checkbox"/> FUNC- TIONAL	<input type="checkbox"/> ALLO- CATED
				<input type="checkbox"/> PROD- UCT	<input type="checkbox"/> YES <input type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
9. TITLE OF DEVIATION/WAIVER Band-6, Voltage Regulator, Series Resistor Change				10. CONTRACT NO. & LINE ITEM NAS5-24200	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II	
				13. DEFECT NO. II	
				14. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED PWB ASSY Postamp-6				16. PART NO. OR TYPE DESIG. 50912-E	
				17. LOT NO. F1	
				18. QTY 1	
				19. RECURRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
20. EFFECT ON COST/PRICE				21. EFFECT ON DELIVERY SCHEDULE	
22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					
23. DESCRIPTION OF DEVIATION/WAIVER Alternate wiring, replaced components, and added components per E03456A required using SP80165. This Engineering Order provides the voltage regulator with current capability to prevent power foldback at Band 6 turn on. Possible component stress as well as initial circuit performance degradation is corrected by the modification.					
24. NEED FOR DEVIATION/WAIVER The Band-6 voltage regulator goes into current limit due to turn-on characteristic of circuit. This characteristic is unacceptable. Redesign and reprourement of electronic circuit boards would be required to eliminate cuts and alternate wiring. Minimum 5 months schedule slip and considerable cost would be involved.					

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 SN 003 only		26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE JH [Signature] J. [Signature]		27. APPROVAL/DISAPPROVAL Minor - System Engineering Major/Critical - Program Manager	
28. GOVERNMENT ACTIVITY NASC GSFC		29. SIGNATURE George B. [Signature]		30. DATE 1/13/82	
31. APPROVAL RECOMMENDED <input type="checkbox"/>		32. APPROVED <input checked="" type="checkbox"/>		33. DISAPPROVED <input type="checkbox"/>	
34. DD FORM 1694					

ORIGINAL PAGE IS  
OF POOR QUALITY

<b>[SBRC] ENGINEERING ORDER / <del>REVISION NOTICE</del></b>		NO. <u>3414A</u>	
SHEET 1 OF <u>3</u>		DRAWING NUMBER <u>50912 (2)</u>	
PROJECT TITLE <u>PRINTED WIRING BOARD ASSY</u>		CLASS CHANGE <input type="checkbox"/> I <input checked="" type="checkbox"/> A <input type="checkbox"/> B	
PROJECT NUMBER <u>PL1162</u>	ITEM DISPOSITION REWORK <input checked="" type="checkbox"/> NO ITEMS MADE <input type="checkbox"/> USE <input type="checkbox"/> ITEMS CONFORM <input type="checkbox"/> REJECT <input type="checkbox"/> NOT APPLICABLE <input type="checkbox"/>	DRAWING TYPE <input type="checkbox"/> A <input type="checkbox"/> B	
EFFECTIVITY <u>ELCCS</u>		AUTHORIZING ECR NUMBER <u>TMA 2402/01</u>	
DESCRIPTION OF CHANGE <u>1. IN LM, CHANGED PN, ITEM 18</u>			

1. IN LM, CHANGED PN, ITEM 18  
 IS: 908611-204 RESISTOR, 13, 1%, 2W  
 WAS: 908665-23 RESISTOR, 22, 5%, 1/8W

2. IN LM, ADDED ITEMS \*1 THRU \*26
- |        |             |       |                                    |    |
|--------|-------------|-------|------------------------------------|----|
| 2 REQD | 908666-1    | 22577 | TRANSISTOR, PNP, NPN (2N3752)      | *1 |
| 1      | 908678-135  |       | RESISTOR, 2.49, 1%, 1W             | *2 |
| 1      | 908678-126  |       | RESISTOR, 2.00, 1%, 1W             | *3 |
| 2      | 908555-186  | 22577 | CAPACITOR, 10UF, 10%, 50V          | *4 |
| 8      | SC80181-8-2 |       | PAD PATTERN                        | *5 |
| 2      | NAS1291C3   |       | NUT, SELF-LOCK, 190-32 (NAS1291)   | *6 |
| 2 REQD | NAS620C10   |       | WASHER FLAT, No. 10 (NAS620)       | *7 |
| AR     | J-W-1177/14 |       | WIRE, INSUL, AWG 26, J-W-1177 TYPE | *8 |

3. IN GENERAL NOTES, ADDED:

- \*9 INSTALL COMPONENTS, PAD PATTERNS AND WIRE  
PER SP20165, PROCEDURE C.

4. IN COMPONENT IDENT TABLE, ADDED

Q1, 2	ITEM *1
R29	ITEM *2
R30	ITEM *3
C23, 24	ITEM *4

\* NOTE AND/OR ITEM NUMBER TO BE ASSIGNED AT TIME OF INCORPORATION

DESIGNED BY <u>CE</u>	DATE <u>7-20-61</u>	QUALITY APPROVAL <u>[Signature]</u>	DATE <u>7-20-61</u>	RELEASED BY <u>[Signature]</u>
CHECKED BY <u>[Signature]</u>	DATE <u>[Blank]</u>	MANUFACTURING APPROVAL <u>[Signature]</u>	DATE <u>[Blank]</u>	INCORPORATED <u>[Blank]</u>
STATUS APPROVAL <u>[Blank]</u>	DATE <u>[Blank]</u>	PROJECT APPROVAL <u>[Signature]</u>	DATE <u>5/17/20</u>	DRAWING REV LETTER <u>[Blank]</u>

DO NOT STATUS THIS PRINT  
MAINTAINED AFTER  
JUL 21 1961  
DO NOT USE THIS PRINT  
ORDER OF REVISIONS  
REVISION 12-11-1961

ORIGINAL PAGE IS  
OF POOR QUALITY



# ENGINEERING ORDER / REVISION NOTICE

SHEET 2

DRAWING TITLE PRINTED WIRING BOARD ASSY

DRAWING NUMBER

AMPLIFIER 6 & COMMAND RELAYS (A16)


50912 (2)

DESCRIPTION OF CHANGE

5. ON F/D, SH3, ZONE 3 D

ADDED Q1-2, R29-30, C23-24 & PAD PATTERNS;

RELOCATED R11-12.



ORIGINAL PAGE IS  
OF POOR QUALITY

<b>SERC</b> ENGINEERING ORDER/REVISION NOTICE		NO. <u>PL1162</u>	
CODE IDENT 11223		SHEET 1 OF 3	
DRAWING TITLE <u>PRINTED WIRING BOARD ASSY</u>		DRAWING NUMBER <u>50912 (2)</u>	
<u>AMPLIFIER 6 &amp; COMMAND RELAYS (A16)</u>			
PROJECT NUMBER <u>PL1162</u>	ITEM DISPOSITION	CLASS CHANGE	DRAWING TYPE
EFFECTIVITY <u>SI005</u>	REWORK <input checked="" type="checkbox"/> ITEMS CONFORM <input type="checkbox"/>	<input type="checkbox"/> A <input checked="" type="checkbox"/> A	<input type="checkbox"/> A <input checked="" type="checkbox"/> B
<u>COL &amp; SUBC</u>	NO ITEMS MADE <input type="checkbox"/> REJECT <input type="checkbox"/>	AUTHORIZING ECR NUMBER	
	USE <input type="checkbox"/> NOT APPLICABLE <input type="checkbox"/>	<u>TR 402/01</u>	

DESCRIPTION OF CHANGE  
1. 3 EO CANCELS AND SUPERSEDES EOs 32911 & 3414A

1. IN LM, CHANGED PN, ITEM 16

IS: 908611-204 RESISTOR, 13, 1%, 2W

WAS: 908665-23 RESISTOR, 22, 5%, 1/8W

2. IN LM, ADDED ITEMS \*1 THRU \*8

2 REQD 908604-1 22577 TRANSISTOR, PNP, NPN (2N3752) \*1

908678-135 RESISTOR, 2.49, 1%, 1W \*2

908678-126 RESISTOR, 2.00, 1%, 1W \*3

908555-186 22577 CAPACITOR, 10NF, 10%, 50V \*4

SC80181-8-2 PAD PATTERN \*5

NAS1291C3 NUT, SELF-LKG, 190-32 (NAS1291) \*6

2 REQD NAS620C10 WASHER FLAT, No. 10 (NAS620) \*7

AR J-W-1177/14 WIRE, INSUL, AWG 26, J-W-1177, TYPE M \*8

3. IN GENERAL NOTES, ADDED:

☒ INSTALL COMPONENTS, PAD PATTERNS AND WIRE  
PER SP20165, PROCEDURE C.

4. IN COMPONENT IDENT TABLE, ADDED

Q1, 2 ITEM \*1

R29 ITEM \*2

R30 ITEM \*3

C23, 24 ITEM \*4

\* NOTE AND/OR ITEM NUMBER TO BE ASSIGNED AT TIME OF INCORPORATION

DESIGNED BY <u>CE</u>	DATE <u>7-20-61</u>	QUALITY APPROVAL <u>[Signature]</u>	DATE <u>7-20-61</u>	RELEASED BY <u>[Signature]</u>
CHECKED BY	DATE	MANUFACTURING APPROVAL	DATE	INCORPORATED
SEALED BY	DATE	PROJECT APPROVAL <u>[Signature]</u>	DATE <u>5/10/70</u>	DRAWING REV LETTER

REVISION STATUS THIS PRINT  
NOT MAINTAINED AFTER  
JUL 21 1961  
DO NOT USE THIS PRINT  
UNLESS YOU HAVE THE LATEST  
REVISION OF THIS DRAWING

ORIGINAL PAGE IS  
OF POOR QUALITY

Program Instruction 010

REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

14 January 1982

PROCEEDING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center 75 Coromar Dr., Goleta, Ca 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
4. DESIGNATION FOR DEVIATION/WAIVER				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
6. MODEL/TYPE F1	8. MFR. CODE 11323	9. SYS. DESIG. TM	4. DEV/CHG NO. D137	5. CASE LINE AFFECTED <input type="checkbox"/> FUNC. TIONAL <input type="checkbox"/> ALLO-CATED <input checked="" type="checkbox"/> PROD-UCT	6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. DRAWINGS AFFECTED	
MFR. CODE SPEC./DOC. NO. SCH				MFR. CODE NUMBER REV. NOR. NO.	
9. SYSTEM				11323 51398 E	
10. TEST PLAN					
9. TITLE OF DEVIATION/WAIVER Cal Shutter Backup, Timing Jitter Correction				10. CONTRACT NO. & LINE ITEM	
11. CONFIGURATION ITEM NOMENCLATURE Radiometer				12. CD NO. II	
13. NAME OF PART OR LATEST ASSEMBLY AFFECTED PWB Cal Shutter Backup				14. DEFECT NO. 1	
15. EFFECT ON COST/PRICE				16. EFFECT ON DELIVERY SCHEDULE	
17. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.				18. EFFECT ON QUALITY	
19. DESCRIPTION OF DEVIATION/WAIVER				20. REQUIREMENTS DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	

Alternate wiring and added component required per SP80165.  
See EO 4031A.

This action will insure that Timing Jitter in the Phase Control Loop of the Redundant Shutter does not occur.

24. NEED FOR DEVIATION/WAIVER

It has been observed that under special conditions which are possible during operation that Redundant Shutter timing signals can move out of tolerance. E.O. 4031A corrects this problem completely. Redesign and reprourement of 51398 PWB would be required to eliminate alternate wiring. Minimum 5 month schedule slip and considerable cost would be involved.

REA <u>J.A. Banach</u> 1/14/82	SYS ENGR <u>[Signature]</u> 1/14/82	QA <u>[Signature]</u> 1-14-82	PE <u>[Signature]</u> 1/14/82
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER			
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <u>[Signature]</u>			
27. APPROVAL/DISAPPROVAL			
<input type="checkbox"/> APPROVAL RECOMMENDED <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED			
28. GOVERNMENT ACTIVITY NATA G5FC			
SIGNATURE <u>George B. Lunt</u> DATE <u>1/15/82</u>			
DD FORM 1694 DEC 68			

# Program Instruction 010

REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-480 OR 481 FOR INSTRUCTIONS)

DATE PREPARED

16 April 1982

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS Santa Barbara Research Center  
Div. of Hughes Aircraft Co., 75 Coromar Dr., Goleta, CA  
93117

2. ☒ DEVIATION ☐ WAIVER  
3. ☒ MINOR ☐ MAJOR ☐ CRITICAL

4. DESIGNATION FOR DEVIATION/WAIVER  
a. MODEL/TYPE Flt. I  
b. MFR. CODE  
c. SYS. DESIG. TM  
d. DEVIATION NO. D-147

5. BASE LINE AFFECTED  
☐ FUNC. TIONAL ☐ ALLO. CATED ☐ PROD. UCT

6. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED  
☐ YES ☒ NO

7. SPECIFICATIONS AFFECTED-TEST PLAN  
a. SYSTEM  
b. ITEM  
c. TEST PLAN

8. DRAWINGS AFFECTED  
MFR. CODE NUMBER REV. NO. NO. 51398

9. TITLE OF DEVIATION/WAIVER  
Soldering of two resistors to R130 pads.

10. CONTRACT NO. & LINE ITEM  
NAS 5-24200

11. CONFIGURATION ITEM IDENTIFICATION  
51398 PWB Assy Cal Shutter Backup (A7)

12. CD NO.  
13. DEFECT NO.  
14. DEFECT CLASSIFICATION  
☒ MINOR ☐ MAJOR ☐ CRITICAL

15. NAME OF PART OR LATEST ASSEMBLY AFFECTED  
A7 PWB

16. PART NO. & TYPE DESIGNATION  
51398-E

17. EFFECT ON COST/PRICE  
None.

18. EFFECT ON DELIVERY SCHEDULE  
2 months if not approved.

19. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.

## 23. DESCRIPTION OF DEVIATION/WAIVER

Request permission to use select resistors (R130 and R130 B, 698 ohm each) outside of select range list (52732-23). Also request permission to use two resistors instead of one in order to satisfy power derating criteria for the resistors. See dra attached.

ORIGINAL PAGE IS  
OF POOR QUALITY

## 24. NEED FOR DEVIATION/WAIVER

Mechanical adjustment of symmetry is not possible without a minimum of two months schedule delay, so we want to use electrical adjustments instead. The required value of resistance is not on the select list. The power rating is too low for the new resistance value required; therefore, two 698 ohm 1/10 watt resistors are needed.

RE 4/16/82  
REQ 4/16/82  
SYS ENGR  
PE  
25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER


26. AUTHORIZING ACTIVITY AUTHORIZING SIGNATURE  
Minor - System Engineering  
Major/Critical - Program Manager

27. APPROVAL/DISAPPROVAL  
☐ APPROVAL RECOMMENDED  
☒ APPROVED ☐ DISAPPROVED

28. GOVERNMENT ACTIVITY  
SIGNATURE DATE  
4/16/82

DD FORM 1694

ORIGINAL PAGE IS  
OF POOR QUALITY



LEAD  
BEND RADII  
TO BE IN  
ACCORDANCE  
WITH NHB 5300.4(3)

TV  
4/19/82

Program Instruction 010A

REPORT FOR DEVIATION/REVISION  
(SEE 44-550-450 OR 451 FOR INSTRUCTIONS)

CASE NUMBER

4 May 1982

*Review*

*P-H-V*

1. CONVICTION NAME AND ADDRESS Santa Barbara Research Center 75 Coronar Drive, Goleta CA 93117				2. DEVIATION/REVISION <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> REVISION			
3. DESIGNATION FOR DEVIATION/REVISION a. MODEL/TYPE: <b>PLT-1</b> b. CDR. CODE: <b>11323</b> c. CDR. CODE: <b>TH</b> d. CDR. CODE: <b>D-150</b>				5. BASIC LINE AFFECTED <input type="checkbox"/> PRE-TIME <input type="checkbox"/> ALD-CATED <input checked="" type="checkbox"/> POST-UCT		6. OTHER SYSTEMS/CRITICAL- DATION ITEMS AFFECTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN a. DUTY: <b>11323</b> b. ITEM: <b>50942</b> c. TEST PLAN: <b>G</b>				8. CRASH/ISS AFFECTED a. DUTY: <b>11323</b> b. ITEM: <b>50942</b> c. TEST PLAN: <b>G</b>			
9. TITLE OF DEVIATION/REVISION Alternate Wiring				10. CONTRACT NO. & LINE ITEM N/A			
11. CUSTOMER'S ITEM NAME Printed Circuit Board Assembly				12. DEVIATION/REVISION II			
13. NAME OF PART OR SUBASSEMBLY AFFECTED Temp Controller				14. PART NO. OR PART NAME 50942			
15. DUTY IS AFFECTED None				16. DEVIATION/REVISION 1			
17. DEVIATION/REVISION None				18. DEVIATION/REVISION 9 months schedule impact if disapproved			
19. DESCRIPTION OF DEVIATION/REVISION Alternate wiring (wire jumper/splice and added parts) incorporated on Assembly drawing to accommodate circuit design change. See 50942 assembly drawing and referenced SP 80165 alternate wiring process specification and EO 4343A (does not conform to NHB S300.4(3A) para. 3A402-4)							

ORIGINAL PAGE IS  
OF POOR QUALITY

20. REDESIGN/RE-PROCUREMENT OF ELECTRONIC CIRCUIT BOARD WOULD BE REQUIRED IN ORDER TO ELIMINATE ALTERNATE WIRING. MINIMUM 9 MONTHS SCHEDULE SLIP AND CONSIDERABLE COST WOULD BE INVOLVED. REDESIGN IS NOT CONSIDERED COST EFFECTIVE AT THIS TIME.	
21. APPROVAL/DISAPPROVAL <input type="checkbox"/> APPROVAL <input checked="" type="checkbox"/> DISAPPROVAL	22. APPROVAL/DISAPPROVAL <input checked="" type="checkbox"/> APPROVAL <input type="checkbox"/> DISAPPROVAL
23. APPROVAL/DISAPPROVAL NASA GSFC	24. APPROVAL/DISAPPROVAL George B. Britt 5/6/82
DD FORM 1694	9 GPO: 1979-444-100/018

RE

QA

REA

Sys Engr

FE



Program Instruction 010

ORIGINAL PAGE IS  
OF POOR QUALITY

REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-460 OR 461 FOR INSTRUCTIONS)

DATE PREPARED

7/7/82

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS SANTA BARBARA RESEARCH CENTER, 75 Coromar Drive, Goleta, California 93117				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE Flight I	8. MFR. CODE 11323	10. SYS. DESIG. TM	4. DEV/WAIVER NO. D-159	<input checked="" type="checkbox"/> FUND. TIONAL	<input type="checkbox"/> ALLO- CATED
				<input type="checkbox"/> PROD- UCT	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
7. SPECIFICATIONS AFFECTED-TEST PLAN				8. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED	
MFR. CODE SPEC./DOC. NO. SON				MFR. CODE NUMBER REV. NOR. NO.	
11323				50904 G 4072A	
9. TEST PLAN					
10. TITLE OF DEVIATION/WAIVER Alternate Wiring				11. CONTRACT NO. & LINE ITEM NAS 5-24200 Item 32	
12. CONFIGURATION ITEM NUMBER Electronics Module Assembly				13. DEFECT NO. 14. DEFECT CLASSIFICATION II <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
15. NAME OF PART OR LOWEST ASSEMBLY AFFECTED PWB PostAmp Band 1				16. PART NO. OR TYPE DESIGN 50904-1/G	
				17. LOT NO. 18. QTY 1	
19. EFFECT ON COST/PRICE None				20. RECORDING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
21. EFFECT ON DELIVERY SCHEDULE None				22. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. 8 mos. schedule impact, if disapproved	
23. DESCRIPTION OF DEVIATION/WAIVER BAND 1 Alternate wiring (added 16 resistors per PWB) incorporated an assembly drawing to accommodate circuit design change. See assembly drawing (EO 4515A) and referenced SP80163 alternate wiring process specification. Added resistors to eliminate coherent noise per FR5779.					

24. NEED FOR DEVIATION/WAIVER  
Redesign and re-procurement of electronic circuit boards would be required in order to eliminate alternate wiring. Minimum 8 months' schedule slip and considerable cost would be involved. Redesign is not considered cost effective at this time.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER 51065 S/N 003 only.	26. SIGNATURE OF AUTHORIZING OFFICIAL J. L. Engel 9/1/82	27. SIGNATURE OF REVIEWING OFFICIAL CNO. J. J. J. 7-2-82
28. APPROVAL/RECOMMENDATION <input type="checkbox"/> APPROVAL RECOMMENDED	29. APPROVAL/RECOMMENDATION <input checked="" type="checkbox"/> APPROVED	30. APPROVAL/RECOMMENDATION <input type="checkbox"/> DISAPPROVED
31. GOVERNMENT ACTIVITY NACA CSFC	32. SIGNATURE George B. Smith 7/16/82	
DD FORM 1694		

523 x7

ORIGINAL PAGE IS  
OF POOR QUALITY

HUGHES AIRCRAFT COMPANY

# FAILURE REPORT

**F 0606**

1. PROGRAM NAME AND NUMBER <b>H5 236</b>		3. QLA		5. MODEL <b>FLIGHT</b>		7. TIME OBSERVED <b>1100</b>		9. DATE OBSERVED <b>3 28 80</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICROC		<input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART	
8. EQUIPMENT IDENTIFICATION									
1. SUBSYSTEM				PART NUMBER		1/4		MANUFACTURER	
2. UNIT									
3. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICROC <input checked="" type="checkbox"/> CARD				<b>(POSTAMP 6 &amp; CMD, RELAY 10) 50912</b>		<b>201</b>		<b>HAC</b>	
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> REPRODUCTION				<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> VIBRATION				<input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> VIBRATION		<input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HES AT		<input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <b>STEP 16 MEASURES INFINITE, INSTEAD OF 10 K. STEP 35 AND STEP 36 MEASURE INFINITE, INSTEAD OF 10 K.</b>									
15. TEST PROCEDURE <b>16368 4.7.2</b>				16. ORIGINATOR <b>NILE PATTY 2200 13 3125-80</b>					
17. VERIFICATION AND FAILURE ANALYSIS <b>SCHEMATIC 50913 REV C INDICATES THE RESISTOR IN STEP 16 IS NO LONGER USED AND R-9 IN STEP 35/36 ARE NO LONGER CONNECTED. TEST PROCEDURE WILL BE E.O. TO BRING UP TO SCHEMATIC LEVEL.</b>									
18. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE				19. FAILED ITEM NAME AND PART NUMBER <b>N/A.</b>					
20. NO DEFECT IN HARDWARE, TEST SPEC 16368 IN ERROR.									
21. AUTHORIZATION <b>[Signature]</b>				22. DATE <b>12-17</b>		23. DATE <b>13 25 80</b>		24. CONTINUATION SHEET USED <input type="checkbox"/>	
25. ACTION/RETEST ACTION TAKEN									
26. LIST ALL PARTS REPLACED									
PART NUMBER	CNT	SYM	PART LOT NO.	DATE CODE	WPR	REASONABLE DEFECT	ANALYSIS NO.		
27. REWORK BY				28. REQUESTED BY		29. DATE		30. CONTINUATION SHEET USED <input type="checkbox"/>	
31. CAUSE AND CORRECTIVE ACTION <b>TEST SPEC 16368 WAS IN ERROR E.O. 9732 DATED 4-24-80 CHANGED PROCEDURE.</b>									
32. DOCUMENT REPRESENTING CORRECTIVE ACTION						33. PRE CLOSURE			
34. BASIC CAUSE 35. VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS						36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER <b>[Signature]</b>						38. CUSTOMER OR SUPPLIER <b>[Signature]</b>			
39. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE						40. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
41. DATE <b>12-5-80</b>						42. DATE <b>6/11/80</b>			

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F 0622**

1. PROGRAM NAME AND NUMBER <b>HS 236TM</b>		2. GLA	3. MODEL <b>FL</b>	4. TIME OBSERVED <b>4 PM</b>	5. DATE OBSERVED <b>5 3 80</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MECHANISM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECHANISM <input checked="" type="checkbox"/> CARD		<b>POSTAMP BOARD 2</b>		<b>50904-2</b>	<b>2.01 HAC</b>
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IMPROGRESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MCH TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE		<b>ALL 16 CHANNELS EXCEED MAX GAIN OF 20 DB FOR MAX BOOST ABOVE THE 100 HZ GAIN.</b>			
15. TEST PROCEDURE <b>16368 4.3.8</b>		16. ORIGINATOR <b>N. PATTY</b>		<b>22.13</b>	<b>516-80</b>
17. VERIFICATION AND FAILURE ANALYSIS					
18. FAILED ITEM NAME AND PART NUMBER		<b>NONE</b>			
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE		<b>RESOLUTION OF FAILURE TO BE ACCOMPLISHED BY CHANGING TOLERANCE OF TEST PROCEDURE 16368 PAR 4.3.8 WITH AN E.O.</b>			
20. AUTHORIZATION		ORG		DATE	
21. Rework/Retest Action Taken <b>NO RETEST REQUIRED BECAUSE ORIGINAL SPECS WERE TOO STRINGENT. FAILURE CURED BY E.O.</b>		22. CONTINUATION SHEET USED		23. QA RESPONSE	
24. LIST ALL PARTS REPLACED		25. RETESTED BY		26. CONTINUATION SHEET USED	
27. Rework by		28. RETESTED BY		29. CONTINUATION SHEET USED	
30. CAUSE AND CORRECTIVE ACTION <b>E.O. 9897 CHANGED SPEC. MAX GAIN ALLOWED IS NOW 26 db. MAX TEST GAIN WAS 21.6 db. TEST DATA SHEETS ATTACHED</b>		31. PROS CLOSURE		32. CONTINUATION SHEET USED	
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIP. <input checked="" type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSE/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY	
36. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		37. RESPONSIBLE ENGINEER <b>SS M. M. RANDALL</b>		38. SPACECRAFT SYSTEM ENGR <b>SS S. G. OXLEY</b>	
39. RELIABILITY <b>51.41</b>		40. CUSTOMER OR SUPPLIER <b>51.41</b>		41. DATE <b>9-18-80</b>	



ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
FAILURE REPORT

**F** 1667

1. PROGRAM NAME AND NUMBER <i>TM, HS 236</i>		2. GLA	3. MODEL <i>F1+</i>	4. TIME OBSERVED <i>9:00A</i>	5. DATE OBSERVED <i>9 21 81</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<i>PWR ASSY-Motor Driver, Under Door</i>		<i>53877</i>	<i>101</i>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Adjusted Model 2005 Voltage reference to -1.500V, output was +5.628V and should be 0.00 ± 0.3V.</i>					
15. TEST PROCEDURE <i>16237</i>		16. PART <i>13.3.21</i>	17. ORIGINATOR <i>E. Aasted</i>	18. ORG	19. DATE <i>7-20-81</i>
20. VERIFICATION AND FAILURE ANALYSIS <i>Open Circuit on pin 4 of AR1, AR2, and AR3 where an incomplete "cut and jump" had been reworked per EO 2762A. Added resistors were soldered to traces to cut instead of to pad. No overstressed components.</i>					
21. FOLLOWING REPORT/RETEST REQUIRED <input type="checkbox"/> Rework to Print 53877 and EO 2762A					
22. AUTHORIZATION <i>E. Aasted</i>					
23. REWORK/RETEST ACTION TAKEN <i>Reworked To EO 2762A</i>					
24. FUNCTIONAL TEST <i>Functional Test per 16237 - Rev F</i>					
25. LIST ALL PARTS REPLACED					
26. REWORK BY <i>Hortencia Sanchez</i>					
27. DATE <i>9/21/81</i>					
28. RETESTED BY <i>E. Aasted</i>					
29. DATE <i>9-22-81</i>					
30. CAUSE AND CORRECTIVE ACTION <i>EO 2762A was not correctly implemented. More careful initial visual check prior to test will identify this problem in future. Mr. J. L. Duncan was informed of this problem and his instructions his supervisor to review current work closely to prevent wires from being wired to wrong terminations.</i>					
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>EO 2762A</i>					
32. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
33. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE <input type="checkbox"/> SECONDARY <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
34. RESPONSIBLE ENGINEER <i>A. Bonatti</i>					
35. DATE <i>22-13</i>					
36. SPACECRAFT SYSTEM ENGINEER <i>10-5-81</i>					
37. RELIABILITY <i>10-5-81</i>					
38. CUSTOMER OR SUPPLIER <i>10-5-81</i>					

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F 1668**

1. PROGRAM NAME AND NUMBER <b>TM, HS-236</b>		2. CL.	3. MODEL <b>F1+</b>	4. TIME OBSERVED <b>9:00A</b>	5. DATE OBSERVED <b>11/18/81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>PWJ Assy, Temp. Control</b> <b>50920</b> <b>101</b> <b>SBRC</b>					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>Mean resistance of values determined in 4.3.2 and 4.3.3 is not within specification limits, nor is it capable of being corrected per 10.1.5.3. Mean Value is 12.77K<math>\Omega</math> Should Be 10.41K<math>\Omega</math></b>					
15. TEST PROCEDURE <b>16236</b> PARA <b>4.3.4</b> 16. OPERATOR <b>E. Aasted</b> ORG <b>12213</b> DATE <b>11/18/81</b> 17. CONTINUATION SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS <b>Reworked To Print. R2 was 12.7K<math>\Omega</math> instead of 12.7K<math>\Omega</math> per print. R68 in a similar circuit was reworked as well. No overstress on any components.</b>					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>R2 and R68.</b>					
20. RETESTING already written in planning.					
21. AUTHORIZATION <b>E. Aasted</b> ORG <b>12213</b> DATE <b>11/18/81</b> 22. CONTINUATION SHEET USED					
23. REWORK/RETEST ACTION TAKEN <b>R2 and R68 removed and replaced with components per 50920 assembly print. Para 4.3 successfully performed.</b>					
24. LIST ALL PARTS REPLACED PART NUMBER CMT SYN PART LOT NO DATE CODE MFR PROBABLE DEFECT ANALYSIS NO.					
25. REWORK BY <b>M. Guerra</b> ORG <b>12274</b> DATE <b>11/18/81</b> 26. RETESTED BY <b>E. Aasted</b> ORG <b>12213</b> DATE <b>11/18/81</b> 27. CONTINUATION SHEET USED					
28. CAUSE AND CORRECTIVE ACTION <b>Assy component placement error. The value of the installed resistor was higher than print callout. This resistor is in series with a 10K resistor. The power dissipated across the resistors, <math>V^2/R</math>, was reduced, thereby eliminating the possibility of overstress. Technicians have been cautioned to check that proper values are fitted.</b>					
29. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
30. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input checked="" type="checkbox"/> ASSEMBLY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
31. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> INDUCED <input type="checkbox"/> NO FAILURE					
32. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
33. RESPONSIBLE ENGINEER <b>A.A. Banach</b> ORG <b>12213</b> DATE <b>12/15/81</b> 34. SPACECRAFT SYSTEM ENGINEER <b>Philip J. Engle</b> ORG <b>SBRC</b> DATE <b>12/2/8</b>					

ORIGINAL PAGE IS  
OF POOR QUALITY

11/17/81
101
1

DATE F/1668  
SER NO.  
SET NO.

SMA HEATER CONTROLLERS

- 4.3.1 + 80 V Line Current ✓ ( $\leq 1.0$  mA) LED IS ON OK (OK)  
+ 28 V Line Current ✓ ( $\leq 1.0$  mA)  
+ 21 V Line Current 22.96 mA ( $25 \pm 10$  mA)  
- 21 V Line Current 2.92 mA ( $5 \pm 4$  mA)
- 4.3.2 + 80 V Line current ✓ ( $\leq 1.0$  mA)  
+ 28 V Line Current 10.99 mA ( $800/1000/1300 \pm 150$  mA)  
+ 21 V Line Current 2.3 mA ( $25 \pm 10$  mA)  
- 21 V Line Current 2.9 mA ( $5 \pm 4$  mA)
- R1 12.8K $\Omega$  +Z HEATER 27.18V +Z COMP 1.39V +Z RET .32V TOGGLE OK (OK)  
10.337K $\Omega$
- 4.3.3 R2 12.74K $\Omega$  +Z HEATER 0.0V +Z COMP .271V +Z RET 28.11V
- 4.3.4 Mean (R1 + R2)/2 10.354K $\Omega$  ( $10.41$  K Ohms  $\pm 84$  Ohms)  
Difference (R1 - R2) 45 $\Omega$  (210 Ohms maximum)
- 4.3.5 + 80 V Line Current ✓ ( $\leq 1.0$  mA) LED IS OFF OK (OK)  
+ 28 V Line Current ✓ ( $\leq 1.0$  mA)  
+ 21 V Line Current ✓ ( $\leq 1.0$  mA)  
- 21 V Line Current ✓ ( $\leq 1.0$  mA)
- 4.3.6 + 80 V Line Current ✓ ( $\leq 1.0$  mA) LED IS ON OK (OK)  
+ 28 V Line Current ✓ ( $\leq 1.0$  mA)  
+ 21 V Line Current 18.65 mA ( $25 \pm 10$  mA)  
- 21 V Line Current 2.7 mA ( $5 \pm 4$  mA)
- 4.3.7 + 80 V Line Current ✓ ( $\leq 1.0$  mA)  
+ 28 V Line Current 11.30 mA ( $800/1000/1300 \pm 150$  mA)  
+ 21 V Line Current 14.6 mA ( $25 \pm 10$  mA)  
- 21 V Line Current 2.8 mA ( $5 \pm 4$  mA)
- R1 10.3824K $\Omega$  -Z HEATER 27.18V -Z COMP 2.333V -Z RET .291V TOGGLE ✓ (OK)
- 4.3.8 R2 10.309K $\Omega$  -Z HEATER 0.001 -Z COMP .269V -Z RET 28.14V
- 4.3.9 Mean (R1 + R2)/2 10.345K $\Omega$  ( $10.41$  K Ohms  $\pm 84$  Ohms)  
Difference (R1 - R2) 73 $\Omega$  (210 Ohms maximum)
- 4.3.10 + 80 V Line Current ✓ ( $\leq 1.0$  mA) LED IS OFF OK (OK)  
+ 28 V Line current ✓ ( $\leq 1.0$  mA)  
+ 21 V Line Current ✓ ( $\leq 1.0$  mA)  
- 21 V Line Current ✓ ( $\leq 1.0$  mA)



SIZE	CODE IDENT NO.	NUMBER
A	11323	16297
SCALE	REV D	SHEET 6

Sheet 6

PART NO. 50920		PART NAME PWB ASSY, Temperature Control		ASSY/LOT SERIAL NO. 101	QTY
OPER NO.	DATE	OPERATOR OR INSP	COMMENTS, TEST DATA, ETC	DISPOSITION	APPROVAL
1520	11/18/81	E. Hastad	1) Lift one leg of R2 for a measurement of its resistance. Refer to ER 1668. 2) Return to test for trouble shooting.	P.R. Drift Value R2 -	J. Miller
			RETURN TO MFG. ENG.		
1520	11/18/81	E. Hastad	Lifted one leg of R2		
	11-18-81	E. Hastad	Rework to print R2 and R68	P.R. Mfg Eng Comm	J. Miller
	11-18-81	P. Sierra	both are 12.7K $\Omega$ and should be 10.7K $\Omega$ .	to have 9 provide	
	11-18-81	P. Sierra	replaced R2 & R68	Planning	
1520	11/18/81	E. Hastad	R Change select nominals as follows: R302 From: 287 $\Omega$ To: 523 $\Omega$ R <sup>127</sup> <sub>127</sub> From: 287 $\Omega$ To: 487 $\Omega$ per <sup>para</sup> 10.1.5.3 of spec 16236		
	11/19/81	Sanchez	Reworked above		
1520	11/18/81	E. Hastad	Change select nominals as follows: R102 From: 523 $\Omega$ To: 619 $\Omega$ spec 16236 per 10.1.5.3 R127 From: 487 $\Omega$ To: 590 $\Omega$ spec 16236 per 10.1.5.3 R45 From: 18.2K $\Omega$ To: 17.8K $\Omega$ spec 16236 per 10.1.6.3		
	11/19/81	Sanchez	Changed above nominals		

ORIGINAL PAGE IS  
OF POOR QUALITY

F 1668



ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F 1761**

1. PROGRAM NAME AND NUMBER <b>HS 236 TM</b>		2. GLA		3. MODEL <b>PT-7</b>		4. TIME OBSERVED <b>1530</b>		5. DATE OBSERVED <b>2-27-80</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART		7. SUBSYSTEM NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		<b>POST AMP-BAND 1</b>		<b>50904-1 A</b>		<b>101</b>		<b>HAC</b>	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> PRODUCTION <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE <b>OFFSET LIMITS OUT OF SPEC ON ELEVEN CHANNELS</b>									
15. TEST PROCEDURE <b>16597 4-4</b>		16. ORIGINATOR <b>NILE PATTY</b>		17. DATE <b>2-27-80</b>		18. CONTINUATION SHEET USED			
19. VERIFICATION AND FAILURE ANALYSIS									
20. FOLLOWING REMOVAL/RETEST REQUIRED REMOVAL/RETEST NOT REQUIRED BECAUSE <b>This failure occurred when this PWB wasn't hardware. This PWB was replaced by SN 201 and SN 101 became flight. This PWB has had DC offset subject determined and tested on the flight hardware and was confirmed as good.</b>		21. AUTHORIZATION <b>WPM Randell</b>		DATE <b>2-22-80</b>		22. CONTINUATION SHEET USED			
23. REMOVAL/RETEST ACTION TAKEN <b>DC offset subject redetermined on flight Band 1 Band 2 and 3. Tests within specification. No over stress of any components.</b>		24. CAUSE AND CORRECTIVE ACTION <b>Could not be accomplished until flight Band 1 Band 2 and 3 was available. THE FLIGHT PWB (SN 201) WAS USED FOR P.F. BECAUSE OF SCHEDULE CONSIDERATIONS. SELTS FOR THIS CURRENT FLIGHT PWB (SN 101) HAD TO BE REDETERMINED TO BE COMPATIBLE WITH BAND 2 PREAMP TO MEET SPEC. REPAIRS. NO CORRECTIVE ACTION BEING</b>		25. PRECLOSURE <b>J. Brown 11/19/81</b>		26. CONTINUATION SHEET USED			
27. LIST ALL PARTS REPLACED PART NUMBER		CMT SYM		PART LOT NO.		DATE CODE		MFR	
28. REMOVED BY ORG		DATE		29. RETESTED BY		ORG		DATE	
30. CAUSE AND CORRECTIVE ACTION									
31. BASIC CAUSE 32. VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> NEAR-OUT <input type="checkbox"/> UNKNOWN DEFECT CODE									
33. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		35. SPACECRAFT SYSTEM ENGR <b>WPM Randell</b>		DATE <b>2-22-80</b>		36. CUSTOMER OR SUPPLIER <b>HS-41</b>	
37. RESPONSIBLE ENGINEER <b>WPM Randell</b>		DATE <b>2-22-80</b>		38. SPACECRAFT SYSTEM ENGR <b>WPM Randell</b>		DATE <b>2-22-80</b>		39. CUSTOMER OR SUPPLIER <b>HS-41</b>	
38. RESPONSIBILITY <b>WPM Randell</b>		DATE <b>2-22-80</b>		39. CUSTOMER OR SUPPLIER <b>HS-41</b>		DATE <b>2-22-80</b>		40. CUSTOMER OR SUPPLIER <b>HS-41</b>	

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
EQUIPMENT CHECKOUT  
FAILURE REPORT  
**CONTINUATION SHEET**

ORIGINAL PAGE IS  
OF POOR QUALITY

F1761

CONT. SHE  
LETTER

FR SERIAL NO.

\* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL P  
CONTINUATION  
SHEET(S) USED

30 ORIGINALLY THE PWB WAS TRIMMED FOR PROTFLIGHT.  
SUBSEQUENTLY IT WAS REMOVED AND PUT INTO THE FLIGHT UNIT,  
THEREFORE THE ORIGINAL SELECTS HAD TO BE RE-TRIMMED.  
11/23/81

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F** 1769

1. PROGRAM NAME AND NUMBER <b>HS 236</b>		2. CLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>1500</b>	5. DATE OBSERVED <b>3-25-80</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
7. EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
8. SUBSYSTEM					
9. UNIT					
10. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input checked="" type="checkbox"/> BAND 4 POST AMP					
11. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <b>50904-23 201 HAC</b>					
12. OTHER					
13. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> INPROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
14. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> TYPE <input type="checkbox"/> EMC/EMI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE					
15. DESCRIPTION OF FAILURE <b>CHANNEL SEVEN SINGLE ENDED OUTPUT IS REDUCED 7.2 DB WHEN VAL IS DISCONNECTED, 5.1 DB WHEN VOT IS DISCONNECTED. SHOULD BE <math>6 \pm 0.5</math> DB.</b>					
16. TEST PROCEDURE <b>16368 PAR 4.3.6</b> 18. ORIGINATOR <b>NILE PATTY 27</b> 19. DATE <b>3-26-80</b> 20. CONTINUATION SHEET USED					
17. VERIFICATION AND FAILURE ANALYSIS <b>CHANNEL SEVEN SINGLE ENDED OUTPUT MINIMALLY DEFECT. RECOMMEND REPLACEMENT OF U3. CONFIGURATION DID NOT VARY FROM PRINT. NO OUT OF SPEC POWER WAS APPLIED, THEREFORE NO ELECTRICAL STRESS COULD HAVE BEEN INDUCED.</b> 18. FAILED ITEM NAME AND PART NUMBER <b>50859-4 9C467P-04</b>					
21. FOLLOWING Rework/Retest Required Because <b>REPLACE U3 AND RETEST TO 16368 PAR 4.3.6.</b>					
22. AUTHORIZATION <b>R. L. Kelly</b> ORG <b>122-67</b> DATE <b>13-26-80</b> 23. CONTINUATION SHEET USED					
24. REWORK/RETEST ACTION TAKEN <b>U3 Replaced and retested per 16368 Par 4.3.6 ATTACHED AHR SHOWS SUCCESSFUL COMPLETION OF 16368 ON 4-1-80.</b>					
25. LIST ALL PARTS REPLACED					
26. CAUSE AND CORRECTIVE ACTION <b>See attached memo HS-236-6824</b>					
27. HYBRID PASSES ACCEPTANCE TEST PROCEDURE BUT FAILS TO PERFORM PROPERLY IN CIRCUIT. SUSPECT BUILDUP OF TOLERANCES. CHANGE OF HYBRID CORRECTS CIRCUIT ANOMALY.					
28. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
29. BASIC CAUSE OF FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input checked="" type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
30. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
31. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
32. RESPONSIBLE ENGINEER <b>W. H. Newkirk</b> ORG <b>SBRC</b> DATE <b>6/25/80</b>					
33. RELIABILITY <b>51.91</b> DATE <b>16-25-80</b> 34. CUSTOMER OR SUPPLIER <b>AB</b>					

SANTA BARBARA RESEARCH CENTER  
A Subsidiary of Hughes Aircraft Company

INTERNAL MEMORANDUM

F 1769

TO: Distribution

CC:

ORIGINAL PAGE IS  
OF POOR QUALITY

DATE: 15 May 80

REF: HS-236-6824

REF 80/21

FROM: [REDACTED]

SUBJECT: Failure of Hybrid Postamp S/N 84

BLDG. TLR5 MAIL STA. 17  
EXT. 2597

Ref: FR F1769 Hybrid Postamp P/N 50859-4 (HAC P/N 1950588-100) S/N 84

This hybrid failed during test of the Band 4 postamp PWB P/N 50904-4 S/N 201. Failure mode was "fails single ended output test S/B  $-6 \pm 0.5$  db, is VOL disconnected = 7.2 db VOH disconnected = 5.1 db". When tested at Fullerton to the acceptance test procedure the device tested acceptable. I requested that a 100Hz signal be applied to the failed channel and VOH be disconnected after a reference point was determined. This duplicated the card level test that the device failed at SBRC. The test results are as follows:

VOH disconnected = loss of 5.5 db.

VOL disconnected = loss of 6.5 db.

This is very close to the readings recorded at SBRC when the tolerance of the monitoring equipment is taken into consideration. The readings at Fullerton were, in any event, at the limit of the established tolerance of  $\pm 0.5$  db. There does not appear to be a specific test that is an equivalent of the single ended output test performed at SBRC. A consensus of opinion is that the common mode rejection test performed at the hybrid level is the same type of test, but there appears to be some question concerning the allowable tolerance.

Mike Slonaker is looking into the details of the test method and parameters. No further analysis is considered necessary at this time. The device was not delidded and is presently being held by SBRC Reliability pending resolution of the failure report.

*M. R. Heath*  
M. R. Heath  
TM Reliability

/akh

Distribution:

L. Altman  
S. Branda  
R. Cooley  
D. Randall  
C. Rodil  
M. Slonaker  
P. Tannous  
L. Wolthausen  
System Test Data Library (11 copies)

F1269

THEMATIC MAPPER	HUGHES AIRCRAFT COMPANY FULLERTON MICROELECTRONIC TEST DATA SHEET	DATE: 12/31/9	
1950599-100		PAGE 1	OF 2
P/N: 50859-4		P.O. No.	
Date Code & S/N 4679-84	POST AMPLIFIER	SPEC NO.: 16075	REV R

ORIGINAL PAGE IS  
OF POOR QUALITYParagraph NoResults

	<u>Pre Burn-In</u>		<u>Final Elect.</u>		<u>Limits &amp; Conditions</u>
	<u>CHA</u>	<u>CHB</u>	<u>CHA</u>	<u>CHB</u>	
13.1 <u>Power</u>					
I +15	1.67 mA	1.61 mA	1.68 mA	1.61 mA	< 2 ma
I -15	1.67 mA	1.60 mA	1.69 mA	1.62 mA	< 2 ma
13.2 <u>Preampl Bias</u>					
PL	-4.95 V	-4.93 V	-4.95 V	-4.93 V	-5 ± 10% volts
13.3 <u>Input Balance</u>					
IN + IL	0.5 mV	0.4 mV	0.6 mV	0.4 mV	3.0 mV p-p 100Hz - 100KHz max.
13.4 <u>Low Frequency Gain</u>					
OH - OL 100Hz	9.5 dB	9.3 dB	9.5 dB	9.3 dB	9.7 ± 1 dB
OH + OL	-43 dB	-31 dB	-42 dB	-31 dB	Min. -20dB below OH - OL
13.5 <u>Frequency Response and</u>					
13.6 <u>Common Mode Rejection</u>					
OH - OL 5KHz	4.2 dB	4.2 dB	4.2 dB	4.1 dB	+4/+5dB ref. 100Hz Gain
OH + OL	-36 dB	-32 dB	-35 dB	-31 dB	Min. -20dB below OH - OL
OH - OL 10KHz	8.5 dB	8.3 dB	8.7 dB	8.5 dB	+8/+10dB ref. 100Hz Gain
OH + OL	-32 dB	-33 dB	-35 dB	-33 dB	Min. -20dB below OH - OL
OH - OL 20KHz	14.3 dB	13.8 dB	14.1 dB	13.8 dB	+13/+15dB ref. 100Hz Gain
OH + OL	-38 dB	-36 dB	-38 dB	-35 dB	Min. -20dB below OH - OL
OH - OL 40KHz	18.7 dB	18.4 dB	18.9 dB	18.6 dB	+17/+20dB ref. 100Hz Gain
OH + OL	-28 dB	-33 dB	-29 dB	-33 dB	Min. -20dB below OH - OL
OH - OL 50KHz	18.6 dB	18.5 dB	19.1 dB	18.8 dB	+17/+20dB ref. 100Hz Gain
OH + OL	-25 dB	-32 dB	-25 dB	-31 dB	Min. -20dB below OH - OL

DUGHER AIRCRAFT COMPANY  
FULLERTON CALIFORNIA

MICROELECTRONIC  
TEST DATA SHEET

PART NO. 1950502-100

S/R:

PAGE 2 OF 2

DATE:

F1769

Paragraph No.	Pre Burn-in	Final Elect.	Limits & Conditions
13.5 and 13.6 (cont.)			
OH - OL 60KHz	<u>17.6 dB</u>	<u>17.3 dB</u>	<u>17.8 dB</u> <u>17.5 dB</u> +15/+19db ref. 100Hz Gain
OH + OL	<u>-24 dB</u>	<u>-33 dB</u>	<u>-24 dB</u> <u>-33 dB</u> Min. -20db below OH - OL
OH - OL 100KHz	<u>8.1 dB</u>	<u>7.6 dB</u>	<u>8.2 dB</u> <u>7.7 dB</u> +1/+10db ref. 100Hz Gain
OH + OL 100KHz	<u>-23 dB</u>	<u>-32 dB</u>	<u>-23 dB</u> <u>-34 dB</u> Min. -20db below OH - OL

13.7 Supply Voltage Rejection

OH - OL (+15V)	<u>9 mv</u>	<u>9 mv</u>	<u>8 mv</u> <u>8 mv</u> < 100 mv p-p
OH + OL (+15V)	<u>11 mv</u>	<u>12 mv</u>	<u>11 mv</u> <u>12 mv</u> < 100 mv p-p
OH - OL (-15V)	<u>8 mv</u>	<u>7 mv</u>	<u>7 mv</u> <u>7 mv</u> < 100 mv p-p
OH + OL (-15V)	<u>2 mv</u>	<u>2 mv</u>	<u>2 mv</u> <u>2 mv</u> < 100 mv p-p

13.8 D.C. Offset

OH	<u>-16 mv</u>	<u>-5 mv</u>	<u>19 mv</u> <u>-8 mv</u> 0 ± 340 mv max.
OL	<u>18 mv</u>	<u>12 mv</u>	<u>20 mv</u> <u>16 mv</u> 0 ± 340 mv max.

13.9 Roll off Terminal Check

Terminal 56 & 47	<u>13.63 K<math>\Omega</math></u>	<u>13.60 K<math>\Omega</math></u>	12.9K - 15.4K
Terminal 41 & 33	<u>13.65 K<math>\Omega</math></u>	<u>13.63 K<math>\Omega</math></u>	12.9K - 15.4K

ORIGINAL PAGE IS  
OF POOR QUALITY

Tested by:

Quality/Responsible Engineer:

38R 12-12-79

THEMATIC MAPPER		HUGHES AIRCRAFT COMPANY FULLERTON MICROELECTRONIC TEST DATA SHEET		DATE: 4-9-80	
1050580-100				Page 1 of 2	
P/N: 50859-4				P.O. No.	
Date Code & S/H 4679 84		POST AMPLIFIER		SPEC NO.: 16075 REV R	

Paragraph No. Results ORIGINAL PAGE IS OF POOR QUALITY F1769

Paragraph No.	Pre-Burn-In		Final Elect.		Limits & Conditions
	CHA	CHB	CHA	CHB	
13.1 Power					
I +15	1.67mA	1.61mA			< 2 ma
I -15	1.67mA	1.60mA			< 2 ma
13.2 Preamp Bias					
RL	-4.99v	-4.98v			-5 ± 10% volts
13.3 Input Balance					
III + IL	0.64v	0.4mw			3.0 mv p-p 100Hz - 100KHz max.
13.4 Low Frequency Gain					
OH - OL 100Hz	+7.5dB	+7.3dB			9.7 ± 1 db
OH + OL	-45dB	-31dB			Min. -20db below OH - OL
13.5 Frequency Response and					
13.6 Common Mode Rejection					
OH - OL 5KHz	+4.5dB	+4.2dB			+4/+5db ref. 100Hz Gain
OH + OL	-39dB	-33dB			Min. -20db below OH - OL
OH - OL 10KHz	+9.1dB	+9.0dB			+8/+10db ref. 100Hz Gain
OH + OL	-38dB	-34dB			Min. -20db below OH - OL
OH - OL 20KHz	+14.5dB	+14.4dB			+13/+15db ref. 100Hz Gain
OH + OL	-38dB	-36dB			Min. -20db below OH - OL
OH - OL 40KHz	+19.4dB	+19.0dB			+17/+20db ref. 100Hz Gain
OH + OL	-27dB	-33dB			Min. -20db below OH - OL
OH - OL 50KHz	+19.5dB	+19.3dB			+17/+20db ref. 100Hz Gain
OH + OL	-25dB	-32dB			Min. -20db below OH - OL

*F1769*

Paragraph No.	Pre Burn-in	Final Elect.	Limits & Conditions
13.5 and 13.6 (cont.)			
OH - OL 60KHz	<i>+18.2dB</i>	<i>+18.0dB</i>	+15/+19db ref. 100Hz Gai
OH + OL	<i>-24dB</i>	<i>-32dB</i>	Min. -20db below OH - 0
OH - OL 100KHz	<i>+8.9dB</i>	<i>+8.5dB</i>	+1/+10db ref. 100Hz Gai
OH + OL 100KHz	<i>-24dB</i>	<i>-32dB</i>	Min. -20db below OH - 0

13.7 Supply Voltage Rejection

OH - OL (+15V)	<i>8mv</i>	<i>8mv</i>	<100 mv p-p
OH + OL (+15V)	<i>10mv</i>	<i>10mv</i>	<100 mv p-p
OH - OL (-15V)	<i>8mv</i>	<i>7mv</i>	<100 mv p-p
OH + OL (-15V)	<i>2mv</i>	<i>2mv</i>	<100 mv p-p

13.8 D.C. Offset

OH	<i>-16mv</i>	<i>-5mv</i>	0 + 300 mv max.
OL	<i>+17mv</i>	<i>+13mv</i>	0 + 340 mv max.

13.9 Roll off Terminal Check

Terminal 56 & 47		12.9K - 15.4K
Terminal 41 & 33		12.9K - 15.4K

ORIGINAL PAGE IS  
OF POOR QUALITY

Tested by: *AJ [signature]* / *12-61*

Quality/Responsible Engineer: \_\_\_\_\_



PART NO.	DATE	OPERATOR OR INSP	PART NAME	COMMENTS, TEST DATA, ETC	ASSY/LOT SERIAL NO.	QTY
50904-4			CUB Assy Coolamplysis 1-4		201	1
OPER NO.	DATE	OPERATOR OR INSP	COMMENTS, TEST DATA, ETC		DISPOSITION	APPROVAL
500	3-21/80	H	CR 57 thru 72 missing from 1st		P.R. P.C.F. & Review 7	J. Wells
					Proceed to 1769	3-20-80
500	3-25-80	M. Pally	FAILED TEST 4.3.6 (CH. 7) EXCEEDS $60 \pm 45$ DB, IS 7.2 DB WHEN Vol Disc., 5.1 WHEN $V_{OH}$ DISC. SEG 1769 gain			
500	3-26-80	R. Baer	REPLACE failed (U3) 50859-4 POST-RMP HYBRID.		REF FAILURE REPORT 1769	
			<del>to inspect installation of new hybrid</del>		REPLACE U3 AND RETEST TO 16368, PAR 43.6	J. Wells
	3-31/80	M. King	replaced above		P.R. Place of test	
500	MAR 31 1980		INSPECT INSTALLATION OF U3		7-302310	
	4/1/80		M.C.I.		1 Route 2. Ray	
			RETEST TO 16368 AND CONTINUE OPER 500		14-11-1980	
500	4-1-80	M. Pally	RETESTED PER 16368 - OK		PROCEED	J. Wells
				ORIGINAL PAGE IS OF POOR QUALITY		

ORIGINAL PAGE IS OF POOR QUALITY

1769

SBRC

## ASSEMBLY HISTORY RECORD CONTINUATION SHEET

SHEET 5 OF 9

PART NUMBER

50904-4

SERIAL OR LOT NUMBER

201

ASSEMBLY NAME

PWB AYSY POSTAMPLIFIER 1-4

CONTINUATION OF:

AIR DATED 3-3-80

AIR SUPPLEMENT NO.

OPER  
NO.S/C  
NO.

## INSTRUCTIONS

PERFORMED BY

OPER

INSP

DATE

## REMARKS

NOTE: Notify QA &amp; AF prior to start of testing.

200

22-13

1) Perform initial circuit test at ambient temperature per Spec 16368.

M. Kelly

112

3-25-80

FAILED TEST  
PARA 4.3.6 (C11,7)

FR 1769 R.R. 4-11-80

2) Perform Electrical test per Spec 16597. Para 4.0

3) Select components using Spec 16597 &amp; per B/P

note 16 &amp; 22.

M. Kelly

4-1-80

TESTED ON  
16368 ON (GI)

4) Record selected values on test data sheet with traceability.

SEE MASTER PLANNING DATED 3/25/80  
FOR CONTINUATION.

200

2-14

Kit and enter traceability of selects R1-R16, R17-R32, R65-R80, R81, R96, C33-C46 and C57-C72 on ABC/TH from test data sheets and MR.

900

51-11

Inspect selects.

ORIGINAL PAGE IS  
OF POOR QUALITY

FR 1769

ORIGINAL PAGE IS  
OF POOR QUALITY

DE  
Removal

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
FAILURE REPORT

F 1774

1. PROGRAM NAME AND NUMBER <b>HS 136 TM</b>		2. GLA	3. MODEL <b>FL</b>	4. TIME OBSERVED <b>2 PM</b>	5. DATE OBSERVED <b>3 5 80</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<b>POSTAMP BAND 7</b>		<b>50908-2</b>	<b>201 HAC</b>
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>ALL 16 CHANNELS EXCEED MAX GAIN OF 20 DB FOR MAX BOOST ABOVE THE 100 HZ GAIN.</b>					
15. TEST PROCEDURE <b>16368 4.3.8</b>		16. ORIGINATOR <b>N. PATTY</b>		ORG <b>72</b>	DATE <b>13 5-80</b>
17. VERIFICATION AND FAILURE ANALYSIS <b>FAILURE WILL BE RESOLVED BY CHANGING TOLERANCES IN TEST PROCEDURE 16368 PARAGRAPH 4.3.8</b>					
18. FAILED ITEM NAME AND PART NUMBER					
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE <b>RESOLUTION OF FAILURE TO BE ACCOMPLISHED BY CHANGING TOLERANCE OF TP. 16368 PAR 4.3.8 WITH AN E.O.</b>					
20. AUTHORIZATION <b>[Signature]</b> ORG <b>72</b> DATE <b>15-5-80</b>					
21. REWORK/RETEST ACTION TAKEN <b>NO RETEST REQUIRED. ORIGINAL SPECS WERE TOO STRINGENT. <del>WAS</del> E.O. 9897 RESOLVES PROBLEM.</b>					
22. LIST ALL PARTS REPLACED					
PART NUMBER	CKT SYN	PART LOT NO.	DATE CODE	MSR	PROBABLE DEFECT
23. CAUSE AND CORRECTIVE ACTION <b>THIS IS NOT A FAILURE - UP ORIGINAL SPECIFICATIONS WERE TOO STRINGENT. E.O. 9897 CHANGES REQUIREMENTS AND ITEM IS NOW WITHIN SPEC. NEW MAX GAIN IS 26 db. MAX TEST GAIN WAS 23.2 db. TEST DATA SHEETS ATTACHED.</b>					
24. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>E.O. 9897</b>					
25. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> SAFETY					
26. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
27. RESPONSIBLE ENGINEER <b>[Signature]</b> ORG <b>72</b> DATE <b>15-5-80</b>					
28. SPACECRAFT SYSTEM ENGR <b>[Signature]</b> ORG <b>72</b> DATE <b>15-5-80</b>					
29. RELIABILITY <b>[Signature]</b> ORG <b>72</b> DATE <b>15-5-80</b>					

DE  
REMOVE

HUGHES AIRCRAFT COMPANY

F 1776

1. PROGRAM NAME AND NUMBER <b>HS 236 TH</b>		2. CLA		3. MODEL <b>FL</b>		4. TIME OBSERVED <b>10 AM</b>		5. DATE OBSERVED <b>9-5-80</b>		NO. <b>5</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:				NAME		PART NUMBER		S/N		MANUFACTURER	
7. SUBSYSTEM											
8. UNIT											
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY											
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD				<b>POST AMB BAND 1</b>		<b>50904-1</b>		<b>2.01</b>		<b>HAC</b>	
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMPERATURE _____ ° AXIS FOR _____ MIN TYPE _____		<input type="checkbox"/> THERMAL VAC _____ °		<input type="checkbox"/> HSE AT _____ °			
14. DESCRIPTION OF FAILURE <b>ALL 16 CHANNELS EXCEED MAX. GAIN OF 20 DB FOR MAX BOOST ABOVE THE 100 HZ GAIN</b>											
15. TEST PROCEDURE <b>16368 4.3.8</b>				16. ORIGINATOR <b>N. PATTY</b>		17. ORG <b>22-13</b>		18. DATE <b>9-6-80</b>		<input type="checkbox"/> CONTINUATION SHEET USED	
19. VERIFICATION AND FAILURE ANALYSIS <b>RESOLUTION OF FAILURE TO BE ACCOMPLISHED BY CHANGING TOLERANCES OF TEST PROCEDURE 16368 PAR 4.3.8 WITH AN E.O.</b>											
				19. FAILED ITEM NAME AND PART NUMBER <b>NONE</b>							
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE <b>RESOLUTION OF FAILURE TO BE ACCOMPLISHED BY CHANGING <del>NONE</del> TOLERANCES IN T.P. 16368 PARA 4.3.8</b>											
				21. AUTHORIZATION <i>[Signature]</i>		17. ORG <b>22-13</b>		18. DATE <b>9-5-80</b>		<input type="checkbox"/> CONTINUATION SHEET USED	
22. REWORK/RETEST ACTION TAKEN <b>NO RETEST REQUIRED. ORIGINAL SPECS WERE TOO STRINGENT. EO 9897 RESOLVES PROBLEM</b>										24. QA REWORK	
										25. QA RETEST	
26. LIST ALL PARTS REPLACED											
PART NUMBER		CCT SYN		PART LOT NO.		DATE CODE		MFR		PRIORABLE DEFECT	
27. REWORK BY _____ ORG _____ DATE _____				28. RETESTED BY _____ ORG _____ DATE _____						<input type="checkbox"/> CONTINUATION SHEET USED	
29. CAUSE AND CORRECTIVE ACTION <b>THIS IS NOT A CHANGE - UP</b>											
<b>ORIGINAL SPECIFICATIONS WERE TOO STRINGENT. EO 9897 CHANGES REQUIREMENTS AND PARTS ARE NOW WITHIN SPEC. NEW MAX GAIN ALLOWED IS 26 db, MAX TEST GAIN WAS 21.6. TEST DATA SHEETS ATTACHED</b>										33. PRG CLOSURE	
										<input type="checkbox"/> CONTINUATION SHEET USED	
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>EO 9897</b>											
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP <input checked="" type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SETUP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input type="checkbox"/> UNKNOWN DEFECT CODE			
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> MINOR		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
37. RESPONSIBLE ENGINEER <b>W. K. [Signature]</b>		38. SPACECRAFT SYSTEM ENGR <b>[Signature]</b>		39. CUSTOMER OR SUPPLIER <b>[Signature]</b>		ORG <b>46-1</b>		DATE <b>9-19-80</b>			
39. RELIABILITY <b>51-41</b>		DATE <b>9-10-80</b>									

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F 1781**

1. PROGRAM NAME AND NUMBER <b>HS 236 T.M.</b>		2. GLA	3. MODEL <b>FLT R/W</b>	4. TIME OBSERVED <b>1110A</b>	5. DATE OBSERVED <b>5-8-80</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<b>MACB - DESCARTES GEN#1</b>		<b>51795</b>	<b>102</b>
11. OTHER					<b>HAC</b>
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> WIN <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>PINS 2, 6 AND 10 ON U35 SHORTED TOGETHER.</b>					
15. TEST PROCEDURE <b>16423</b> PARA <b>5.3.3</b> 16. ORIGINATOR <b>J.A. Banach</b> ORG <b>22-13</b> DATE <b>11-9-80</b> CONTINUATION SHEET USED					
17. VERIFICATION AND FAILURE ANALYSIS <b>PHYSICAL EXAMINATION SHOWS NO SOLDERING DEFECTS OR INSTALLATION DEFECTS. PINS 2, 6 AND 10 TO BE LIFTED TO ISOLATE DEFECTS.</b>					
18. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE <b>REMOVE SHORT ON PWB TRACES FOR U35 PINS 2, 6, 10</b> <b>Heatsink removed on MRCO 295760.</b> <b>Retest per 16423 Para 5.3.3</b>					
21. AUTHORIZATION <b>J.A. Banach</b> ORG <b>22-13</b> DATE <b>5-9-80</b> CONTINUATION SHEET USED					
23. REWORK/RETEST ACTION TAKEN <b>Heatsink removed, shorted traces opened</b> <b>Retest per 16423 Para 5.3.3</b>					
24. CAUSE <b>11-19-80</b>					
25. CAUSE <b>11-19-80</b>					
26. LIST ALL PARTS REPLACED					
PART NUMBER EXT SYM PART LOT NO DATE CODE MFR PROBABLE DEFECT ANALYSIS NO.					
27. REWORK BY <b>A. BROWN</b> ORG <b>22-17</b> DATE <b>1-21-80</b> 28. RETESTED BY <b>J. GUYTON</b> ORG <b>22-13</b> DATE <b>11-9-81</b> CONTINUATION SHEET USED					
29. CAUSE AND CORRECTIVE ACTION <b>PRINTED WIRING BOARD FABRICATED WITH TRACE ERROR.</b>					
CHECK PWB TRACES COMPLETELY PRIOR TO HEATSINK INSTALLATION AND COMPONENT PLACEMENT.					
CIA - PARTS DISPOSITION THEN MRB SEE NCMR #290489					
DATE 5/12/80 (ATTACHED) WITH NO FUTURE COMPLICATIONS NOTED.					
STRESS ANALYSIS REPORT (ATTACHED) HS-236-172					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>MRCO 295760, NCRM # 290489 (ATTACHED)</b>					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PART <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC. <input type="checkbox"/> TEST SET UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSEMBLY ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
36. FAILURE CLASSIFICATION <input checked="" type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
37. RESPONSIBLE ENGINEER <b>J.A. Banach</b> ORG <b>22-13</b> DATE <b>11/17/81</b>					
38. SPACECRAFT SYSTEM ENGINEER <b>John Banach</b> ORG <b>22-41</b> DATE <b>11/19/81</b>					
39. RELIABILITY <b>100%</b> ORG <b>31-41</b> DATE <b>11/18/81</b>					
40. CUSTOMER OR SUPPLIER <b>Boeing</b> ORG <b>22-41</b> DATE <b>11/19/81</b>					

# FORMS INSTRUCTIONS FOR FORM 11628 CS (COMPLETE ONLY APPLICABLE BLOCKS)

DIVISIONAL INSTRUCTIONS  
PROVIDE INFORMATION.

SPECIFIC WORK STATIONS OR  
SPECIFIC ORG CODES

WORK TRANSFER DOCUMENTS ETC.

THIS LINE USED BY REC. INSP

SPECIFY CLEAR CONCISE  
DESCRIPTION OF EACH  
NONCONFORMITY, INCLUDING:

- (1) SERIAL NO.
- (2) DRAWING AREA OR LOCATION
- (3) IS: S/B TOLERANCES
- (4) SPECIFICATION PARA. REF. NO.,  
ETC.

DIVISIONAL PROCEDURES SPECIFY  
LEVEL OF PERSONNEL REQUIRED

THIS AREA TO BE USED AS  
NECESSARY TO SPECIFY:

1. REPAIR INSTRUCTIONS
2. REWORK INSTRUCTIONS
3. USE AS IS JUSTIFICATION
4. MRU INSTRUCTIONS

DISTRIBUTION DETERMINED  
BY DIVISIONAL INSTRUCTIONS

CORRECTIVE ACTION STATEMENTS  
SHOULD INCLUDE THE FOLLOWING

- (1) DESCRIPTION OF THE CAUSE  
OF THE NONCONFORMANCE
- (2) ACTION TAKEN TO PREVENT  
RECURRENCE
- (3) EFFECTIVITY OF C/A BY DATE,  
LOT OR S/N

HUGHES

PROBLEM NO.

DATE


REPAIR INSTRUCTIONS

REWORK INSTRUCTIONS

USE AS IS JUSTIFICATION

MRU INSTRUCTIONS

11628 CS July 77



ORIGINAL PAGE IS  
OF POOR QUALITY

THIS LINE USED BY MATERIEL

WHEN SUPPLIER CORRECTIVE  
ACTION IS REQUESTED THE SUPPLIER  
CORRECTIVE ACTION REQUEST  
(SCAR) IS USED

F11781

**WILSON JAMES L. LIBRARY**

PROGRAM ID THEMATIC MAPPER VO12

YPRG/X-17

0489

5/12/50

OF

RT NO. 51495		S/N 102		ENG. CHANGES		NOMENCLATURE MICRO DISC SET 1 PLUB	
JMK ORDER DOC NO.		LOT SIZE 1	QTY. SUSP 1	SUSPENDED IN TEST	HARDWARE I.D. NO.		REF. DOCUMENTS
PPLIER HAC E/S			DIV. OR LOCATION		SUPPLIER CODE	P.O. NO. PA 9300	ITEM NO.
							R.R. NO.

ITEM NO.	QTY INSP.	QTY SUSP.	DESCRIPTION OF NONCONFORMANCE	RESP. DEPT.	PRIOR OCCUR.	M.A. LEVEL	CODE
1	1	1	STARTED TRACE FAKSIDE IN AREA OF COMPONENT U-35. (FEEDTHRU HOLES ACROSS PINS 2 & 6) SEE X-RAY PROVIDED.		10	MIKE	

INITIATOR	M. G. Givicka	DATE	2/12/80	QUALITY	J. J. Givicka	DATE	3-22-80	ENGINEERING	A. E. Givicka	DATE	3-17-80
-----------	---------------	------	---------	---------	---------------	------	---------	-------------	---------------	------	---------

EM	DISP.	DISPOSITION/INSTRUCTIONS	STAMP
----	-------	--------------------------	-------

TO	CODE			
1	1	REMOVE M/S FROM PWB FOR FURTHER EVALUATION, PEK AIR	RETURN TO MKB	(107)
b			(C) PROCEED AT LOW ALTITUDE WITH HELICOPTER FORMATION AFTERWARDS / ... ... ..	

ENGINEER *[Signature]* DATE *5/22/80* QUALITY *[Signature]* DATE *6-11-80* CUSTOMER *[Signature]* DATE *10-23/80*

EM 10.	CAUSE OF NONCONFORMANCE	RESULTS OF CORRECTIVE ACTION INVESTIGATION	CORRECTIVE ACTION

1	ISOLATED ERROR CAUSED BY SICK SCREEN PROCESSING AT PCB MANUFACTURER.	Isolated process error not expected to be repetitive
---	--	--

SIGNATURE *W. H. Brant* DATE *10-23-81* SIGNATURE *H. H. Brant* DATE *10-23-81*

RESPONSIBILITY		DEBIT VENDOR		DISP CODE	VENDOR PACKING SHEET	QTY. R.T.V.	QTY. SCRAP	BUYERS SIGNATURE	DATE	COPY
NDOR	HAC	YES	NO							
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>							

ORIGINAL PAGE IS  
OF POOR QUALITY

41781

ORIGINAL PAGE IS  
OF POOR QUALITY

F1781

MATERIAL REVIEW  
CONTROL ORDER

MRCO

3	0	0	4	8	9	R
W	/	A	V	0	1	2

CONTINUATION SHEET

PAGE 2 OF     

OPR NO.	INSTRUCTIONS	DATE	QTY ACC	QTY SUS	INSP OPER	COMMENTS
2214 600	1. CLEAN SURFACES OF ITEMS 1 & 2 PER SP 80030, PARA 3.3.9.1 & BIP NOTE (17).	10/24/			START	
	2. PRIME BONDING SURFACE OF H/P PER SH 80145 TYPE 1 & BIP NOTE (17) CURE 1 HRS. AT 100°F					MIX NO. 5320
	3. BAND ITEMS 1 & 2 PER SP 80042 & BIP NOTE (13). USE TAPING #V012-3350 MAINTAIN DHT'S. OF SH. 3 SEC. B-B CURE 4 HRS. AT 100°F					MIX NO. 5321
51-11	INSPECT ABOVE ACTIVITIES.	10/27/81	1	0		
GSE	HCE.	10/27/81				
LAST	RETURN THIS CARD TO MATERIAL REVIEW FOR RECORD CLEARANCE.					
CPR						

SB 0344-B-1 FEB 78

Revised Planning 9/25/80 Thomas



ORIGINAL PAGE IS  
OF POOR QUALITY

F178

MATERIAL REVIEW  
CONTROL ORDER

MRCO

3 0 0 4 8 9  
W / A V 0 1

PART NO. 51795 REVISION     

PART NAME MACRO DISCRETE NO1 PWB

QUANTITY 1 S/N 102

ROUTE TO: RM 5322

P. O. MASTER CLEARED     

S/C	OPR NO.	INSTRUCTIONS	DATE	QTY ACC	QTY SUS	INSP OPER	COMMENTS
22-14	100	REMOVE HEATSINK FROM PWB	6/19/80			SPK	
	200	INSPECT AND IDENTIFY SHORT	6/19/80 AUG 21 1980			25- 277 (113)	Determine cause of CH PHI L.H. H. 425
	300	REMOVE SHORT	8/21/80			114 Finger	
	400	INSPECT	AUG 21 1980			(113)	
	500	MCT	8/21/80	0	1	(113)	INSUFFICIENT PWB INSTRUCTIONS F CLEANING & BONDING THE HEAT SINK TO THE
	600	BOND HEATSINK TO PWB	8/22/80	1	0	(113) 2718	SEE CONTINUATION FOR ADDITIONAL MIX NO.
		CURE HRS <u>    </u>					
	700	INSPECT					
LAST		RETURN THIS CARD TO MATERIAL REVIEW FOR RECORD CLEARANCE					
OPR							

SB 0344-B-1 FEB 78

QA APPROVAL     

DATE 6/19/80

ENG APPROVAL     

DATE 5/22/8

F1781

T3  
TEST PROGRAM NO. 3 - - - - > MACRO DISCRETE CMD. TEST - CH #1  
SENDS ALTERNATING BIT PATTERN TO  
BOARD AND VERIFIES PROPER OPERATION

ENTER OPERATOR DATA, YES OR NO : N

PRINT VERIFICATION ERRORS, YES OR NO : Y

ORIGINAL PAGE IS  
OF POOR QUALITY

CURRENT CYCLE COUNT IS : 0000000050

CURRENT ERROR COUNT IS : 0000000000

MONITOR

T3  
TEST PROGRAM NO. 3 - - - - > MACRO DISCRETE CMD. TEST - CH #1  
SENDS ALTERNATING BIT PATTERN TO  
BOARD AND VERIFIES PROPER OPERATION

ENTER OPERATOR DATA, YES OR NO : Y

ASSY. NO.: ----- 51795  
CARD NAME: ----- MACRODISCRETE CMD GEN #1  
SERIAL NO.: ----- 102  
DATE & TIME: ----- NOV 15 '81 9:11  
PRI. OR RDT.: --- RDT  
TEST OPERATOR: -- J BANACH  
OTHER TEST  
CONDITIONS: ----- LIFE CYCLE TESTING AT AMBIENT (RDT)

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)

G

PRINT VERIFICATION ERRORS, YES OR NO : Y

CURRENT CYCLE COUNT IS : 0001011026

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- NOV 17 '81 8:05  
PRI. OR RDT.: --- RDT  
TEST OPERATOR: -- J BANACH  
OTHER TEST  
CONDITIONS: ----- LIFE CYCLE TESTING AT AMBIENT (RDT)

ORIGINAL PAGE IS  
OF POOR QUALITY

F1781

HH>>S=9%Q=IJRT>>>5RZ>>WHH>>>S=9%Q=IJRT>>>5RZ>>

MONITOR

T3

TEST PROGRAM NO. 3 - - - - > MACRO DISCRETE CMD. TEST - CH #1  
SENDS ALTERNATING BIT PATTERN TO  
BOARD AND VERIFIES PROPER OPERATION

ENTER OPERATOR DATA, YES OR NO : Y

ASSY. NO.: ----- 51795  
CARD NAME: ----- MACRO DISCRETE CMD GEN #1  
SERIAL NO.: ----- 102  
DATE & TIME: ----- 13 NOV '81 10:07  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- LIFE CYCLE TESTING AT AMBIENT (PRI)

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

PRINT VERIFICATION ERRORS, YES OR NO : Y

CURRENT CYCLE COUNT IS : 0001007910

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 15 NOV '81 8:56  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J BANACH  
OTHER TEST  
CONDITIONS: ----- LIFE CYCLE TESTING AT AMBIENT (PRI)

F 1781

ORIGINAL PAGE IS  
OF POOR QUALITY  
SANTA BARBARA RESEARCH CENTER  
*A Subsidiary of Hughes Aircraft Company*  
INTERNAL MEMORANDUM

TO: L. O'Connell  
CC: Distribution  
SUBJECT: Failure Report, F1781 (Macrodiscrete  
Command Generator Board No. 1, Flt)

DATE: December 8, 1981  
REF: HS236-7762  
RE/AH 81/66  
FROM: A. Huber

BLDG. B11 MAIL STA. 102  
EXT. 6246

FR: F1781, dated 5/8/80

The failure was encountered during board test of the macrodiscrete command generator No. 1 board (assy. No. 51795), with the board heat sink plate mounted to the board. It was found that three outputs (pins 2, 6, and 10) of flatpack U35 (54L04) were shorted together. The short-circuit was not visible on the top, component-side of the board; x-ray photographs of the board revealed the short-circuit to exist on the bottom-side, and to consist of an extraneous interconnecting trace. The heat sink was removed to accomplish the repair. After the repair was made the board functioned properly. It is believed that no overstress occurred and that replacement of U35 is not warranted.

The three outputs which were shorted together are designated U35B, U35C, and U35E and are shown in Figure 1. Two of the outputs (designated 'enable'; U35B and U35C) have an identical input signal and produce identical output signals; they function to strobe data into the register shown in Figure 1 upon receipt of an enable signal. The third output signal produces a reset signal to reset the register upon completion of processing. All three outputs are normally in the high-state.

When the board is tested and a macrodiscrete command is issued by the test set, an enable signal is issued, causing the outputs of U35B and U35C to go to the low-state, as shown in Figure 1, case A. Since the reset signal (U35E) is in the high state, the two enable outputs attempt to pull the reset output to the low-state. The resulting maximum stress is that of having one output shorted to signal ground. This is not a condition of overstress; the manufacturer states that one output can be shorted-circuited to signal ground indefinitely.

The test set issues enable signals (70 microseconds in duration) at 100 millisecond intervals. Approximately 40 milliseconds after the occurrence of an enable signal, a reset signal is issued. The reset signal causes the U35E output to go to the "low state", as shown in Figure 1, case B. Since the two enable outputs (U35B and U35C) are in the high-state, an attempt is made to pull the enable outputs to the low-state. The resulting theoretical maximum stress is that of having two outputs in the same flatpack, short-circuited to signal ground.

Memo to L. O'Connell  
12-8-81  
Page 2

ORIGINAL PAGE IS  
OF POOR QUALITY

F1781

The maximum short-circuit output current of a 54L04 is 15 ma. For two outputs short-circuited to signal ground the total current is 30 ma. It is believed that 30 ma (plus an additional 4.32 ma of loads from gates connected to the three outputs) is beyond the sink current capability of U35E, which has a guaranteed capability of at least 2.0 ma. However, if U35E is capable of this current, the resulting stress would not be excessive. For example, the maximum additional power increase with two outputs short-circuited (neglecting the 4.32 ma of external loads) is 150 mw ( $5v \times 30 \text{ ma}$ ). For an assumed thermal resistance of  $150^\circ \text{ C/W}$ , junction-to-ambient, the maximum increase in junction temperatures would be  $+22.5^\circ \text{C}$ , resulting in junction temperatures of  $+45.5^\circ \text{C}$  ( $+22.5^\circ \text{C}$  temperature rise above a  $+23^\circ \text{C}$  ambient). Since the part is capable of operation at  $+125^\circ \text{C}$ , the resulting stress would not have been excessive.

Andrew E. Huber  
A. Huber

Distribution: Altman, L.  
Banach, J.  
Barnett, G. C.  
Day, J. G.  
Evans, D.

RECEIVED NOV 11 1981

# HUGHES

HUGHES AIRCRAFT COMPANY

## ORIGINAL PAGE IS OF POOR QUALITY SPACE AND COMMUNICATION GROUP FAILURE REPORT

F 1783

1. PROGRAM NAME AND NUMBER HS 236 T.M.		2. GLA		3. MODEL AT		4. TIME OBSERVED 8:30A		5. DATE OBSERVED MO 5 DA 9 YR 80	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		CARD MARK DESCRIPTION NO. 1		51795		102		HAC	
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> PROGRESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMPERATURE AXIS FOR		<input type="checkbox"/> THERMAL VAC H2S AT	
14. DESCRIPTION OF FAILURE		NO CLOCK INPUT TO UB (PIN 1) & UT (PIN 1)							
15. TEST PROCEDURE		16. ORIGINATOR		17. ORG		18. DATE		19. CONTINUATION SHEET USED	
16. VERIFICATION AND FAILURE ANALYSIS		EXAMINATION OF AIRWORK REVEALS THAT BOTH UB-7 AND UT-1 ARE LOCATED DUE TO AN ERROR IN AIRWORK.							
20. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE		INSTALL JUMPER PER P.O. 9902 AND RETEST							
21. AUTHORIZATION		ORG		DATE		22. CONTINUATION SHEET USED			
23. REMOVED/RETEST ACTION TAKEN		Installed jumper and retested							
24. LIST ALL PARTS REPLACED		PART NUMBER		QTY SYN		PART LOT NO.		DATE CODE	
27. REPORT BY		ORG		DATE		28. RETESTED BY		ORG	
29. CAUSE AND CORRECTIVE ACTION		DEFECTIVE AIRWORK -							
		DOGS AND ED 9902 CORRECTS AIRWORK							
		Serial Effectivity S/H 002 & up.							
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
34. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC <input type="checkbox"/> TEST SET UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> SCREWTIGHT	
35. FAILURE TYPE		<input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION		<input checked="" type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
37. RESPONSIBLE ENGINEER		38. SPACECRAFT SYSTEM ENGR		39. CUSTOMER OR SUPPLIER		40. DATE		41. DATE	
J. L. Loring		J. L. Loring		J. L. Loring		22-61		22-61	
22-17		18-13-80		16-17-81		16-17-81		16-17-81	

ORIGINAL PAGE IS  
OF POOR QUALITY



1733

[SEPC] ENGINEERING ORDER/REVISION NOTICE				NO. 7707	
SHEET 1 OF 1					
DRAWING TITLE FIVE BAY WARD DISCRETE COMMAND NO. 1 (R128 R12)			DRAWING NUMBER 51795 (6)		
PROJECT NUMBER E-1162	ITEM DISPOSITION		CLASS CHANGE	DRAWING TYPE	
EFFECTIVITY E1065 SERNO 002 & SUEQ	REWORK <input checked="" type="checkbox"/> ITEMS CONFORM <input type="checkbox"/> NO ITEMS MADE <input type="checkbox"/> REJECT <input type="checkbox"/> USE <input type="checkbox"/> NOT APPLICABLE <input type="checkbox"/>		<input type="checkbox"/> I <input checked="" type="checkbox"/> S <input type="checkbox"/> T <input type="checkbox"/> A <input type="checkbox"/> B	AUTHORIZING ECR NUMBER TM16-3/C1	

DESCRIPTION OF CHANGE

- 1) ADDED ITEM TO LM.
- IS: RE J-W-1177/15 WIRE, INSUL, AWG 30, CL 220, TYPE M (J-W-1177).
- 2) ADDED NOTE. (21).
- IS: INSTALL WIRE ITEM 2 BETWEEN PADS OF U7-1 AND U7-7.
- 3) ADDED NOTE CALLOUT TO SHT 2 ZONE 3D AND WIRE DEPICTION.

IS:



\* NOTE AND/OR ITEM NUMBER TO BE ASSIGNED AT TIME OF INCORPORATION.

PREPARED BY T. J. HILL	DATE 20-5-8	QUALITY APPROVAL [Signature]	DATE 20-5-8	RELEASED BY [Signature]	DATE 20-5-8
CHECKED BY S. J. HILL	DATE 20-5-8	MANUFACTURING APPROVAL	DATE	INCORPORATED BY	DATE
SEA/SEA APPROVAL [Signature]	DATE 20-5-8	PROJECT APPROVAL [Signature]	DATE 20-5-8	DRAWING REV LETTER	

1783

1. ORIGINATOR NAME AND ADDRESS <b>HUGHES AIRCRAFT COMPANY (SBRC)</b>				2. <input checked="" type="checkbox"/> DEVIATION <input type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE <b>PF5F</b>	7. MFR. CODE <b>11323</b>	8. SYS. DESIG. <b>TM</b>	9. DEV/WAIVER NO. <b>D065</b>	10. OTHER SYSTEMS/CONFIGURATION ITEMS AFFECTED	
				11. YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
12. SPECIFICATIONS AFFECTED-TEST PLAN				13. DRAWINGS AFFECTED	
14. MFR. CODE <b>11323</b>				15. NUMBER <b>51795</b>	
16. SYSTEM				17. REV. <b>B</b>	
18. ITEM				19. NOR. NO. <b>EO 8976, 9302, 9578, 9669, 9822, 9902, 1422A</b>	
20. TEST PLAN					
21. TITLE OF DEVIATION/WAIVER <b>ALTERNATE WIRING</b>				22. CONTRACT NO. & LINE ITEM <b>NAS 5-24200</b>	
23. CONFIGURATION ITEM NOMENCLATURE <b>ELECTRONICS MODULE ASSEMBLY</b>				24. CLASSIFICATION OF DEFECT	
25. NAME OF PART OR LATEST ASSEMBLY AFFECTED <b>MACRO DISCRETE COMMAND NO. 1.</b>				26. DEFECT NO. <b>II</b>	
27. PART NO. OR TYPE DESIGN <b>51795</b>				28. DEFECT CLASSIFICATION <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
29. EFFECT ON COST/PRICE				30. LOT NO. <b>-4-</b>	
31. EFFECT ON DELIVERY SCHEDULE <b>5 Months schedule impact if disapproved.</b>				32. RECORDING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
33. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC.					

23. DESCRIPTION OF DEVIATION/WAIVER

Alternate wiring (artwork error - trace omitted on A/W) incorporated on assembly drawing to accommodate circuit design changes. See 51795 assembly drawing and referenced SP80165 alternate wiring process. specification attached. See also EO 9902.

ORIGINAL PAGE IS  
OF POOR QUALITY

24. NEED FOR DEVIATION/WAIVER

Redesign and re-procurement of electronic circuit boards would be required in order to eliminate alternate wiring. Minimum 5 months schedule slip and considerable cost would be involved. Redesign is not considered cost effective at this time.

25. PRODUCTION EFFECTIVITY BY SERIAL NUMBER <b>S/Ns 101, 102, 201, 202</b>		RE <i>[Signature]</i> SYS ENGR <i>[Signature]</i> PE <i>[Signature]</i>	
26. SUBMITTING ACTIVITY AUTHORIZING SIGNATURE <i>[Signature]</i> <b>3/19/80</b>		TITLE <b>Minor - System Engineering Major/Critical - Program Manager</b>	
27. APPROVAL/DISAPPROVAL			
28. <input type="checkbox"/> APPROVAL RECOMMENDED		29. <input checked="" type="checkbox"/> APPROVED <input type="checkbox"/> DISAPPROVED	
30. GOVERNMENT ACTIVITY <b>NASA GSFC</b>		31. SIGNATURE <i>[Signature]</i> <b>2/10/80</b>	

DD FORM 1694



ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
FAILURE REPORT

F 2722

1. PROGRAM NAME AND NUMBER <i>TM PL 1162</i>		2. CLA <i>V411</i>	3. MODEL <i>RF11</i>	4. TIME OBSERVED <i>8:10</i>	5. DATE OBSERVED <i>12/23/81</i>	6. NO <i>23</i>	7. DA <i>71</i>
8. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM							
EQUIPMENT IDENTIFICATION:							
7. SUBSYSTEM		NAME		PART NUMBER		SYN	
8. UNIT							
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY							
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<i>Calibration Shutter Main</i>		<i>50916</i>		<i>201 SBR C</i>	
11. OTHER							
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> PRODUCTION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT <input type="checkbox"/> OTHER <input type="checkbox"/> ESC/CRP <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN <input type="checkbox"/> TYPE							
14. DESCRIPTION OF FAILURE <i>Observed improper waveform during Test 16238 Para 3.3.4</i> <i>Upon visual inspection found trace cut between AR4-3 and R48</i>							
15. TEST PROCEDURE <i>16238</i>		PARA <i>3.3.4</i>		16. ORIGINATOR <i>Floyd Evans</i>		17. CONTINUATION SHEET USED <i>12213 12/23/81</i>	
18. VERIFICATION AND FAILURE ANALYSIS <i>Repair CUT Trace, Trace cut in Error during manufacturing. No overstress, Signal is a input</i>							
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE <i>Repair CUT Trace. Retest per 16238 3.3.4.</i>							
20. AUTHORIZATION <i>F. Evans</i>		ORG <i>12213</i>		DATE <i>12/23/81</i>		21. CONTINUATION SHEET USED <i>12213 12/23/81</i>	
22. REWORK/RETEST ACTION TAKEN <i>Installed Jumper Wire on CUT Trace</i> <i>Retested Per TP 16238 Para 3.3.4</i>							
23. LIST ALL PARTS REPLACED							
PART NUMBER		CCT SYM		PART LOT NO.		DATE CODE	
MPN		PROBABLE DEFECT		ANALYSIS NO.			
27. REWORK BY <i>M. Davis</i>		DATE <i>12-74</i>		28. RETESTED BY <i>F. Evans</i>		DATE <i>1/10/82</i>	
29. CAUSE AND CORRECTIVE ACTION <i>OPERATOR ERROR CAUSED CUT AT WRONG TRACE DURING REWORK PER EQ9425. OPERATOR AND SUPERVISOR CAUTIONED. RPN Common 1/8/82</i>							
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION							
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST PROC. <input type="checkbox"/> ASBY/PAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT							
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> INDUCED <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY					
37. RESPONSIBLE ENGINEER <i>J. G. Brown</i>		ORG <i>22-13</i>		DATE <i>1/27/82</i>		38. SPACECRAFT SYSTEM ENGR <i>J. G. Brown</i>	
39. RELIABILITY		ORG <i>22-13</i>		DATE <i>1/27/82</i>		40. CUSTOMER OR SUPPLIER <i>J. G. Brown</i>	

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP

**FAILURE REPORT**

**F 2723**

1. PROGRAM NAME AND NUMBER <b>TM PL1162</b>		2. GLA <b>V411</b>		3. MODEL <b>FL1</b>		4. TIME OBSERVED <b>8:30</b>		5. DATE OBSERVED <b>12-23-81</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> INCAM <input type="checkbox"/> PART							
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		SN		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> INCAM <input checked="" type="checkbox"/> CARD		<b>Calibration Shutter Unit</b>		<b>50916</b>		<b>201</b>		<b>SBRC</b>	
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input type="checkbox"/> INFPROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMPERATURE <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS. AT		<input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> M/N <input type="checkbox"/> TYPE <input type="checkbox"/> OTHER							
14. DESCRIPTION OF FAILURE <b>Observed improper current peak amplitude,</b>									
15. TEST PROCEDURE <b>16238</b>		PARA <b>3.3.8</b>		16. ORIGINATOR <b>K. G. G. G.</b>		CRG <b>2213</b>		DATE <b>12/23/81</b>	
17. VERIFICATION AND FAILURE ANALYSIS <b>Incorrect Values For Resistors R119 &amp; R109 are 5.1K should be 5.1KΩ</b>									
18. FOLLOWING REWORK/RETEST REQUIRED <b>Remove &amp; Replace R119 &amp; R109 Per Assembly drawing 50916</b>									
19. REWORK/RETEST ACTION TAKEN <b>Replace due to overstress Q12 &amp; Q14, Replace due to possible overstress Q13, Q15, Q18, Q21, Q11</b>									
20. LIST ALL PARTS REPLACED									
PART NUMBER		CKT SYM		PART LOT NO.		DATE CODE		ANALYSIS NO.	
<b>908006-3</b>		<b>Q11,13,15,17</b>							
<b>708309-1</b>		<b>Q21,12,14</b>							
21. REWORK BY <b>H. S. S. S.</b>									
22. RETESTED BY <b>K. G. G. G.</b>									
23. CAUSE AND CORRECTIVE ACTION <b>REFER TO IDC # PE 15:82 FROM L. O'CONNELL TO O. I. N. N. N. (COPY ATTACHED)</b>									
24. BASIC CAUSE OF FAILURE <b>EO1327A WAS NOT INCORPORATED INTO AHR</b>									
25. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>2/F/82 CLOSER REVIEW OF AHR REQD.</b>									
26. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
27. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
28. RESPONSIBLE ENGINEER <b>M. B. B. B.</b>									
29. RELIABILITY <b>157-41</b>									
30. SPACECRAFT SYSTEM ENGINEER <b>L. G. G. G.</b>									
31. CUSTOMER OR SUPPLIER <b>SBRC</b>									

ORIGINAL PAGE IS  
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER  
*A Subsidiary of Hughes Aircraft Company*  
INTERNAL MEMORANDUM

TO: O.I. Nakano

CC: D. Adams  
L. Altman

DATE: 1 February 1982

REF: PE 15:82

SUBJECT: Failure Reports F2723,  
F2724 and S8051


FROM: L. O'Connell  
51-41

BLDG. B-11 MAIL STA. 39  
EXT. 6357

This is to confirm our Tel-Con of February 1, 1982 regarding subject Failure Reports.

As I stated to you all three Failure Reports were written against the same printed wiring board (P/N 50916, S/N 201). The cause of the test failures in each case was the installation of an incorrect resistor.

Contract quantities of subject boards have been completed. However, to help you preclude reoccurrence of this type of discrepancy on future orders or current production, copies of subject Failure Reports are attached so you can discuss the problem with Responsible Manufacturing Supervision.



L. O'Connell, Manager  
Administration and Reliability  
Thematic Mapper Program

LO:jc

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
**FAILURE REPORT**

**F 2724**

1. PROGRAM NAME AND NUMBER <b>TM PL1162</b>		2. GLA <b>V411</b>		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>2:30</b>		5. DATE OBSERVED <b>1 MO/3 ON 8/2</b>			
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:											
7. SUBSYSTEM				NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT											
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY											
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD				<b>Cal. Shutter Main</b>		<b>50916</b>		<b>201</b>		<b>SBRC</b>	
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED				<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED				<input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION		<input type="checkbox"/> TEMPERATURE		<input type="checkbox"/> THERMAL VAC		<input type="checkbox"/> MRS. AT	
				<input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION		AXIS FOR		MIS		TYPE	
14. DESCRIPTION OF FAILURE				<b>Phase offset unable to Adj. properly. Visual inspection showed R24 to be wrong Value is 30K should be 10K</b>							
15. TEST PROCEDURES <b>16238</b>				PARA <b>3.4.2.2</b>		16. ORIGINATOR <b>L Crane</b>		ORG <b>2213</b>		DATE <b>1/13/82</b>	
17. VERIFICATION AND FAILURE ANALYSIS				<b>No Stress To Components. Rework To print. (Install 10K for R24)</b>							
18. FAILED ITEM NAME AND PART NUMBER											
19. FOLLOWING REWORK/RETEST REQUIRED REWORK/RETEST NOT REQUIRED BECAUSE				<b>Remove and replace R24 per Assembly drawing- 50916</b>							
				<b>Retest per TP16238 PARA 3.4.2.2</b>							
20. AUTHORIZATION				<b>L Crane</b>		ORG <b>2213</b>		DATE <b>1/13/82</b>		CONTINUATION SHEET USED	
21. Rework/Retest Action Taken				<b>R24 removed and replaced. Replaced with proper R24</b>							
				<b>Retested per TP16238 Para 3.4.2.2.</b>							
22. LIST ALL PARTS REPLACED											
PART NUMBER				CKT SYM		PART LOT NO.		DATE CODE		MFR	
				<b>R24</b>							
23. Rework/Retest Action				BY <b>M. Davis</b>		ORG <b>22-741</b>		DATE <b>1-13-82</b>		24. RETESTED BY <b>L Crane</b>	
										ORG <b>2213</b> DATE <b>1/13/82</b>	
25. CAUSE AND CORRECTIVE ACTION				<b>REFER TO ITC # PE 15122 FROM L-01EON-61C - To OTC. N/A. (COPY ATTACHED) - 1/14-61 3-16-82</b>							
26. P/B CLOSURE				<b>OPERATOR AND QA ERROR. R24 SHOULD HAVE BEEN CHANGED PER ATR SUP'L NO 4. 2/2/82</b>							
27. DOCUMENT IMPLEMENTING CORRECTIVE ACTION				<b>ITC # PE 15122 (COPY ATTACHED)</b>							
28. BASIC CAUSE OF VERIFIED FAILURE				<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIP <input type="checkbox"/> TEST PROC <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASST/PAS ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
29. FAILURE TYPE				<input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		30. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
31. RESPONSIBLE ENGINEER				<b>L Crane</b>		ORG <b>22-13</b>		DATE <b>1/12/82</b>		32. SPACECRAFT SYSTEM ENGR <b>L Crane</b>	
33. RELIABILITY				<b>51-41</b>		ORG <b>22-13</b>		DATE <b>1/12/82</b>		34. CUSTOMER OR SUPPLIER <b>SBRC</b>	

SANTA BARBARA RESEARCH CENTER  
A Subsidiary of Hughes Aircraft Company  
INTERNAL MEMORANDUM

TO: O.I. Nakano

CC: D. Adams  
L. Altman

DATE: 1 February 1982

REF: PE 15:82

SUBJECT: Failure Reports F2723,  
F2724 and S8051

FROM: L. O'Connell  
51-41

BLDG. B-11 MAIL STA.  
EXT. 6357

This is to confirm our Tel-Con of February 1, 1982 regarding subject Failure Reports.

As I stated to you all three Failure Reports were written against the same printed wiring board (P/N 50916, S/N 201). The cause of the test failures in each case was the installation of an incorrect resistor.

Contract quantities of subject boards have been completed. However, to help you preclude reoccurrence of this type of discrepancy on future orders or current production, copies of subject Failure Reports are attached so you can discuss the problem with Responsible Manufacturing Supervision.



L. O'Connell, Manager  
Administration and Reliability  
Thematic Mapper Program

LO:jc

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
FAILURE REPORTORIGINAL PAGE IS  
OF POOR QUALITY**S** 8049

1. PROGRAM NAME AND NUMBER <b>TM PL 1162</b>		2. GLA <b>V411</b>	3. MODEL <b>F1</b>	4. TIME OBSERVED <b>7:37</b>	5. DATE OBSERVED MO <b>11</b> DA <b>6</b> YR <b>81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<b>SLC PWB ASSY</b>		<b>52250-1</b>	<b>201</b>
11. OTHER					<b>SBAC</b>
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP AXIS FOR MIN TYPE <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>Observed improper waveform during test. Upon examination of test set up found scope ground shorting to K3 pin 4</b>					
15. TEST PROCEDURE <b>16520</b>		16. PARA <b>4.2.2.6</b>	18. ORIGINATOR <b>L Evans</b>	ORG <b>22-13</b>	DATE <b>11/6/81</b>
17. CONTINUATION <input type="checkbox"/> SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS <b>K3 Should Be Replaced, <del>REMOVED AND REPLACED</del> CARD MOTORED OK (mm) U2 To Be Replaced Due To possible overstress</b>					
19. FAILED ITEM NAME AND PART NUMBER <b>R14 (6.49m, 2w, 170, <del>REMOVED</del> RD) TO BE REPLACED DUE TO POSSIBLE OVERSTRESS</b>					
20. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Remove and replace</b>					
<b>U1, U2, K3, R14</b>					
<b>Retest per TP 16520 Para 4.5.1</b>					
21. AUTHORIZATION <b>A Bonach</b>		ORG <b>22-13</b>	DATE <b>11/6/81</b>	22. CONTINUATION <input type="checkbox"/> SHEET USED	
23. REWORK/RETEST ACTION TAKEN <b>Removed and replaced U1, U2, K3, R14</b>		Retested to Test Procedure 16520 Para 4.5.1		24. QA REVIEW <b>110</b>	
25. LIST ALL PARTS REPLACED		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
<b>K3, 908311-5</b>			<b>7326K 33</b>	<b>752303</b>	<b>AME PITT</b>
<b>U2, 909955-1</b>					<b>AME PITT</b>
<b>R14</b>					<b>AME PITT</b>
27. REWORK BY <b>M. Guerra</b>		ORG <b>22-74</b>	DATE <b>11/17/81</b>	28. RETESTED BY <b>L. Evans</b>	ORG <b>22-13</b>
29. CAUSE AND CORRECTIVE ACTION <b>Incorrect test setup.</b>		DATE <b>11/17/81</b>		29. CONTINUATION <input type="checkbox"/> SHEET USED	
Carefully insure test set up prior to initiation of test.				30. FRB CLOSURE	
TECHNICIAN'S WERE CAUTIONED TO CHECK TEST-SET UP PRIOR TO TEST.				31. CONTINUATION <input type="checkbox"/> SHEET USED	
NO OTHER COMPONENTS OTHER THAN THE FOUR WERE FOUND TO BE OVERSTRESSED.				32. CONTINUATION <input type="checkbox"/> SHEET USED	
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>HS236-7718 (COPY ATTACHED)</b>					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input checked="" type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		37. RESPONSIBLE ENGINEER <b>A Bonach</b>	
38. SPACECRAFT SYSTEM ENGINEER <b>R. E.</b>		39. DATE <b>11/17/81</b>		40. DATE <b>11/17/81</b>	
41. DATE <b>11/18/81</b>		42. DATE <b>11/18/81</b>		43. DATE <b>11/17/81</b>	

ORIGINAL PAGE IS  
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER  
A Subsidiary of Hughes Aircraft Company  
INTERNAL MEMORANDUM

5 8049

TO: L. O'Connell	CC: Altman, L. Banach, J.A. Barnett, G.C. Day, J.G. Evans, L.B. Wolthausen, L.H. Data Bank	DATE: 12 November 1981 REF: HS236-7718 REAH 81/59 FROM: A. Huber BLDG. B-11 MAIL STA. 102 EXT. 6246
SUBJECT: FR: S8049 (Scan Line Corrector Board, Flight)		

FR: S8049, dated November 6, 1981

The failure occurred when performing optical/electrical calibration of the scan line corrector subassembly, with the scan line corrector board (assy. no. 52250-1, S/N 201) mounted in the SLC test box and receiving +19V power (actually +21V) from a power supply within the test box. At the time of the failure two (2) oscilloscope probes were attached to test points at the top of the board and signals were being monitored on the oscilloscope display. The SLC motor and mirrors were in operation. With the occurrence of the failure the display went blank and SLC motor/mirror operation ceased. It was estimated that test equipment power was turned OFF within 15 seconds of the occurrence of the failure.

Investigation of the scan line corrector board found the ground lead of an oscilloscope probe in contact with the +19V on the SLC board, shorting the test equipment +19V power supply to signal ground and causing the +19V fuse (3 amp) to open. Figure 1 illustrates the point at which the short occurred (pin 4 of relay K3). Measurement of the resistances from (through) the SLC connector pins, to the input of relay K3, indicated nearly identical resistances for the '+19V' and '-19V' lines (0.061 ohms, connector pin 22 to relay pin 3; 0.058 ohms, connector pin 23 to relay pin 2). Measurement of the contact resistances of K3 indicated 0.013 ohms (pin 3 to pin 4) versus 0.010 ohms (pin 2 to pin 5). Subsequent testing of the board after the fuse was replaced (and before any components were replaced) revealed no change in board performance as a result of the failure.

Four components were eventually replaced: (1), relay K3; (2), voltage regulator U2; (3), voltage regulator U1; and (4), resistor R14 (6.49 ohms, 2w, 1%), appearing on motor driver assembly 54018, part of SLC board assembly 52250.

Relay K3 was replaced because of the possibility that the short circuit surge current from the 27,000  $\mu$ fd power supply capacitor caused some degradation of the relay contacts.

Voltage regulator U2 (LM125) was replaced because of a possible overstress of Q12 within U2. This component, Q12, has a capability of approximately 30ma to 40ma (National Semiconductor, Tim Reagan, 408-737-5000 x 3887) and may have experienced a surge of 450 ma, depending upon the position of the SLC motor at the time of the failure. A second reason for replacement of this part was the possibility of excessive input voltage (greater than 30V) due to an inductive transient from the short circuit surge current. This latter possibility was also the reason for replacing the other LM125 voltage regulator, U1.

The resistor R14 (6.49 ohm, 1%) was replaced because in the presence of a short circuited +19V, the SLC motor driver produces a steady-state output as shown

FR:S8094  
A. Huber, to L. O'Connell

HS 236-7718  
Page 2

58049

in Figure 2, resulting in a power dissipation of 2.5w for R14. This component has a manufacturer's rating of 2w.

All other components of the SLC board were analyzed for possible overstress. No other components (other than the four that were replaced) were found to have been possibly overstressed.

Andrew E. Huber  
A. Huber

AH:jc

ORIGINAL PAGE IS  
OF POOR QUALITY






FIGURE 1. SLC  $\pm 19V$  POWER INPUT CIRCUITRY, ILLUSTRATING POINT AT WHICH FAILURE OCCURRED

5 2049  
ORIGINAL PAGE IS  
OF POOR QUALITY




FIGURE 2. MOTOR DRIVER STEADY-STATE OUTPUT FOR  
+14V SHORT TO GND

C-2

# 4.5.1 Track Rate, Linearity, and Overlap/Underlap

## FINAL LINEARITY DATA

ORIGINAL PAGE IS  
OF POOR QUALITY

1. CYCLES 200

ET. NO.	1	ERROR FRACT. +	5.41				
COUNT MEAN	1128.92	COUNT MAX	1130	COUNT MIN	1128	CNT STD DEV	.2
ET. NO.	2	ERROR FRACT. +	5.93				
COUNT MEAN	1764.96	COUNT MAX	1765	COUNT MIN	1764	CNT STD DEV	.1
ET. NO.	3	ERROR FRACT. +	5.16				
COUNT MEAN	2485.04	COUNT MAX	2486	COUNT MIN	2485	CNT STD DEV	.1
ET. NO.	4	ERROR FRACT. +	4.78				
COUNT MEAN	3054.19	COUNT MAX	3055	COUNT MIN	3054	CNT STD DEV	3.9
ET. NO.	5	ERROR FRACT. +	4.38				
COUNT MEAN	3700.84	COUNT MAX	3701	COUNT MIN	3700	CNT STD DEV	.3
ET. NO.	6	ERROR FRACT. +	4.19				
COUNT MEAN	4257.99	COUNT MAX	4258	COUNT MIN	4257	CNT STD DEV	4.6
ET. NO.	7	ERROR FRACT. +	3.92				
COUNT MEAN	4882.04	COUNT MAX	4883	COUNT MIN	4882	CNT STD DEV	4.9
ET. NO.	8	ERROR FRACT. +	4.23				
COUNT MEAN	5570.99	COUNT MAX	5571	COUNT MIN	5570	CNT STD DEV	.
ET. NO.	9	ERROR FRACT. +	4.51				
COUNT MEAN	6120.06	COUNT MAX	6121	COUNT MIN	6120	CNT STD DEV	.2
ET. NO.	10	ERROR FRACT. +	5.15				
COUNT MEAN	6759.24	COUNT MAX	6760	COUNT MIN	6759	CNT STD DEV	.4

SIZE A	CODE IDENT NO 11323	NUMBER 11615
SCALE	REV A	SHEET 8

# 4.5.1 Track Rate, Linearity, and Overlap/Underlap

58049

## FINAL LINEARITY DATA

ORIGINAL PAGE IS  
OF POOR QUALITY

D. CYCLES 200

ET. NO.	1	ERROR FRACT. +	5.33				
JUNT MEAN	1128.03	COUNT MAX	1129	COUNT MIN	1128	CNT STD DEV	2
ET. NO.	2	ERROR FRACT. +	5.93				
JUNT MEAN	1765.00	COUNT MAX	1765	COUNT MIN	1765	CNT STD DEV	
ET. NO.	3	ERROR FRACT. +	5.17				
JUNT MEAN	2485.09	COUNT MAX	2486	COUNT MIN	2485	CNT STD DEV	3
ET. NO.	4	ERROR FRACT. +	4.77				
JUNT MEAN	3054.03	COUNT MAX	3055	COUNT MIN	3054	CNT STD DEV	
ET. NO.	5	ERROR FRACT. +	4.38				
JUNT MEAN	3700.84	COUNT MAX	3701	COUNT MIN	3700	CNT STD DEV	
ET. NO.	6	ERROR FRACT. +	4.29				
JUNT MEAN	4258.95	COUNT MAX	4259	COUNT MIN	4258	CNT STD DEV	
ET. NO.	7	ERROR FRACT. +	3.92				
JUNT MEAN	4882.04	COUNT MAX	4883	COUNT MIN	4882	CNT STD DEV	
ET. NO.	8	ERROR FRACT. +	4.15				
JUNT MEAN	5570.04	COUNT MAX	5571	COUNT MIN	5570	CNT STD DEV	5.
ET. NO.	9	ERROR FRACT. +	4.59				
JUNT MEAN	6120.98	COUNT MAX	6121	COUNT MIN	6120	CNT STD DEV	5.
ET. NO.	10	ERROR FRACT. +	5.22				
JUNT MEAN	6759.97	COUNT MAX	6760	COUNT MIN	6759	CNT STD DEV	

SIZE A	CODE IDENT NO 11323	NUMBER 11615
SCALE	REV A	SHEET 8

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS  
OF POOR QUALITY  
SPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY  
**S 8050**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>TM PL1162</b>		2. GLA <b>V411</b>		3. MODEL <b>P1</b>		4. TIME OBSERVED <b>3:30</b>		5. DATE OBSERVED <b>MO 11 DA 20 YR 81</b>					
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART					
	EQUIPMENT IDENTIFICATION:													
	7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER					
ENGINEERING EVALUATION	8. UNIT													
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY													
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<b>SLC PWB Assy</b>		<b>52250-2</b>		<b>201</b>		<b>SDRC</b>					
	11. OTHER													
ENGINEERING EVALUATION	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS							
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMP <b>50</b> °C AXIS FOR _____ MIN TYPE _____		<input type="checkbox"/> THERMAL VAC _____ HRS AT _____		<input type="checkbox"/> OTHER _____					
	14. DESCRIPTION OF FAILURE <b>Observed improper linearity data over temperature per spec. 16123 as per Test Procedure 16520. Para 4.3</b>													
	15. TEST PROCEDURE <b>16520</b>		PARA <b>4.3</b>		16. ORIGINATOR <b>Alfred Crane</b>		ORG <b>2213</b>		DATE <b>11/24/81</b>		17. CONTINUATION SHEET USED <input type="checkbox"/>			
ENGINEERING EVALUATION	18. VERIFICATION AND FAILURE ANALYSIS <b>Excessive leakage current (500pA @ +20°C, 100pA @ +50°C through DR18CAL (U13) switch contacts -20°C to +13.6V. FAILURE CONFIRMED (FAR 9274)</b>													
	19. FAILED ITEM NAME AND PART NUMBER <b>U13 JFET SWITCH 912922</b>													
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Remove and replace U13 (912922-1)</b> <b>Retest per TP 16520 Para 4.3</b>													
	21. AUTHORIZATION <b>Alfred Crane / JABonach</b>													
MANUFACTURING AND TEST	22. REWORK/RETEST ACTION TAKEN <b>REPLACED U13 PER AHR 52250-2, SUPPL 6 &amp; TP 16520.4.3</b>		23. CONTINUATION SHEET USED <input type="checkbox"/>											
	24. <b>REPLACED (RESELECTED) R32 TO 2.2K, 1% PER AHR 52250-2 OP. 7.150 ON QA COMMENT SHEET &amp; TP 16520, 4.2.3</b>													
	25. LIST ALL PARTS REPLACED PART NUMBER		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT		ANALYSIS NUMBER					
	<b>912922-1</b>		<b>U13</b>	<b>902495026</b>	<b>7913</b>	<b>SILICONIX</b>								
ENGINEERING/RELIABILITY	26. SN <b>G3347</b>													
	27. REWORK BY <b>M. GUERRA</b>		ORG <b>22-74</b>		DATE <b>11-30-81</b>		28. RETESTED BY <b>L. EVANS</b>		ORG <b>22-13</b>		DATE <b>12-7-81</b>		29. CONTINUATION SHEET USED <input type="checkbox"/>	
	30. CAUSE AND CORRECTIVE ACTION <b>CAUSED BY FAILURE OF P/N 912922 FET SWITCH, CONFIRMED BY FAR 9274. THIS IS CONSIDERED A RANDOM FAILURE THAT COULD HAVE BEEN CAUSED IN ASSEMBLY OF THE FET SWITCH. NO CORRECTIVE ACTION IS DEEMED NECESSARY UNLESS A REPEAT OF THIS FAILURE MECHANISM IS SEEN, AND THE RANDOM HYPOTHESIS IS DISCARDED. THIS</b>										31. FRB CLOSURE <b>3/10/82</b>			
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION										33. CONTINUATION SHEET USED <input type="checkbox"/>			
ENGINEERING/RELIABILITY	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		<input checked="" type="checkbox"/> UNKNOWN		DEFECT CODE			
	35. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR		<input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY							
	37. RESPONSIBLE ENGINEER <b>M. J. Sawicki</b>		ORG <b>22-17</b>		DATE <b>12-8-81</b>		38. SPACECRAFT SYSTEM ENGINEER <b>J. J. Evans</b>		ORG <b>22-41</b>		DATE <b>3/9/82</b>			
	39. RELIABILITY <b>C. Perlin</b>		ORG <b>5141</b>		DATE <b>03-08-82</b>		40. TESTER OR SUPPLIER <b>AA</b>							

**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

**SPACE AND COMMUNICATIONS GROUP**

**FAILURE REPORT  
CONTINUATION SHEET**

FR SERIAL NO.

2050

CONTINUATION SHEET LETTER

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

☐ IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED

30 WAS A VENDOR'S PROBLEM. HS 236-7891 ADVISER  
THE PART BOARD OF THIS PROBLEM.

ORIGINAL PAGE IS  
OF POOR QUALITY

PART NO.		PART NAME		ASSY/LOT SERIAL NO.	QTY
52250-2		PWB. Assoc. Hand Line Correction		201	1
OPER NO.	DATE	OPERATOR OR INSP	COMMENTS, TEST DATA, ETC	DISPOSITION	APPROVAL
2106	11/18/81	[Signature]	U.S. Hand wireline that are bent.	P.R. Removal to B/R & Re-engage with G. Amerson	[Signature]
	11/18/81	[Signature]	replaced washers		
2107	11/18/81	[Signature]	Clip bent left on back of small board.	P.R. Tester Removal & Return to Defect	[Signature]
	11/18/81	[Signature]	removed Clip - end		
3150	11/25/81	[Signature]	F/R 8050		
B	11-30-81		AS A RESULT OF REPLACING U13 PER FR 8050 SELECT RESISTORS R31 & R32 WILL REQUIRE RESELECTING AS FOLLOWS:		[Signature]
3101	11-30-81	22-74	1. UNSOLDER R31, TACK SOLDER 28 AWG STANDOFF WIRES TO PADS & R31 TO WIRES.		
	11-30-81	M. Elmer	2. UNSOLDER R32, TACK SOLDER 28 AWG STANDOFF WIRES TO PADS & R32 TO WIRES.		
3102	11/30/81	22-13	TEST PER 16520 REV. A PARA 4.2.2 TO RESELECT R31 & R32 ENTER ON TEST DATA SHEET		
3103	12-1-81	m. m. m. 22-72	KIT AND ENTER NEW SELECTS ON ABCTR FROM TEST DATA RECORDS		

ORIGINAL PAGE IS  
OF POOR QUALITY

5  
8050

[illegible]

ORIGINAL PAGE IS  
OF POOR QUALITY

2050



**SBRC**

**ASSEMBLY HISTORY RECORD SUPPLEMENT**

SHEET 1 OF 4

PART NUMBER 52250-2	SERIAL OR LOT NUMBER 201	DRAWING NO. 52250	DRAWING REVISION C	REQ SOURCE CODE 22-73	PREPARED BY G.W. Cannon	SUPPLEMENT NO. 6 TO AHR DATED 23 June 80
ASSEMBLY NAME PWB ASSEMBLY SCAN LINE CORRECTOR			APPROVED BY DATE	RESP. ENG. APPROVAL <i>[Signature]</i>	QUALITY APPROVAL <i>[Signature]</i>	SUPPLEMENT RELEASE DATE 25 Nov. 81
PURPOSE OF SUPPLEMENT - INCORPORATES NEW ASSY DWG (REVISION 1) OR COST 1; REWORK 1; OTHER 1; EXPLAIN.				PRODUCTION APPROVAL <i>[Signature]</i>	PROJ. ENG. APPROVAL <i>[Signature]</i>	NOTE TO PRODUCTION - UPON RECEIPT, ENTER SUPPLEMENT NO. AND RECEIPT DATE ON FRONT SHEET OF AHR. INITIAL THE ENTRY.
FR S 8050				OTHER <i>[Signature]</i>	OTHER	

NOTES: SAME AS ORIGINAL

OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY:			REMARKS
			OPER	INSP	DATE	
		REASON; Improper linearity data over tempera- ture test.				
		PURPOSE: Perform test at 0°C and 50°C for voltage verification.				
		NOTIFY QA AND AF PRIOR TO TEST				
3105	22-13	1) Perform and record the following at 50°C with 108KHZ out and TP14 at +13V measure and record the following voltages;	<i>[Signature]</i>		11/25/81	<i>[Signature]</i> 11/25/81

ORIGINAL PAGE IS  
OF POOR QUALITY

58050

**SHRC**

# ASSEMBLY HISTORY RECORD CONTINUATION SHEET

SHEET 2 OF 4

PART NUMBER 52250-2	SERIAL OR LOT NUMBER 201	ASSEMBLY NAME PWB ASSEMBLY SCAN LINE CORRECTOR	CONTINUATION OF: AHR DATED AHR SUPPLEMENT NO. 6
------------------------	-----------------------------	--	---

OPER NO.	S/C NO.	INSTRUCTIONS	PERFORMED BY			REMARKS
			OPER	INSP	DATE	
3105	Cor.	Junction of R31 and R32 - 2.7430 V	✓		11/23/61	
		Junction of R32 and R33 - 2.0276 V				
		2) Repeat with 108KHZ out and TP14 at -2V--Record.				
		Junction of R31 and R32 - 2.657 V				
		Junction of R32 and R33 - 2.0065 V				
		3) Test at 0°C with 108KHZ out and TP14 at +13V--Record.				
		Junction of R31 and R32 - 2.6575 V				
		Junction of R32 and R33 - 2.0272 V				
		4) Repeat with 108KHZ out and TP14 at -2V--Record.				
		Junction of R31 and R32 - 2.6520 V				
		Junction of R32 and R33 - 2.0075 V				
		Record change of parts as determined by above test.				
		REPLACE: 013				

ORIGINAL PAGE IS  
OF POOR QUALITY

52050

**SRRC**

# ASSEMBLY HISTORY RECORD CONTINUATION SHEET

SHEET 3 OF 4

PART NUMBER		SERIAL OR IOI NUMBER	ASSEMBLY NAME	CONTINUATION OF:			
52250-2		201	PWB ASSEMBLY SCAN LINE CORRECTOR	AHR DATED AHR SUPPLEMENT NO. 6			
OPER NO.	S/C NO.	INSTRUCTIONS		PERFORMED BY			REMARKS
				OPER	INSP	DATE	
3110	22-72	Kit and enter on ABC/TR the following:		AS		11-2-81	
		1 EA 912922-1 1C 1113 ITEM 25					
3115	51-11	Kit inspect.			(1) 117	11-2-81	
3120	22-74	Carefully remove the following part 1113, bag, bag and forward to Q.A.				11-2-81	
		1113 per B/P.				11-2-81	

ORIGINAL PAGE IS  
OF POOR QUALITY

518050



ORIGINAL PAGE IS  
OF POOR QUALITY

**SBRC**

# REQUEST FOR SHIPMENT

0249

THIS REQUEST MUST BE FILLED OUT COMPLETELY IN ACCORDANCE WITH THE INSTRUCTIONS ON THE REVERSE SIDE HEREOF  
SHIPPING CANNOT PROCESS INCOMPLETE REQUESTS

DATE: 12-21-81

P TO:

Hughes  
El Segundo  
Space Communications Div  
Bldg S-41 Rm 1103C  
1650 E Imperial Hwy  
El Segundo, CA 90245

RK FOR:  
A NO.:

• SHIPMENT REQUIRED AT DESTINATION BY: 12-23-81

• THIS SHIPMENT IS AGAINST REQUIREMENTS OF:

W.A. NO. ACCT. NO.: V410-64-03  
GOV'T CONT NO.: NAS 5-24600  
CUSTOMER P.O.: 59011  
SBRC P.O. I.P.A.: 59011

• SHIPMENT TO BE: PREPAID ☐ COLLECT ☐

## SHIPMENT CLASSIFICATION

CONTRACT OR P.O. SHIPMENT IS:

PARTIAL ☐

FINAL ☒

HAZARDOUS MAT'L ☐

NON-HAZARDOUS ☒

• SECURITY CLASSIFICATION:

UNCLASSIFIED ☒

CONFIDENTIAL ☐

SECRET ☐

REF SEC'Y PRACTICES  
NOS 11-2-1, 11-2-14

• PROPERTY OWNERSHIP:

COMPANY ☒

IDENTIFIED ☐

GOVERNMENT ☐

DD 1149 ☐

CUSTOMER OR SUPPLIER ☐

• TYPE OF SHIPMENT:

RTV ☐

OUTSIDE PROCE ☐

SALE ☐

MISCELLANEOUS ☐

P.O. PA  
CONTR  
SER NO.

QUANTITY

THIS  
SHIPMENT

UNIT

ON  
ORD

BACK  
ORD'S

SBRC P/N

ITEM(S) DESCRIPTION

DC  
V.

1

EA

90994-1

Shift Register

1

EA

912922-1

I.C.

50

To be shipped for Failure Analysis

SPECIAL SHIPPING, MARKING INSTRUCTIONS: Please place on SBRC Shuttle

SHIPMENT REQUESTED BY:

DATE:

APPROVED BY:

Jensler Bldg Rm m/c24 12/21/81

0

ORIGINAL PAGE IS  
-OF POOR QUALITY

# FAILURE ANALYSIS REPORT

**HUGHES**

HUGHES AIRCRAFT COMPANY  
TECHNOLOGY SUPPORT  
DIVISION

FAR No. 9274  
Program: Thematic Map  
Page 1 of 7

DATE OF RECEIPT <u>1-11-82</u>	TSD PROJECT ENGINEER <u>W. Gettys</u>
REQUESTER <u>H. Persh/F. Carle</u>	PHONE <u>6458194</u> BLDG./MS <u>STD/C340</u>
ORG <u>44-07</u> PHONE <u>6488388</u> BLDG./MS <u>S41/B355</u>	GLA/CMAER <u>40930 (F263A2151)</u>
REA <u>Lionel Altman</u> PHONE _____	
COMPONENT <u>I.C. (1)</u>	FAILURE REFERENCE <u>FR S8050/FA82-006</u>
FUNCTION/TYPE <u>FET Switch</u>	DATE OF FAILURE <u>11-20-81</u>
GENERIC P/N <u>DG185AL</u>	FAILURE LEVEL <u>Card</u>
HUGHES P/N <u>912922</u>	LOT NUMBER <u>9C249-5026</u>
MFG. <u>Siliconix</u> P/N <u>S08531</u>	CIRCUIT SYMBOL <u>U13</u>
DATE CODE <u>7913</u> S/N <u>G3347</u>	MODULE <u>52250-2</u> S/N <u>201</u>

## ABSTRACT

The reported failure, high "off" state leakage, was confirmed. Internal examination revealed a crack across the die which contained the driving circuitry for the defective output switch. It is believed that the leakage was due to this crack. This failure is judged to have been primary.

TECHNICAL  
COMMENTARY

☐ NOT REQUIRED

☒ APPENDED

*C. A. Edelman*  
C. A. Edelman

FAILURE ANALYST

L1153-121

JOURNAL

*P. G. Backes*  
P. G. Backes

APPROVAL

DATE

2/15/82

52050

Reported Failure:

High "off" state leakage of 5uA @ 20°C, increasing to 10uA @ 50°C on pins 1 and 2 only.

Background Information:

The above failure was observed while testing per procedure 16520 para. 4.3. The subject device, which was U13 on the SLC PWB, assembly 52250-2 S/N 201, was replaced. No additional testing of the device was performed prior to its submittal for failure analysis.

Outline of Analysis:

1. External Visual Examination
2. Electrical Tests
3. Hermeticity Testing
4. Particle Impact Noise Detection (PIND) Testing
5. Internal Examination
6. Electrical Probing

Results of Analysis:

1. External Visual Examination.

- a) Markings: G3347 (on attached label)  
SDG8531  
(Siliconix logo) 7913

b) Case Examination:

The leads were crimped, slightly bent and solder coated. There was adhesive tape on the bottom surface. No other obvious visual physical anomalies were noted.

2. Electrical Testing.

a) Curve Tracer Measurements:

Current-voltage characteristics were obtained for each pin to V+ (pin 6) and to V- (pin 9), in both polarities. Pins 1 and 2 were degraded to both V+ and V- as compared to other JFET output pins. No other obvious defects were indicated. See Figures 1 and 2 for pin connection and schematic diagrams.

b) Functional and Parametric Tests:

The device was functionally tested with V+ = 15V, V- = -15V, VL = 5V, VR = 0V, VIL = 0.8V and VIH = 2.0V. With no current flow across the JFET, source and drain voltages were measured. All outputs remained at 0V regardless of the input state except pins 1 and 2 (S4 and D4), which floated at -14.72V to -14.77V for input states 0 and 1, respectively.

The device was tested per 912922 for rDS(on), IS(off), IIN, I+, I-, IL and IR. All data were within the specified limits except IS(off) of pin 1 (gate 4), which was 33.4uA but should be 1.0nA maximum. The data are summarized as follows:

(continued)



5-2050

Results of Analysis: (continued)

2. Electrical Testing. (continued)

b) Functional and Parametric Tests: (continued)

PARAMETER	GATE 1	GATE 2	GATE 3	GATE 4	LIMIT
$r_{DS(on)}$	34.5 $\Omega$	34.0 $\Omega$	30.9 $\Omega$	30.6 $\Omega$	75 $\Omega$ max.
$I_{S(off)1}$	0.109nA	0.133nA	0.079nA	*33.4 $\mu$ A	1.0nA max
$I_{D(off)1}$	0.051nA	0.070nA	0.035nA	0.030nA	1.0nA max
$I_{INL}$	-13.3 $\mu$ A				-250 $\mu$ A max
$I_{INH}$	0.152nA				10nA max
$I^+_1$	8.9nA				0.1mA max
$I^-_1$	1.68mA				-4.0mA max
$I_{L1}$	2.57mA				4.5mA max
$I_{R1}$	-0.88mA				-2.0mA max
$I^+_2$	0.86mA				3.0mA max
$I^-_2$	-2.54mA				-5.5mA max
$I_{L2}$	2.54mA				4.5mA max
$I_{R2}$	-0.85mA				-2.0mA max

\* Out of tolerance.

c) Baking and Additional Testing.

The device was baked for 2 hours at +150°C and retested for  $I_{S(off)1}$ .  
 $I_{S(off)1}$  of gate 4 was 38.1 $\mu$ A compared to 33.4 $\mu$ A before baking.  
The other gates did not change significantly in  $I_{S(off)1}$ .

3. Hermeticity Testing.

The device passed the fine leak test and the gross leak characterization.

4. Particle Impact Noise Detection (PIND) Testing.

No indications of loose internal particles were noted during PIND testing.

5. Internal Examination.

Internal examination revealed a crack in the die containing the driver circuitry. The crack extended across the source and channel regions of MOSFET Q5 and terminated at the scribe surface. The crack also passed under the metallization leading from the source of Q5 to the output JFET, Q6. The above mentioned defects pertain only to gate 4. (See Figures 3 through 5.)

6. Electrical Probing.

The JFET between pins 1 and 2 was isolated from the driver chip by lifting the source and gate leads. The JFET was then tested for source-gate and drain-gate characteristics and was not found to be degraded.

ORIGINAL PAGE IS  
OF POOR QUALITY

FAR. NO. 9274  
PAGE 4 of 7

52050

Conclusions:

The reported failure, high "off" state leakage, was confirmed. Excessive leakage current ( $I_{S(off)}$ ) was observed through pins 1 and 2 at ambient temperature. Pins 1 and 2 were also observed to float near  $V_-$  while the other switch outputs were at ground. No other electrical defects were indicated. Baking did not elicit significant change in  $I_{S(off)}$  of pins 1 and 2. Internal examination revealed a crack across the die containing the driving circuitry. This crack passed through the MOSFET leading to the source and gate of the JFET switch across pins 1 and 2. It is believed that the high leakage was due to the crack since the JFET switch was not found to be defective. This failure is judged to have been primary.

58050

Pin Number	Designation
1	S4
2	D4
3	D2
4	S2
5	IN 2
6	V <sup>+</sup>
7	V <sub>L</sub>
8	V <sub>R</sub>
9	V <sup>-</sup>
10	IN 1
11	S1
12	D1
13	D3
14	S3

ORIGINAL PAGE IS  
OF POOR QUALITY

Figure No. 1

Pin connection table for the  
912922.





Figure No. 2

Schematic diagram  
for a typical input  
channel with two  
DPST JFET switches

ORIGINAL PAGE IS  
OF POOR QUALITY

58050



## ENGINEERING TECHNICAL COMMENTARY

Approved to FAR 9274  
Page 1 of 1

### COMMENTARY

The device was tested and found to have failed the reported failed parameter, IS(off). The spec limit was 1.0nA max. and the device measured 33.4 A. This high leakage was probably due to the crack discovered in the die during the internal visual examination. The crack was probably caused by poor handling techniques during assembly.

### RECOMMENDATIONS:

Device is considered a random failure. If other devices from this lot are available, a few devices should be temperature cycled to determine if other devices may have this same sort of defect.

John V. Varrille  
ENGINEER

[Signature]  
ENGINEERING APPROVAL

2/20/92  
DATE

ORIGINAL PAGE IS  
OF POOR QUALITY

58050  
FAR. NO. 9274  
PAGE 6 of 7




Figure No. 3

Photomicrograph of the cavity  
showing the driver circuitry  
(center die) and the four  
JFET switches on separate  
substrates.

(13.7X)




Figure No. 4

Overall view of the center die  
showing the location of the  
crack shown in Figure 5 (be-  
tween arrows).

(45.2X)

5'2050

ORIGINAL PAGE IS  
OF POOR QUALITY




Figure No. 5. Detailed view of the crack across MOSFET Q5 of the driver circuitry. Note that the crack extends to the scribe surface at the edge of the die (between arrows). (182X)

ORIGINAL PAGE IS  
OF POOR QUALITY

SANTA BARBARA RESEARCH CENTER  
*A Subsidiary of Hughes Aircraft Company*  
INTERNAL MEMORANDUM

5' 2050

TO: Frank Carle  
Parts Board

CC: See Distribution List

DATE: 15 March 1982

REF: RS 236-7891

PE 55:82

FROM: L. O'Connell

SUBJECT: Failure of P/N 912922

BLDG. B-11 MAIL STA. 39  
EXT. 6357

1. On 20 November 1981 a failure was observed in the TM Scan Line Corrector. This failure was repaired by the replacement of P/N 912922.
2. TSD FAR 9274 declares that the failure may be due to possible mishandling during the manufacturing process.
3. This unit was procured from Siliconix. Please take any necessary action to advise the manufacturer and to preclude the repetition of this type of failure.



L. O'Connell, Manager  
Administration and Reliability  
Thematic Mapper Program

LOC:jc

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8051**

1. PROGRAM NAME AND NUMBER <i>TM PL 1162</i>		2. GLA <i>V411</i>		3. MODEL <i>FLT</i>		4. TIME OBSERVED <i>4:22</i>		5. DATE OBSERVED MO / DA / YR <i>82</i>							
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART							
EQUIPMENT IDENTIFICATION:															
7. SUBSYSTEM				NAME		PART NUMBER		S/N		MANUFACTURER					
8. UNIT															
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY															
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD				<i>Cal Shutter Main</i>		<i>50916</i>		<i>201</i>		<i>SARC</i>					
11. OTHER															
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS															
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER															
14. DESCRIPTION OF FAILURE <i>Phase Ramp unable to Adjust correctly. Found R87 incorrect Value. Should be 169K<math>\Omega</math> is 442K<math>\Omega</math>.</i>															
15. TEST PROCEDURE <i>16238</i>										16. ORIGINATOR <i>LCRama</i>		17. CONTINUATION <input type="checkbox"/> SHEET USED			
18. VERIFICATION AND FAILURE ANALYSIS <i>R87 incorrect Value Should be 169K<math>\Omega</math> is 442K<math>\Omega</math> No Stress To Components</i>										19. FAILED ITEM NAME AND PART NUMBER					
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>Replace R87 per Assembly drawing 50916 Retest per T.P. 16238 3.3.7</i>										21. AUTHORIZATION <i>LCRama</i>		22. CONTINUATION <input type="checkbox"/> SHEET USED			
23. REWORK/RETEST ACTION TAKEN <i>R87 Removed and Replaced</i>										24. QA REVIEW <i>107</i>		25. OR REWORK <i>107</i>			
26. LIST ALL PARTS REPLACED										27. CONTINUATION <input type="checkbox"/> SHEET USED					
PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUMBER			
<i>R87</i>															
27. REWORK BY <i>P. Dralier</i>										28. TESTED BY <i>LCRama</i>		29. CONTINUATION <input type="checkbox"/> SHEET USED			
28. CAUSE AND CORRECTIVE ACTION <i>REFER TO IDC #PE 15.82 FROM L. O'CONNELL TO O.I. NAKANO. (COPY ATTACHED)</i>										30. FBG CLOSURE <i>LCRama 2/2/82</i>					
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <i>IDC #PE 15.82 (COPY ATTACHED)</i>										32. CONTINUATION <input type="checkbox"/> SHEET USED					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN										34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		DEFECT CODE	
36. RESPONSIBLE ENGINEER <i>LCRama</i>										37. SPACECRAFT SYSTEM ENGINEER <i>LCRama</i>		38. CUSTOMER OR SUPPLIER <i>LCRama</i>		39. DATE <i>2/2/82</i>	
40. DATE <i>5/1/82</i>										41. DATE <i>2/1/82</i>		42. DATE <i>2/1/82</i>		43. DATE <i>2/1/82</i>	



**SANTA BARBARA RESEARCH CENTER**  
*A Subsidiary of Hughes Aircraft Company*  
**INTERNAL MEMORANDUM**

BLDG. B-11 MAIL STA. 39  
EXT. 6357

LO:jc

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8107

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>TM PL 1162</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>0845</b>	5. DATE OBSERVED <b>MO 3 DA 30 YR 82</b>	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART	
	EQUIPMENT IDENTIFICATION:		NAME		PART NUMBER		S/N
	7. SUBSYSTEM <b>Electronic Module</b>				<b>52347</b>		<b>003</b>
	8. UNIT <b>51402</b>				<b>51402</b>		
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY						
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD						
	11. OTHER						
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS		
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP AXIS FOR	<input type="checkbox"/> THERMAL VAC MIN TYPE	HRS AT	
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE <b>J24 Pin 5 and 6 +/- 20V Return reads 1.6 ohms to chassis ground. It should be 10 meg ohm min. J24 pin 11 reads 0.12 ohms thru 32 read too low (approx. 86k should be 10 M ohm min) to chassis</b>						
	15. TEST PROCEDURE <b>TP 33015-53</b>		16. ORIGINATOR <b>P.C. Buckley</b>	17. DATE <b>224213-70-82</b>	18. CONTINUATION SHEET USED		
	18. VERIFICATION AND FAILURE ANALYSIS <b>U3 mounting screw was shorting heat sink to board ground. Above hole w/ (AB) board in. Reads (Pin 11) 124 k w/ AB out. (Meter + to chassis) and 1.07 M ohm (Meter + to Pin 11)</b>						
	19. FAILED ITEM NAME AND PART NUMBER <b>None</b>						
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Correct fault by re-mounting U3 and assuring that sleeving correctly insulates the screw from contact with anything but the U3 case.</b>						
	21. AUTHORIZATION <b>Current</b>		22. DATE <b>3/31/82</b>	23. CONTINUATION SHEET USED			
	23. REWORK/RETEST ACTION TAKEN <b>Repositioned and U3 and reinstalled hardware in new sleeving on screws.</b>						
	24. QA Rework						
	25. QA RETEST						
	MANUFACTURING AND TEST	26. LIST ALL PARTS REPLACED					
PART NUMBER		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER
ENGINEERING/RELIABILITY	27. REWORK BY <b>ADP/ma</b>		28. DATE <b>3/31/82</b>	29. RETESTED BY		30. DATE <b>3/31/82</b>	31. CONTINUATION SHEET USED
	30. CAUSE AND CORRECTIVE ACTION <b>MOUNTING OF TO-3 DEVICES WAS NOT STANDARDIZED. THIS LED TO MOUNTING WITH SLEEVING OF WRONG LENGTH AND SCREWS OF DIFFERENT DIAMETERS. THIS FAILURE WAS APPARENTLY A DESIGN PROBLEM. ECA 2722/01 WRITTEN AT END OF CONTRACT SHOULD PREVENT SIMILAR PROBLEMS IN ANY FUTURE FABRICATIONS.</b>						
	31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ECA 2722 EDC</b>						
	32. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR/OUT	<input type="checkbox"/> UNKNOWN DEFECT CODE	
	33. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR		<input type="checkbox"/> SAFETY	
	35. RESPONSIBLE ENGINEER <b>Current</b>		36. DATE <b>22-17 5/11/82</b>	37. SPACECRAFT SYSTEM ENGINEER <b>FLCangel</b>		38. DATE <b>22-41 5/11/82</b>	39. DATE
	39. RELIABILITY <b>Li. Rulian</b>		40. DATE <b>5/11/82</b>	40. CUSTOMER OR SUPPLIER		41. DATE	
	42. CUSTOMER OR SUPPLIER						
	43. CUSTOMER OR SUPPLIER						
	44. CUSTOMER OR SUPPLIER						

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

# FAILURE REPORT CONTINUATION SHEET

58107

58107

CONTINUATION SHEET LETTER\*

A

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED

☐

30 NOTE: SLEEVING WAS CRUSHED DUE TO MISALIGNMENT  
BETWEEN BOARD AND U.S. STANDARDIZED MOUNTING  
(ECA 2722/01) WILL CORRECT PROBLEM - QVP

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 810**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>TM PL 1162</b>	2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>1000</b>	5. DATE OBSERVED <b>MO 3 DA 30 YR 8</b>
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART				
	EQUIPMENT IDENTIFICATION:				
	7. SUBSYSTEM <b>Electronic Module</b>	NAME	PART NUMBER <b>5247</b>	S/N <b>003</b>	MANUFACTURER
	8. UNIT				
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				
	11. OTHER				
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS				
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER				
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE <b>J24-1, C1, P4 P5, 01, 3 G2 which are connected to J24-1 should read 10 meg ohm min. Then all on J24-1 and seem to be related to the A &amp; board failure on PR 8107</b>				
	15. TEST PROCEDURE <b>TP 32015-531</b>	16. ORIGINATOR <b>RC Buckley</b>	17. CONTINUATION SHEET USED <input type="checkbox"/>		
	18. VERIFICATION AND FAILURE ANALYSIS <b>N/A -</b>				
	<b>ITEM 14 IDENTIFIED WRONG PINS - TO BE RE-WRITTEN (INCORRECT PIN #'S IN 14a)</b>				
	19. FILED ITEM NAME AND PART NUMBER				
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>See 18</b>				
	21. AUTHORIZATION				
	22. CONTINUATION SHEET USED <input type="checkbox"/>				
	23. QA Rework				
	24. QA RETEST				
MANUFACTURING AND TEST	25. Rework/Retest Action Taken <b>N/A</b>				
	26. QA RETEST				
	27. CONTINUATION SHEET USED <input type="checkbox"/>				
	28. QA Rework				
	29. QA RETEST				
	30. CONTINUATION SHEET USED <input type="checkbox"/>				
	31. QA Rework				
	32. QA RETEST				
	33. CONTINUATION SHEET USED <input type="checkbox"/>				
	34. QA Rework				
ENGINEERING/RELIABILITY	35. CAUSE AND CORRECTIVE ACTION <b>THIS DISCREPANCY WAS TRANSFERRED TO S 811 BECAUSE OF ERROR NOTED IN ITEM 18</b>				
	36. CONTINUATION SHEET USED <input type="checkbox"/>				
	37. QA Rework				
	38. QA RETEST				
	39. CONTINUATION SHEET USED <input type="checkbox"/>				
	40. QA Rework				
	41. QA RETEST				
	42. CONTINUATION SHEET USED <input type="checkbox"/>				
	43. QA Rework				
	44. QA RETEST				
45. CONTINUATION SHEET USED <input type="checkbox"/>					
46. QA Rework					
47. QA RETEST					
48. CONTINUATION SHEET USED <input type="checkbox"/>					
49. QA Rework					
50. QA RETEST					
51. CONTINUATION SHEET USED <input type="checkbox"/>					
52. QA Rework					
53. QA RETEST					
54. CONTINUATION SHEET USED <input type="checkbox"/>					
55. QA Rework					
56. QA RETEST					
57. CONTINUATION SHEET USED <input type="checkbox"/>					
58. QA Rework					
59. QA RETEST					
60. CONTINUATION SHEET USED <input type="checkbox"/>					
61. QA Rework					
62. QA RETEST					
63. CONTINUATION SHEET USED <input type="checkbox"/>					
64. QA Rework					
65. QA RETEST					
66. CONTINUATION SHEET USED <input type="checkbox"/>					
67. QA Rework					
68. QA RETEST					
69. CONTINUATION SHEET USED <input type="checkbox"/>					
70. QA Rework					
71. QA RETEST					
72. CONTINUATION SHEET USED <input type="checkbox"/>					
73. QA Rework					
74. QA RETEST					
75. CONTINUATION SHEET USED <input type="checkbox"/>					
76. QA Rework					
77. QA RETEST					
78. CONTINUATION SHEET USED <input type="checkbox"/>					
79. QA Rework					
80. QA RETEST					
81. CONTINUATION SHEET USED <input type="checkbox"/>					
82. QA Rework					
83. QA RETEST					
84. CONTINUATION SHEET USED <input type="checkbox"/>					
85. QA Rework					
86. QA RETEST					
87. CONTINUATION SHEET USED <input type="checkbox"/>					
88. QA Rework					
89. QA RETEST					
90. CONTINUATION SHEET USED <input type="checkbox"/>					
91. QA Rework					
92. QA RETEST					
93. CONTINUATION SHEET USED <input type="checkbox"/>					
94. QA Rework					
95. QA RETEST					
96. CONTINUATION SHEET USED <input type="checkbox"/>					
97. QA Rework					
98. QA RETEST					
99. CONTINUATION SHEET USED <input type="checkbox"/>					
100. QA Rework					
101. QA RETEST					
102. CONTINUATION SHEET USED <input type="checkbox"/>					
103. QA Rework					
104. QA RETEST					
105. CONTINUATION SHEET USED <input type="checkbox"/>					
106. QA Rework					
107. QA RETEST					
108. CONTINUATION SHEET USED <input type="checkbox"/>					
109. QA Rework					
110. QA RETEST					
111. CONTINUATION SHEET USED <input type="checkbox"/>					
112. QA Rework					
113. QA RETEST					
114. CONTINUATION SHEET USED <input type="checkbox"/>					
115. QA Rework					
116. QA RETEST					
117. CONTINUATION SHEET USED <input type="checkbox"/>					
118. QA Rework					
119. QA RETEST					
120. CONTINUATION SHEET USED <input type="checkbox"/>					
121. QA Rework					
122. QA RETEST					
123. CONTINUATION SHEET USED <input type="checkbox"/>					
124. QA Rework					
125. QA RETEST					
126. CONTINUATION SHEET USED <input type="checkbox"/>					
127. QA Rework					
128. QA RETEST					
129. CONTINUATION SHEET USED <input type="checkbox"/>					
130. QA Rework					
131. QA RETEST					
132. CONTINUATION SHEET USED <input type="checkbox"/>					
133. QA Rework					
134. QA RETEST					
135. CONTINUATION SHEET USED <input type="checkbox"/>					
136. QA Rework					
137. QA RETEST					
138. CONTINUATION SHEET USED <input type="checkbox"/>					
139. QA Rework					
140. QA RETEST					
141. CONTINUATION SHEET USED <input type="checkbox"/>					
142. QA Rework					
143. QA RETEST					
144. CONTINUATION SHEET USED <input type="checkbox"/>					
145. QA Rework					
146. QA RETEST					
147. CONTINUATION SHEET USED <input type="checkbox"/>					
148. QA Rework					
149. QA RETEST					
150. CONTINUATION SHEET USED <input type="checkbox"/>					
151. QA Rework					
152. QA RETEST					
153. CONTINUATION SHEET USED <input type="checkbox"/>					
154. QA Rework					
155. QA RETEST					
156. CONTINUATION SHEET USED <input type="checkbox"/>					
157. QA Rework					
158. QA RETEST					
159. CONTINUATION SHEET USED <input type="checkbox"/>					
160. QA Rework					
161. QA RETEST					
162. CONTINUATION SHEET USED <input type="checkbox"/>					
163. QA Rework					
164. QA RETEST					
165. CONTINUATION SHEET USED <input type="checkbox"/>					
166. QA Rework					
167. QA RETEST					
168. CONTINUATION SHEET USED <input type="checkbox"/>					
169. QA Rework					
170. QA RETEST					
171. CONTINUATION SHEET USED <input type="checkbox"/>					
172. QA Rework					
173. QA RETEST					
174. CONTINUATION SHEET USED <input type="checkbox"/>					
175. QA Rework					
176. QA RETEST					
177. CONTINUATION SHEET USED <input type="checkbox"/>					
178. QA Rework					
179. QA RETEST					
180. CONTINUATION SHEET USED <input type="checkbox"/>					
181. QA Rework					
182. QA RETEST					
183. CONTINUATION SHEET USED <input type="checkbox"/>					
184. QA Rework					
185. QA RETEST					
186. CONTINUATION SHEET USED <input type="checkbox"/>					
187. QA Rework					
188. QA RETEST					
189. CONTINUATION SHEET USED <input type="checkbox"/>					
190. QA Rework					
191. QA RETEST					
192. CONTINUATION SHEET USED <input type="checkbox"/>					
193. QA Rework					
194. QA RETEST					
195. CONTINUATION SHEET USED <input type="checkbox"/>					
196. QA Rework					
197. QA RETEST					
198. CONTINUATION SHEET USED <input type="checkbox"/>					
199. QA Rework					
200. QA RETEST					
201. CONTINUATION SHEET USED <input type="checkbox"/>					
202. QA Rework					
203. QA RETEST					
204. CONTINUATION SHEET USED <input type="checkbox"/>					
205. QA Rework					
206. QA RETEST					
207. CONTINUATION SHEET USED <input type="checkbox"/>					
208. QA Rework					
209. QA RETEST					
210. CONTINUATION SHEET USED <input type="checkbox"/>					
211. QA Rework					
212. QA RETEST					
213. CONTINUATION SHEET USED <input type="checkbox"/>					
214. QA Rework					
215. QA RETEST					
216. CONTINUATION SHEET USED <input type="checkbox"/>					
217. QA Rework					
218. QA RETEST					
219. CONTINUATION SHEET USED <input type="checkbox"/>					
220. QA Rework					
221. QA RETEST					
222. CONTINUATION SHEET USED <input type="checkbox"/>					
223. QA Rework					
224. QA RETEST					
225. CONTINUATION SHEET USED <input type="checkbox"/>					
226. QA Rework					
227. QA RETEST					
228. CONTINUATION SHEET USED <input type="checkbox"/>					
229. QA Rework					
230. QA RETEST					
231. CONTINUATION SHEET USED <input type="checkbox"/>					
232. QA Rework					
233. QA RETEST					
234. CONTINUATION SHEET USED <input type="checkbox"/>					
235. QA Rework					
236. QA RETEST					
237. CONTINUATION SHEET USED <input type="checkbox"/>					
238. QA Rework					
239. QA RETEST					
240. CONTINUATION SHEET USED <input type="checkbox"/>					
241. QA Rework					
242. QA RETEST					
243. CONTINUATION SHEET USED <input type="checkbox"/>					
244. QA Rework					
245. QA RETEST					
246. CONTINUATION SHEET USED <input type="checkbox"/>					
247. QA Rework					
248. QA RETEST					
249. CONTINUATION SHEET USED <input type="checkbox"/>					
250. QA Rework					
251. QA RETEST					
252. CONTINUATION SHEET USED <input type="checkbox"/>					
253. QA Rework					
254. QA RETEST					
255. CONTINUATION SHEET USED <input type="checkbox"/>					
256. QA Rework					
257. QA RETEST					
258. CONTINUATION SHEET USED <input type="checkbox"/>					
259. QA Rework					
260. QA RETEST					
261. CONTINUATION SHEET USED <input type="checkbox"/>					
262. QA Rework					
263. QA RETEST					
264. CONTINUATION SHEET USED <input type="checkbox"/>					
265. QA Rework					
266. QA RETEST					
267. CONTINUATION SHEET USED <input type="checkbox"/>					
268. QA Rework					
269. QA RETEST					
270. CONTINUATION SHEET USED <input type="checkbox"/>					
271. QA Rework					
272. QA RETEST					
273. CONTINUATION SHEET USED <input type="checkbox"/>					
274. QA Rework					
275. QA RETEST					
276. CONTINUATION SHEET USED <input type="checkbox"/>					
277. QA Rework					
278. QA RETEST					
279. CONTINUATION SHEET USED <input type="checkbox"/>					
280. QA Rework					
281. QA RETEST					
282. CONTINUATION SHEET USED <input type="checkbox"/>					
283. QA Rework					
284. QA RETEST					
285. CONTINUATION SHEET USED <input type="checkbox"/>					
286. QA Rework					
287. QA RETEST					
288. CONTINUATION SHEET USED <input type="checkbox"/>					
289. QA Rework					
290. QA RETEST					
291. CONTINUATION SHEET USED <input type="checkbox"/>					
292. QA Rework					
293. QA RETEST					
294. CONTINUATION SHEET USED <input type="checkbox"/>					
295. QA Rework					
296. QA RETEST					
297. CONTINUATION SHEET USED <input type="checkbox"/>					
298. QA Rework					
299. QA RETEST					
300. CONTINUATION SHEET USED <input type="checkbox"/>					
301. QA Rework					
302. QA RETEST					
303. CONTINUATION SHEET USED <input type="checkbox"/>					
304. QA Rework					
305. QA RETEST					
306. CONTINUATION SHEET USED <input type="checkbox"/>					
307. QA Rework					
308. QA RETEST					
309. CONTINUATION SHEET USED <input type="checkbox"/>					
310. QA Rework					
311. QA RETEST					
312. CONTINUATION SHEET USED <input type="checkbox"/>					
313. QA Rework					
314. QA RETEST					
315. CONTINUATION SHEET USED <input type="checkbox"/>					
316. QA Rework					
317. QA RETEST					
318. CONTINUATION SHEET USED <input type="checkbox"/>					
319. QA Rework					
320. QA RETEST					
321. CONTINUATION SHEET USED <input type="checkbox"/>					
322. QA Rework					
323. QA RETEST					
324. CONTINUATION SHEET USED <input type="checkbox"/>					
325. QA Rework					
326. QA RETEST					
327. CONTINUATION SHEET USED <input type="checkbox"/>					
328. QA Rework					
329. QA RETEST					
330. CONTINUATION SHEET USED <input type="checkbox"/>					
331. QA Rework					
332. QA RETEST					
333. CONTINUATION SHEET USED <input type="checkbox"/>					
334. QA Rework					
335. QA RETEST					
336. CONTINUATION SHEET USED <input type="checkbox"/>					
337. QA Rework					
338. QA RETEST					
339. CONTINUATION SHEET USED <input type="checkbox"/>					
340. QA Rework					
341. QA RETEST					
342. CONTINUATION SHEET USED <input type="checkbox"/>					
343. QA Rework					
344. QA RETEST					
345. CONTINUATION SHEET USED <input type="checkbox"/>					
346. QA Rework					
347. QA RETEST					
348. CONTINUATION SHEET USED <input type="checkbox"/>					
349. QA Rework					
350. QA RETEST					
351. CONTINUATION SHEET USED <input type="checkbox"/>					
352. QA Rework					
353. QA RETEST					
354. CONTINUATION SHEET USED <input type="checkbox"/>					
355. QA Rework					
356. QA RETEST					
357. CONTINUATION SHEET USED <input type="checkbox"/>					
358. QA Rework					
359. QA RETEST					
360. CONTINUATION SHEET USED <input type="checkbox"/>					
361. QA Rework					
362. QA RETEST					
363. CONTINUATION SHEET USED <input type="checkbox"/>					
364. QA Rework					
365. QA RETEST					
366. CONTINUATION SHEET USED <input type="checkbox"/>					
367. QA Rework					
368. QA RETEST					
369. CONTINUATION SHEET USED <input type="checkbox"/>					
370. QA Rework					
371. QA RETEST					
372. CONTINUATION SHEET USED <input type="checkbox"/>					
373. QA Rework					
374. QA RETEST					
375. CONTINUATION SHEET USED <input type="checkbox"/>					
376. QA Rework					
377. QA RETEST					
378. CONTINUATION SHEET USED <input type="checkbox"/>					
379. QA Rework					
380. QA RETEST					
381. CONTINUATION SHEET USED <input type="checkbox"/>					
382. QA Rework					
383. QA RETEST					
384. CONTINUATION SHEET USED <input type="checkbox"/>					
385. QA Rework					
386. QA RETEST					
387. CONTINUATION SHEET USED <input type="checkbox"/>					
388. QA Rework					
389. QA RETEST					
390. CONTINUATION SHEET USED <input type="checkbox"/>					
391. QA Rework					
392. QA RETEST					
393. CONTINUATION SHEET USED <input type="checkbox"/>					
394. QA Rework					
395. QA RETEST					
396. CONTINUATION SHEET USED <input type="checkbox"/>					
397. QA Rework					
398. QA RETEST					
399. CONTINUATION SHEET USED <input type="checkbox"/>					
400. QA Rework					
401. QA RETEST					
402. CONTINUATION SHEET USED <input type="checkbox"/>					
403. QA Rework					
404. QA RETEST					
405. CONTINUATION SHEET USED <input type="checkbox"/>					
406. QA Rework					
407. QA RETEST					
408. CONTINUATION SHEET USED <input type="checkbox"/>					
409. QA Rework					
410. QA RETEST					
411. CONTINUATION SHEET USED <input type="checkbox"/>					
412. QA Rework					
413. QA RETEST					
414. CONTINUATION SHEET USED <input type="checkbox"/>					
415. QA Rework					
416. QA RETEST					
417. CONTINUATION SHEET USED <input type="checkbox"/>					
418. QA Rework					
419. QA RETEST					
420. CONTINUATION SHEET USED <input type="checkbox"/>					
421. QA Rework					
422. QA RETEST					
423. CONTINUATION SHEET USED <input type="checkbox"/>					
424. QA Rework					
425. QA RETEST					
426. CONTINUATION SHEET USED <input type="checkbox"/>					
427. QA Rework					
428. QA RETEST					
429. CONTINUATION SHEET USED <input type="checkbox"/>					
430. QA Rework					
431. QA RETEST					
432. CONTINUATION SHEET USED <input type="checkbox"/>					
433. QA Rework					
434. QA RETEST					
435. CONTINUATION SHEET USED <input type="checkbox"/>					
436. QA Rework					
437. QA RETEST					
438. CONTINUATION SHEET USED <input type="checkbox"/>					
439. QA Rework					
440. QA RETEST					
441. CONTINUATION SHEET USED <input type="checkbox"/>					
442. QA Rework					
443. QA RETEST					
444. CONTINUATION SHEET USED <input type="checkbox"/>					
445. QA Rework					
446. QA RETEST					
447. CONTINUATION SHEET USED <input type="checkbox"/>					
448. QA Rework					
449. QA RETEST					
450. CONTINUATION SHEET USED <input type="checkbox"/>					
451. QA Rework					
452. QA RETEST					
453. CONTINUATION SHEET USED <input type="checkbox"/>					
454. QA Rework					
455. QA RETEST					
456. CONTINUATION SHEET USED <input type="checkbox"/>					
457. QA Rework					
458. QA RETEST					
459. CONTINUATION SHEET USED <input type="checkbox"/>					
460. QA Rework					
461. QA RETEST					
462. CONTINUATION SHEET USED <input type="checkbox"/>					
463. QA Rework					
464. QA RETEST					
465. CONTINUATION SHEET USED <input type="checkbox"/>					
466. QA Rework					
467. QA RETEST					
468. CONTINUATION SHEET USED <input type="checkbox"/>					
469. QA Rework					
470. QA RETEST					
471. CONTINUATION SHEET USED <input type="checkbox"/>					
472. QA Rework					
473. QA RETEST					
474. CONTINUATION SHEET USED <input type="checkbox"/>					
475. QA Rework					
476. QA RETEST					
477. CONTINUATION SHEET USED <input type="checkbox"/>					
478. QA Rework					
479. QA RETEST					
480. CONTINUATION SHEET USED <input type="checkbox"/>					
481. QA Rework					
482. QA RETEST					
483. CONTINUATION SHEET USED <input type="checkbox"/>					
484. QA Rework					
485. QA RETEST					
486. CONTINUATION SHEET USED <input type="checkbox"/>					
487. QA Rework					
488. QA RETEST					
489. CONTINUATION SHEET USED <input type="checkbox"/>					
490. QA Rework					
491. QA RETEST					
492. CONTINUATION SHEET USED <input type="checkbox"/>					
493. QA Rework					
494. QA RETEST					
495. CONTINUATION SHEET USED <input type="checkbox"/>					
496. QA Rework					
497. QA RETEST					
498. CONTINUATION SHEET USED <input type="checkbox"/>					
499. QA Rework					
500. QA RETEST					
501. CONTINUATION SHEET USED <input type="checkbox"/>					
502. QA Rework					
503. QA RETEST					
504. CONTINUATION SHEET USED <input type="checkbox"/>					
505. QA Rework					
506. QA RETEST					
507. CONTINUATION SHEET USED <input type="checkbox"/>					
508. QA Rework					
509. QA RETEST					
510. CONTINUATION SHEET USED <input type="checkbox"/>					
511. QA Rework					
512. QA RETEST					
513. CONTINUATION SHEET USED <input type="checkbox"/>					
514. QA Rework					
515. QA RETEST					
516. CONTINUATION SHEET USED <input type="checkbox"/>					
517. QA Rework					
518. QA RETEST					
519. CONTINUATION SHEET USED <input type="checkbox"/>					
520. QA Rework					
521. QA RETEST					
522. CONTINUATION SHEET USED <input type="checkbox"/>					
523. QA Rework					
524. QA RETEST					
525. CONTINUATION SHEET USED <input type="checkbox"/>					
526. QA Rework					
527. QA RETEST					
52					

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT****S 8112**

1. PROGRAM NAME AND NUMBER <b>TAI PL1162</b>		2. GLA		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>1000</b>		5. DATE OBSERVED <b>MO 3 DA 30 YR 82</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM <b>Electronics Module</b>		NAME <b>T.M.</b>		PART NUMBER <b>52347</b>		S/N <b>WJ</b>		MANUFACTURER	
8. UNIT <b>NOTE: Cancels &amp; supersedes FR 8108 which has wrong 124 pin nos.</b>									
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE <b>124 Pins 1, 12, 29, 30, 31, 32 read 86.25K ohms to chassis ground and should read &gt; 10meg ohms. Seemed related to (A8) board fault in FR 8107. A8 board was in place for above readings.</b>									
15. TEST PROCEDURE <b>72 3215-531</b>		P/R <b>5-1-1.3</b>		16. ORIGINATOR <b>Roy C. Buckley</b>		ORG <b>2242</b>		DATE <b>3-31-82</b>	
17. CONTINUATION SHEET USED <input type="checkbox"/>									
18. VERIFICATION AND FAILURE ANALYSIS <b>When the A8 and A7 board shorts were repaired these readings returned to normal. A8, 5140<math>\Omega</math>; A7, 5139<math>\Omega</math></b>									
19. FAILED ITEM NAME AND PART NUMBER									
20. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Already done on FR's 8107 &amp; 8368</b>									
21. AUTHORIZATION									
22. CONTINUATION SHEET USED <input type="checkbox"/>									
23. REWORK, RETEST ACTION TAKEN <b>N/A</b>									
24. QA Rework <input checked="" type="checkbox"/>									
25. QA Retest <input checked="" type="checkbox"/>									
26. JUST ALL PARTS REPLACED									
PART NUMBER		CMT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
PROBABLE DEFECT		ANALYSIS NUMBER							
27. REWORK BY <b>N/A</b>									
ORG		DATE		28. RETESTED BY		ORG		DATE	
29. CONTINUATION SHEET USED <input type="checkbox"/>									
30. CAUSE AND CORRECTIVE ACTION <b>CASE UNKNOWN SECOND TORN TAPE WITH GROUND. See 20 - For 8368 A KAPTON TAPE INSULATOR WAS INSTALLED BETWEEN U28 AND PWB. THERE WAS NO DETERMINATION OF CAUSE OF TEAR IN INSULATION. (POSSIBLE DEFECTIVE MATERIAL) For 8107 A MISALIGNMENT BETWEEN U3 AND PWB CAUSED THE</b>									
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ECA 2222 EOC</b>									
32. BASIC CAUSE OF FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> MIRRORING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input checked="" type="checkbox"/> UNKNOWN									
33. DEFECT CODE									
34. FAILURE MODE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
36. SPACECRAFT SYSTEMS ENGINEER <b>2241</b>									
37. RESPONSIBLE ENGINEER <b>2241</b>									
38. DATE <b>4/6/82</b>									
39. DATE <b>4-26-82</b>									
40. DATE <b>5-11-82</b>									

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT  
CONTINUATION SHEET

FAILURE NO.

58112

CONTINUATION ENTRY LETTER

A

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED



30 SLEEVING TO BE CRUSHED. ECA 2722 (END OF  
CONTRACT) WILL STANDARDIZE THIS MOUNTING, AND  
PREVENT FUTURE OCCURRENCE OF SIMILAR DISCREP-  
ANCIES. QP

<div style="border: 1px solid black; padding: 2px; display: inline-block;"> <b>SBRC</b> </div>		<b>ENGINEERING CHANGE REQUEST</b>		NO. <u>TM2722/01</u>	
SHEET 1 OF <u>1</u>					
DRAWING TITLE <b>PWB ASSY, TELEMETRY SCALING - FUSELINK - LAMP SEQUENCER</b>			DRAWING NUMBER <b>51402</b>		REV <b>D</b>
CLASS CHANGE <input type="checkbox"/> I <input checked="" type="checkbox"/> A	DRAWING TYPE <input type="checkbox"/> A <input checked="" type="checkbox"/> R	PRIORITY OF CHANGE <input type="checkbox"/> emergency <input type="checkbox"/> urgent <input checked="" type="checkbox"/> routine		PL NO. <b>1162</b> PL	WORK AUTHORIZATION NO. <b>V415-67-30</b>
OTHER AFFECTED ENGINEERING DOCUMENTS <b>SEE ECA</b>					
REASON CHANGE NEEDED (EXPLAIN IN FULL) <b>U3 MOUNTING SCREW WAS SHORTING HEATSINK TO PWB GROUND (REF: FR 58107)</b>					
NATURE OF PROBLEM AND/OR REQUIRED CHANGE <b>STANDARDIZE MOUNTING OF TO-3 CONFIGURED DEVICES &amp; ICs.</b>					
<div style="text-align: right; padding-right: 50px;">           ORIGINAL PAGE IS OF POOR QUALITY         </div>					
REQUESTED BY <b>R.T. Luchessa</b>		DATE <b>8/25/82</b>	APPROVAL <b>[Signature]</b>		DATE <b>5/10/82</b>
CHECKED BY <b>[Signature]</b>		DATE <b>8/25/82</b>	APPROVAL <b>[Signature]</b>		DATE <b>5-11-82</b>
EFFECTIVITY <b>EOC 51065</b> <b>SN C04 &amp; S453</b>		APPROVAL <b>[Signature]</b>	DATE <b>5-11-82</b>	ACTION TAKEN <b>EOC _____ DWG. REV. _____</b>	
ITEM DISPOSITION REWORK <input type="checkbox"/> ITEMS CONFORM <input type="checkbox"/> NO. ITEMS MADE <input type="checkbox"/> REJECT <input type="checkbox"/> USE <input checked="" type="checkbox"/> NOT APPLICABLE <input type="checkbox"/>		APPROVAL <b>[Signature]</b>	DATE <b>5/11/82</b>	CHECKED BY <b>[Signature]</b>	DATE <b>5/12/82</b>
		APPROVAL <b>[Signature]</b>	DATE <b>5/27/82</b>	CHECKED BY <b>[Signature]</b>	DATE <b>5/27/82</b>

58112

SE DEC JAN SI



38112

~~SBRC~~  
CONTINUATION SHEETSBRC  
A SUBSIDIARY OF HUGHES AIRCRAFT COMPANY☐ ECR ☒ ECA ☐ ECAE

NO.

REV

SH NO.

2

ALL INFORMATION ENTERED HEREON SHALL BE IDENTIFIED BY THE APPROPRIATE BLOCK HEADING FROM THE ECR, ECA, OR E

ENGINEERING DRAWINGS/  
ASSEMBLIES AFFECTED (CONTD)50918  
51398  
51400  
51402  
51404  
53877  
53878  
50900  
50902  
50948  
50950  
51813  
51815  
52797  
52799ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS  
OF POOR QUALITY  
SPACE AND COMMUNICATIONS GROUP  
FAILURE REPORT

S 8125

1. PROGRAM NAME AND NUMBER <b>TM PL 1162</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>1700</b>	5. DATE OBSERVED <b>MO 4 DA 6 YR 82</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MCAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM <b>Electronic Module</b>		PART NUMBER <b>52347</b>		S/N <b>603</b>	MANUFACTURER
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MCAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEMS <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>J35 PIN 29 (Signal ground Band 1 ch 10) open</b>					
15. TEST PROCEDURE <b>TP 32015-531</b>		16. PARA <b>53.2.5</b>	18. ORIGINATOR <b>Roy G. Buckley</b>	19. ORG <b>2242</b>	DATE <b>4/6/82</b>
17. VERIFICATION AND FAILURE ANALYSIS <b>Traced fault to loosely mounted wear saver. Tightened wear saver and problem was solved.</b>		19. CONTINUATION <input type="checkbox"/> SHEET USED			
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>See 18</b>					
21. AUTHORIZATION					
22. REWORK/RETEST ACTION TAKEN <b>N/A</b>					
23. QA Rework					
24. QA Retest					
25. LIST ALL PARTS REPLACED PART NUMBER		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
PROBABLE DEFECT		ANALYSIS NUMBER			
27. REWORK BY		ORG	DATE	28. RETESTED BY	ORG
29. CAUSE AND CORRECTIVE ACTION <b>TEST SETUP WAS NOT PROPERLY MATED THROUGH WEAR Saver In future, torque wear saver screws better TEST TECHNICIANS HAVE BEEN ALERTED TO CHECK MATING OF CONNECTOR Mole THOROUGHLY - 2</b>		30. FAILURE CLASSIFICATION <b>2241</b>			
31. CONTINUATION <input type="checkbox"/> SHEET USED		32. PRO CLOSURE <b>4-9-82</b>			
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT TEST PROCEDURE TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING/ERROR ROUGH HANDLING WEAR-OUT <input type="checkbox"/> UNKNOWN			
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		36. UNKNOWN NO FAILURE		37. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR SAFETY	
38. RESPONSIBLE ENGINEER <b>Current</b>		DATE <b>4/5/82</b>		DATE <b>4/9/82</b>	
39. RELIABILITY <b>Q. Kerline</b>		DATE <b>4-8-82</b>		DATE <b>4-9-82</b>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8126**

1. PROGRAM NAME AND NUMBER <b>TN PL 1162</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>1730</b>	5. DATE OBSERVED <b>MO 40 CA 6 YR 82</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:		NAME	PART NUMBER	S/N	MANUFACTURER
7. SUBSYSTEM <b>Electronics Module</b>			<b>57347</b>	<b>003</b>	
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS		<input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT		<input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER			
14. DESCRIPTION OF FAILURE <b>J30 PIN 49 A (Signal ground Band 1 Ch 15) open</b>					
15. TEST PROCEDURE <b>TP 32015-531</b>		16. PARA <b>6.3.2.3</b>	18. ORIGINATOR <b>Roy C Buckley</b>	19. ORG <b>2242</b>	20. DATE <b>4/7/82</b>
17. VERIFICATION AND FAILURE ANALYSIS <b>Traced fault to loosely mounted wear saver. Tightened wear saver and problem was solved.</b>		17. CONTINUATION SHEET USED <input type="checkbox"/>			
19. FAILED ITEM NAME AND PART NUMBER <b>N/A</b>					
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>See 1B</b>					
21. AUTHORIZATION		ORG	DATE	22. CONTINUATION SHEET USED <input type="checkbox"/>	
23. REWORK/RETEST ACTION TAKEN <b>N/A</b>		24. QA REWORK			
		25. QA RETEST			
26. LIST ALL PARTS REPLACED PART NUMBER		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
<b>N/A</b>					
27. REWORK BY		ORG	DATE	28. RETESTED BY	ORG
29. CAUSE AND CORRECTIVE ACTION <b>TEST SETUP WAS POORLY MATED THROUGH WEARSAVER. In future to prove wear saver screens better. TEST TECHNICIANS HAVE BEEN ALERTED TO CHECK MATING OF CONNECTORS MORE THOROUGHLY.</b>		30. CONTINUATION SHEET USED <input type="checkbox"/>			
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		32. CONTINUATION SHEET USED <input type="checkbox"/>			
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		34. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		35. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
36. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		37. UNKNOWN <input type="checkbox"/> NO FAILURE		38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
39. RESPONSIBLE ENGINEER <b>C. G. G. G.</b>		40. DATE <b>4/8/82</b>	41. DATE <b>4/8/82</b>	42. DATE <b>4/9/82</b>	43. DATE <b>4/9/82</b>
44. RECALLABILITY		45. CUSTOMER OR SUPPLIER			

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8139

1. PROGRAM NAME AND NUMBER <b>TM A-1162</b>		2. GLA		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>10P</b>		5. DATE OBSERVED <b>MO 5 DA 8 YR 82</b>			
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:											
7. SUBSYSTEM				NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT											
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY											
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD						<b>50942 (A4)</b>		<b>202</b>			
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS				<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI				<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR		<input type="checkbox"/> THERMAL VAC MIN TYPE		HRS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <b>CONTROL TEMP VOLTAGE OUT OF SPEC.</b>											
IN P44.6, READING WAS +3.885, S/B 3.0 ± 0.1											
IN P44.7, READING WAS +3.876, S/B 4.0 ± 0.1											
15. TEST PROCEDURE <b>16235 4.4.6, 4.4.7</b>				16. ORIGINATOR <b>SLONAKHP</b>		17. CONTINUATION SHEET USED <input type="checkbox"/>		18. CONTINUATION SHEET USED <input type="checkbox"/>			
19. VERIFICATION AND FAILURE ANALYSIS											
19. FAILED ITEM NAME AND PART NUMBER <b>TEMP CONTROL RD 50942</b>											
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>SPEC WILL BE CHANGED PER EO 4366A TO EXTEND ACCEPTABLE RANGE</b>											
21. AUTHORIZATION <b>Shalens</b>										22. CONTINUATION SHEET USED <input type="checkbox"/>	
23. REWORK/RETEST ACTION TAKEN <b>EO 4366A ISSUED</b>										24. QA Rework	
25. LIST ALL PARTS REPLACED										26. QA RETEST	
PART NUMBER		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT		ANALYSIS NUMBER			
27. REWORK BY										28. RETESTED BY	
ORG		DATE		ORG		DATE		29. CONTINUATION SHEET USED <input type="checkbox"/>			
30. CAUSE AND CORRECTIVE ACTION <b>VOLTAGE TOLERANCES IN SPEC. WERE TOO TIGHT.</b>											
<b>EO 4366A CHANGES TOLERANCES SO THAT PREVIOUS CHANGE READINGS ARE NOW WITHIN SPEC.</b>										31. FRB CLOSURE	
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>EO 4366A EFFECTIVITY 1/23/82</b>										33. CONTINUATION SHEET USED <input type="checkbox"/>	
34. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING/ERROR <input type="checkbox"/> ROUGH/HANDLING <input type="checkbox"/> WEAR/CRIT		35. UNKNOWN DEFECT CODE	
35. FAILURE TYPE		<input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> SPACECRAFT SYSTEM ENGINEER		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
37. RESPONSIBLE ENGINEER <b>Current</b>		ORG <b>51-41</b>		DATE <b>5/21/82</b>		38. SPACECRAFT SYSTEM ENGINEER <b>Exel</b>		ORG <b>50RC</b>		DATE <b>5/21/82</b>	
39. RELIABILITY <b>Current</b>		ORG <b>51-41</b>		DATE <b>5-24-82</b>		40. FLIGHT/TESTER OR SUPPLIER <b>FLC</b>		ORG <b>51-41</b>		DATE <b>5/24/82</b>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAMAIN AHR-OP#600-STEP 2  
REF NCMR 393234  
SPACE AND COMMUNICATIONS GROUP  
FAILURE REPORTORIGINAL PAGE IS  
OF POOR QUALITY  
S 8283

ORIGINATOR	1. PROGRAM NAME AND NUMBER TM VOII PL1162		2. GLA	3. MODEL FLIGHT	4. TIME OBSERVED DAY SHIFT	5. DATE OBSERVED MO 8 DA 20 YR 81
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART
	EQUIPMENT IDENTIFICATION:					
	NAME		PART NUMBER		S/N	MANUFACTURER
	7. SUBSYSTEM					
	8. UNIT					
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY BAND 2 POST AMP SD904-2 201 SBRC					
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
	11. OTHER					
	12. TEST WHEN FAILURE WAS OBSERVED					
ENGINEERING EVALUATION	<input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS	
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> AMBIENT <input type="checkbox"/> EKC/RR	<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP 15.0 <input type="checkbox"/> THERMAL VAC MRS AT. MIN TYPE OTHER	
	14. DESCRIPTION OF FAILURE CHANNEL 13 FAILED TO MEET PRE-GAIN RESISTOR (R8) SELECTION REQUIREMENTS WITHOUT USING AN OUT-OF-RANGE COMPONENT. LIMITS: 4.12K TO 11.8K; VALUE: 3.83K					
	15. TEST PROCEDURE 16597		PARA 4.5	16. ORIGINATOR A.C. DAVISON	ORG 2213	DATE 8-25-81
	17. CONTINUATION <input type="checkbox"/> SHEET USED					
	18. VERIFICATION AND FAILURE ANALYSIS					
	SITUATION VERIFIED AT TEST! SELECTION STEP. NO PARTS OVERSTRESSED THROUGH THE USE OF THIS PART VALUE.					
	19. FAILED ITEM NAME AND PART NUMBER PREGAIN RESISTOR (R87)					
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE OBVIOUSLY AN OUT-OF-RANGE VALUE IS REQUIRED TO MEET GAIN SPECIFICATIONS.					
	21. REWORK/RETEST ACTION TAKEN NONE					
MANUFACTURING AND TEST	22. LIST ALL PARTS REPLACED PART NUMBER		CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
	N/A					
	23. Rework by N/A		ORG	DATE	24. RETESTED BY N/A	ORG
	25. CAUSE AND CORRECTIVE ACTION RANGE SPECIFIED IN 16597 NOT BROAD ENOUGH TO PROVIDE ADJUSTMENT. E.O. TO SPEC REQUIRED. RANGE WAS: 4.12K TO 11.8K CHANGE TO: 3.01K TO 11.8K		26. FAB CLOSURE			
	27. CONTINUATION <input type="checkbox"/> SHEET USED		28. CONTINUATION <input type="checkbox"/> SHEET USED			
	29. DOCUMENT IMPLEMENTING CORRECTIVE ACTION E.O. 3442A-EFFECTIVITY IN 3 & SUBP.		30. BASIC CAUSE OF VERIFIED FAILURE			
	<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
	31. FAILURE TYPE PRIMARY INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		32. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR	
	33. RESPONSIBLE ENGINEER A.C. DAVISON		ORG 2213		DATE 8/26/81	
	34. CAPABILITY COMM		5/41		DATE 10/20/81	
ENGINEERING/RELIABILITY	35. TEST EQUIPMENT DATE 8/26/81		36. SPACECRAFT SYSTEM ENGINEER DATE 8/26/81		37. E.O. NUMBER OR SUPPLIER DATE	
	38. CONTINUATION <input type="checkbox"/> SHEET USED		39. CONTINUATION <input type="checkbox"/> SHEET USED			

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
FAILURE REPORT**S** 8309ORIGINAL PAGE IS  
OF POOR QUALITY

1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER HS 236 2 GLA</b>		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>11AM</b>		5. DATE OBSERVED <b>MO 10 DA 28 YR 81</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
EQUIPMENT IDENTIFICATION:							
7. SUBSYSTEM		NAME		PART NUMBER		S/N	
8. UNIT							
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		VERIFICATION REGISTER UNIT		50948		201	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD							
11. OTHER							
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER		<input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE					
14. DESCRIPTION OF FAILURE <b>SOLDER BRIDGE BETWEEN TRACES TO U31 PIN 7 AND U31 PIN 8</b>							
15. TEST PROCEDURE <b>16422</b>		16. PARA <b>S.1</b>		17. ORIGINATOR <b>J. GUYTON</b>		18. ORG <b>22-13</b>	
19. VERIFICATION AND FAILURE ANALYSIS <b>U31 PIN 7 SHORT TO GND CAUSED NO WORD G PRIMARY OUTPUT. SHORT OBSERVED AND SHOULD BE REMOVED. NO FAILURE TO U31 PIN 7 OUTPUT AS RESULT OF WORKMANSHIP ERROR REFER TO HS 236-7701 ERR STRESS ANALYSIS (COPY ATTACHED)</b>		19. FAILED ITEM NAME AND PART NUMBER		17. CONTINUATION <input type="checkbox"/> SHEET USED			
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		<b>REMOVE SOLDER BRIDGE BETWEEN U31 PIN 7 AND U31 PIN 8. RETEST PER 16422 PARA S.1</b>					
21. AUTHORIZATION <b>J. GUYTON</b>		18. ORG <b>22-13</b>		DATE <b>10-28-81</b>		22. CONTINUATION <input type="checkbox"/> SHEET USED	
23. Rework/Retest Action Taken <b>REMOVED SOLDER BRIDGE BETWEEN TRACES TO U31 PIN 7 AND U31 PIN 8. RETESTED PER 16422 PARA S.1</b>		24. ORG <b>22-13</b>		DATE <b>10-28-81</b>		25. CONTINUATION <input type="checkbox"/> SHEET USED	
26. LIST ALL PARTS REPLACED PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE	
MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUMBER			
27. REWORK BY <b>L. TORRES</b>		ORG <b>22-74</b>		DATE <b>10-28-81</b>		28. RETESTED BY <b>J. GUYTON</b>	
29. ORG <b>22-13</b>		DATE <b>10-30-81</b>		29. CONTINUATION <input type="checkbox"/> SHEET USED			
30. CAUSE AND CORRECTIVE ACTION <b>POOR WORKMANSHIP CAUSED SOLDER SPLASH.</b>							
31. CLOSER SUBSEQUENT VISUAL INSPECTIONS CAN OBSERVE PROBLEM. A MEET WAS HELD WITH MFL AND QA INSPECTION AND REVIEWED THE ABOVE PROBLEM, AND THIS SOLDER BRIDGE FUTURE ASSIGNED							
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION							
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN		DEFECT CODE					
34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
36. RESPONSIBLE ENGINEER <b>J. Bonach</b>		ORG <b>22-13</b>		DATE <b>10-30-81</b>		37. SPACECRAFT SYSTEM ENGINEER <b>J. GUYTON</b>	
38. ORG <b>22-13</b>		DATE <b>10-30-81</b>		39. CUSTOMER OR SUPPLIER <b>Y. J.</b>		DATE <b>22-61 811103</b>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS  
OF POOR QUALITY  
SPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT** 1430**S** 8310

1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER HS 236</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>2:30 PM</b>	5. DATE OBSERVED <b>MO 10 DA 28 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:					
NAME		PART NUMBER		S/N	MANUFACTURER
7. SUBSYSTEM					
8. UNIT <b>ELECTRONIC MODULE</b>					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<b>CAS AMP/T.NCHWORM DRIVER</b>		<b>50926</b>	<b>201</b>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		<b>STB KC</b>			
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE					
14. DESCRIPTION OF FAILURE <b>TS 16234 PARA 3.3.2.2 NO -12V OUTPUT</b>					
15. TEST PROCEDURE <b>TS 16234</b>					
16. VERIFICATION AND FAILURE ANALYSIS <b>AR 6 OPERATIONAL AMPLIFIER INSTALLED UPSIDE DOWN (CLOSED BACKWARD)</b> <b>AR 6 OVERSTRESSED - NO OTHER PARTS OVERSTRESSED @ 2-9-82</b> <b>+12V AND -12V POWER TO AR 6 WERE INTERCHANGED - THIS WOULD CAUSE THE OPAMP TO</b>		17. CONTINUATION <input type="checkbox"/> SHEET USED			
18. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REMOVE AND REPLACE AR 6</b> <b>RETEST PER PARA 3.3.2.2</b>					
21. AUTHORIZATION <b>JH Bernick</b>					
22. CONTINUATION <input type="checkbox"/> SHEET USED					
23. QA RETEST					
24. LIST ALL PARTS REPLACED					
PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
	<b>AR 6</b>				
27. REWORK BY <b>M GUERRA</b>					
28. RETESTED BY <b>E. P. O'NEILL</b>					
29. CONTINUATION <input type="checkbox"/> SHEET USED					
30. CAUSE AND CORRECTIVE ACTION <b>WORKMANSHIP ERROR. ASSEMBLY TECHNICIAN HAS BEEN CAUTIONED TO REVIEW ORIENTATION OF DEVICE PRIOR TO SOLDERING. @ 2-9-82</b>					
31. CONTINUATION <input type="checkbox"/> SHEET USED					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN					
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
35. RESPONSIBLE ENGINEER <b>JH Bernick</b>					
36. DATE <b>2-2-82</b>					
37. DATE <b>2-11-82</b>					
38. DATE <b>2-11-82</b>					
39. DATE <b>2-11-82</b>					
40. DATE <b>2-11-82</b>					

**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT  
CONTINUATION SHEET

FR SERIAL NO.

58310

CONTINUATION SHEET LETTER\*

A

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

☒ IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED ☐

18 FAIL, HOWEVER NO OUT OF SPEC SIGNAL WAS SENT  
TO ANY FOLLOW-ON CIRCUITRY AS THE LM108  
IS USED AS A  $\pm 13.5V$  TO  $-13.5V$  SOURCE. THE MAX  
SEEN IN THIS INSTANCE COULD HAVE BEEN BETWEEN  
 $\pm$  AND MINUS 12 V. CP-2-15-82

ORIGINAL PAGE IS  
OF POOR QUALITY



**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8311

1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER H5236</b>		2. GLA		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>11:00</b>		5. DATE OBSERVED <b>MO 10 DA 29 YR 81</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
NAME				PART NUMBER		S/N		MANUFACTURER	
7. SUBSYSTEM									
8. UNIT									
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>SERIAL AND REC/DEC</b> <b>50900</b> <b>202</b>									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP <b>50 °C</b> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MRS AT <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE <b>TEST FOR T12 RECORDS 5 FAILURES IN 2(10<sup>6</sup>) CYCLES AT 50 °C</b>									
15. TEST PROCEDURE <b>16389</b> <b>5.4</b> <b>160YTON</b> <b>22-13</b> <b>10/29/81</b>									
16. ORIGINATOR									
17. CONTINUATION SHEET USED									
18. VERIFICATION AND FAILURE ANALYSIS <b>SHIFT REGISTER U17 909940-1 (54165) OUTPUT AT HI TEMP (50 °C) APPEARS TO SHIFT INCORRECTLY AS DOCUMENTED IN ATTACHED TEST DATA RECORD</b>									
19. FAILED ITEM NAME AND PART NUMBER <b>SHIFT REGISTER (U17) 909940-1</b>									
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REMOVE AND REPLACE U17 (909940-1)</b> <b>RERUN 16389 ALSO PERFORM PENALTY TEST STR FOOT</b> <b>COPY ATTACHED</b>									
21. AUTHORIZATION <b>J A Sanchez</b> <b>22-13</b> <b>10-30-81</b>									
22. REWORK/RETEST ACTION TAKEN <b>U17 REPLACED STR FOOT SUCCESSFULLY COMPLETE 14055°C</b> <b>TEST SPEC 16389 PARA 5.1 RERAN. INITIALLY FAILED AT 50 °C</b> <b>AFTER ONE HOUR TESTING (2x10<sup>6</sup> CYCLES) SUBSEQUENT TESTS AT 50 °C</b> <b>FOR &gt; ONE HOUR AS SPECIFIED ON 5 NOV AND 6 NOV 1981 PASSED WITHOUT FAILURE.</b>									
23. QA WORK <b>115</b>									
24. QA SELECT <b>115</b>									
25. LIST ALL PARTS REPLACED									
PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
909940-1		U17							
26. PROBABLE DEFECT									
27. ANALYSIS NUMBER									
27. REWORK BY <b>H SANCHEZ</b> <b>22-74</b> <b>11/2</b> <b>J GUYTON</b> <b>22-73</b> <b>11/5 11/6</b>									
28. CONTINUATION SHEET USED									
29. CAUSE AND CORRECTIVE ACTION <b>REFER TO H5 236-7714 (COPY ATTACHED)</b> <b>DEFECTIVE U-17 PROBABLE</b> <b>RARE TEMP FAILURE SHOULD BE CHECKED AT</b> <b>INCOMING SCREENING</b>									
30. FB8 CLOSURE									
31. CONTINUATION SHEET USED									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>REFER TO H5 236-7714 (COPY ATTACHED)</b>									
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT									
34. FAILURE TYPE <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY									
35. RESPONSIBLE ENGINEER <b>J A Sanchez</b> <b>22-13</b> <b>11/10/81</b> <b>J GUYTON</b> <b>22-61</b> <b>8/11/11</b>									
36. SPACECRAFT SYSTEM ENGINEER									
37. PART NUMBER OR SUPPLIER									

**SANTA BARBARA RESEARCH CENTER**  
*A Subsidiary of Hughes Aircraft Company*  
**INTERNAL MEMORANDUM**

DATE: November 9, 1981  
REF: MS 236-7714  
FROM: J. A. Banach  
BLDG. B12 MAIL STA. S8  
EXT. 6203

The function of subject board is to receive serial data and process it as Discrete Digital TTL Commands; in addition, the card echoes back as telemetry serial input commands.

At high temperature (+50°C) following approximately one (1) hour of operation (> 1,000,000 cycles) the primary side experienced failures on two (2) separate occasions (consecutive days). Following replacement of U17 the same failure occurred once.

The echo telemetry did not meet specification, although the output commands were always correct. NOTE: Is condition - data sent was 5555. Command data outputted from board was 5555. Confirmed telemetry data received was AB55. Should be condition - Telemetry data received should be 5555. (refer to attached data sheet.)

Subsequently on two following days (including in excess of four (4) hours of additional high temperature testing) the failure mode could not be duplicated. (Engineering estimate of test cycles is > 10,000,000 cycles).

The board's telemetry is read in real time, such that this failure observation is unlikely to occur. (NOTE: Output commands are always observed to be correct in our testing of subject board.)

J. A. Banach  
J. A. Banach  
Head, Circuit Design, System Integration  
Thematic Mapper Program

L. O'Connell  
Reliability Manager  
Thematic Mapper Program

MONITOR

ORIGINAL PAGE IS  
OF POOR QUALITY

58311

T12

TEST PROGRAM NO. 12 - - - - - SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO IMC R.D.  
READS TELEMETRY & ACTUAL OUTPUT FOR VERIF.

ENTER OPERATOR DATA, YES OR NO : Y

ASSY. NO.: ----- 50900  
CARD NAME: ----- SERIAL MAG CMD REC/DEC  
SERIAL NO.: ----- 202  
DATE & TIME: ----- 29 OCT '81  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- OPERATIONAL TEMPERATURE 50 DEGREES C.

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)

5

RUN WITH CONSTANT DELAY, YES OR NO : YES  
PRINT VERIFICATION ERRORS, YES OR NO : YES

50 DEGREES C REACHED AT 10:15

DATA SENT WAS 5555 TELEMETRY IS AB55 ACTUAL OUTPUT IS 5555  
DATA SENT WAS 5555 TELEMETRY IS AB55 ACTUAL OUTPUT IS 5555  
DATA SENT WAS 5555 TELEMETRY IS AB55 ACTUAL OUTPUT IS 5555  
DATA SENT WAS 5555 TELEMETRY IS AB55 ACTUAL OUTPUT IS 5555  
DATA SENT WAS 5555 TELEMETRY IS AB55 ACTUAL OUTPUT IS 5555

CURRENT CYCLE COUNT IS : 0002079500

CURRENT ERROR COUNT IS : 0000000005

- - TESTING COMPLETED - -

DATE & TIME: ----- 29 OCT '81 11:15

PRI. OR RDT.: --- PRI

TEST OPERATOR: -- J GUYTON

OTHER TEST

CONDITIONS: ----- PRIMARY SIDE DATA CYCLING AT 50 DEGREE C  
TERMINATED AT 11:15

MONITOR

58311  
F1R  
29 OCT '81

S 8311

## TEST DATA RECORD SHEET

ORIGINAL PAGE IS  
OF POGR QUALITY

Assembly 50900 (PWS A10)

Step	Ref. Spec. Paragraph	Measurement	Observed Value	Requirement
1.	5.1.6.3	U1-emitter voltage	<u>+4.97</u>	+5.0 $\pm$ 0.2 vdc
2.	5.1.7.1	PRI current, nominal line	<u>87.6 mA</u>	$\leq$ 0.30 amperes
3.	5.1.7.2	PRI current, low line	<u>86.0 mA</u>	Nominal Value $\pm$ 10%
4.	5.1.7.3	PRI current, high line	<u>87.7 mA</u>	Nominal Value $\pm$ 10%
5.	5.1.8.2	U21-emitter voltage	<u>+5.10</u>	+5.0 $\pm$ 0.2 vdc
6.	5.1.9.1	RDT, current, nominal line	<u>91.8 mA</u>	$\leq$ 0.30 amperes
7.	5.1.9.2	RDT current, low line	<u>90.0 mA</u>	Nominal Value $\pm$ 10%
8.	5.1.9.3	RDT current, high line	<u>91.9 mA</u>	Nominal Value $\pm$ 10%

9. At the conclusion of testing, verify that all appropriate entries have been made on the terminal printout either from the terminal or in long hand by the test operator.

10. Verify that the original of the terminal printout has been reproduced for the purpose of maintaining a permanent record. (The thermal paper used by the terminals deteriorates with time.)

11. Signatures:

Test Engineer J. F. Ford Date 11-6-81  
 Design Engineer \_\_\_\_\_ Date \_\_\_\_\_  
 Quality Assurance 110 J. H. Brumbaugh Date 11-6-81

RETEST FOR F/R 8311 AFTER U17 REPLACEMENT

SIZE A	CODE IDENT NO 11323	NUMBER 16389
SCALE	REV E	SHEET 21

58311

ORIGINAL PAGE IS  
OF POOR QUALITY

T12

TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC R/D, AND  
READS TELEMETRY & ACTUAL OUTPUT FOR VERF.

ENTER OPERATOR DATA. YES OR NO : Y

ASSY. NO.: ----- 50900  
CARD NAME: ----- SER MAG CMD REC/DEC (A10)  
SERIAL NO.: ----- 202  
DATE & TIME: ----- 5 NOV '81  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- OPERATIONAL TEMP 50 DEGREES C AT 10:44  
(PRI)

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY. YES OR NO : Y  
PRINT VERIFICATION ERRORS. YES OR NO : Y

CURRENT CYCLE COUNT IS : 0001858252

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 5 NOV '81 11:44  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON *Delayed 5 Nov '81*  
OTHER TEST  
CONDITIONS: ----- TERMINATE DATA CYCLING AT 50 DEGREES C (PRI)

*Retest  
P/R 58311*

58311

ORIGINAL PAGE IS  
OF POOR QUALITY

MONITOR

T12

TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC R/D. AN  
READS TELEMETRY & ACTUAL OUTPUT FOR VERF.

ENTER OPERATOR DATA: YES OR NO : YES

ASSY. NO.: ----- 50900  
CARD NAME: ----- SER MAG CMD REC / DEC  
SERIAL NO.: ----- 202  
DATE & TIME: ----- 5 NOV '81 11:55  
PRI. OR RDT.: ----- RDT  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- OPERATIONAL TEMP (50 DEGREES C) REACHED AT 11:55

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY: YES OR NO : Y  
PRINT VERIFICATION ERRORS: YES OR NO : Y

CURRENT CYCLE COUNT IS : 0001910341

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 5 NOV '81 12:56  
PRI. OR RDT.: ----- RDT  
TEST OPERATOR: -- J GUYTON *J Guyton 5 NOV '81*  
OTHER TEST  
CONDITIONS: ----- TERMINATE REDUNDANT DATA CYCLING AT 50 DEGREES C.  
AT 12:56.

*Latest  
FIR 8311*

ORIGINAL PAGE IS  
OF POOR QUALITY

58311

MONITOR

T12

TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC R/D. AND  
READS TELEMETRY & ACTUAL OUTPUT FOR VERR.

ENTER OPERATOR DATA, YES OR NO : Y

ASSY. NO.: ----- 50900  
CARD NAME: ----- SER MAG CMD REC/DEC (A10)  
SERIAL NO.: ----- 202  
DATE & TIME: -----  
PRI. OP RDT.: --- RDT 5 NOV '81 13:07  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- OPERATIONAL TEMPERATURE 0 DEGREES C.

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY, YES OR NO : Y  
PRINT VERIFICATION ERRORS, YES OR NO : Y

0 DEGREE C. REACHED AT 13:14.

CURRENT CYCLE COUNT IS : 0002075128

CURRENT ERROR COUNT IS : 0003000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 5 NOV '81 14:14  
PRI. OP RDT.: --- RDT  
TEST OPERATOR: -- J GUYTON *J Guyton 5 NOV 81*  
OTHER TEST  
CONDITIONS: ----- RDT SIDE DATA CYCLING AT 0 DEGREE C  
TERMINATED AT 14:14

MONITOR

*Reset*  
*F/R 8311*

58311

ORIGINAL PAGE IS  
OF POOR QUALITY

T12

TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC P/D. AND  
READS TELEMETRY & ACTUAL OUTPUT FOR VERIF.

ENTER OPERATOR DATA. YES OR NO : Y

ASSY. NO.: ----- 50900  
CARD NAME: ----- SER MAG CMD REC/DEC  
SERIAL NO.: ----- 202  
DATE & TIME: ----- 5 NOV '81 14:19  
PRI. OR PDT.: --- PRI  
TEST OPERATOR: --- J GUYTON  
OTHER TEST  
CONDITIONS: ----- PRI SIDE DATA CYCLING AT 0 DEGREES C  
BUGUN AT 14:21

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY. YES OR NO : Y  
PRINT VERIFICATION ERRORS. YES OR NO : Y

CURRENT CYCLE COUNT IS : 0001839075

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 5 NOV '81 15:21  
PRI. OR PDT.: --- PRI  
TEST OPERATOR: --- J GUYTON *Stoped 5 Nov '81*  
OTHER TEST  
CONDITIONS: ----- PRIMARY SIDE 0 DEGREE DATA CYCLING  
TERMINATED AT 15:21.

MONITOR

*Retest  
F/K 58311*



S0311

ORIGINAL PAGE IS  
OF POOR QUALITY

MONITOR

T12

TEST PROGRAM NO. 12 - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC R/D. /  
READS TELEMETRY & ACTUAL OUTPUT FOR VEFF.

ENTER OPERATOR DATA: YES OR NO : YES

ASSY. NO.: ----- 50900  
CARD NAME: ----- SER MAG CMD REC/DEC (A10)  
SERIAL NO.: ----- 202  
DATE & TIME: ----- 5 NOV '81 16:22  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- PRI SIDE COLD START UP AT -25 DEGREEESC.

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY: YES OR NO : Y  
PRINT VERIFICATION ERRORS: YES OR NO : Y

CURRENT CYCLE COUNT IS : 0000045438

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 5 NOV '81 16:23  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON *J Guyton 5 NOV 81*  
OTHER TEST  
CONDITIONS: ----- TERMINATE PRI SIDE COLD START UP.

*Retest  
FIR 8311*

ORIGINAL PAGE IS  
OF POOR QUALITY

58311

T12  
TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO CMD R/D. AND  
READS TELEMETRY & ACTUAL OUTPUT FOR VERF.

ENTER OPERATOR DATA: YES OR NO : Y

ASSY. NO.: ----- 50900  
CARD NAME: ----- SER MAG CMD REC/DEC (A10)  
SERIAL NO.: ----- 202  
DATE & TIME: ----- 5 NOV '81 17:23  
PRI. OR RDT.: --- RDT  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- RDT SIDE COLD STARTUP AT -25 DEGREES C.

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY: YES OR NO : Y  
PRINT VERIFICATION ERRORS: YES OR NO : Y

CURRENT CYCLE COUNT IS : 0000064979

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 5 NOV '81 17:25  
PRI. OR RDT.: --- RDT  
TEST OPERATOR: -- J GUYTON J Guyton 5 Nov '81  
OTHER TEST  
CONDITIONS: ----- TERMINATE RDT SIDE COLD STARTUP.

MONITOR

Restest  
F/R 8311

ORIGINAL PAGE IS  
OF POOR QUALITY

58311

T12  
TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC R/D. A  
READS TELEMETRY & ACTUAL OUTPUT FOR VERF.

ENTER OPERATOR DATA. YES OR NO : Y

ASSY. NO.: ----- 50900  
CARD NAME: ----- CER MAG CMD REC/DEC (A10)  
SERIAL NO.: ----- 202  
DATE & TIME: ----- ~~5 NOV '81~~ 09:30 6 NOV '81 H Guyton  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- OPERATIONAL TEMP 50 DEGREES C REACHED AT  
09:50

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY, YES OR NO : Y  
PRINT VERIFICATION ERRORS, YES OR NO : Y

CURRENT CYCLE COUNT IS : 0002151151

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 6 NOV '81 10:54  
PRI. OR RDT.: --- PRI  
TEST OPERATOR: -- J GUYTON  
OTHER TEST  
CONDITIONS: ----- TERMINATE PRI SIDE DATA CYCLING AT 50 DEGREES C.

MONITOR

Retest  
FIRE 311

58311

STR NO F-001  
PG 1 OF 1

SPECIAL TEST REQUEST

ORIGINAL PAGE IS  
OF POOR QUALITY

TITLE SERIAL MAGNITUDE COMMAND BOARD 55°C PENALTY ORIGINATOR J. BANACH  
TEST

INSTRUMENT/MODEL TM/FLT 50900/SIN 201 MAJOR TEST PHASE ASSEMBLY ACCEPTANCE TEST

APPLICABLE DOC. 16389 APPROX. TEST TIME 2 HRS.

PURPOSE OF TEST: PERFORM ADDITIONAL PENALTY TESTING AT 55°C FOR 50900 SIN 201  
BOARD IN RESPONSE TO FAILURE REPORT 58311. PREVIOUS PENALTY TESTING AT  
50°C AND DOCUMENTED IN HS236-7714 WAS UNACCEPTABLE TO NASA OFFICER. QAR

TEST CONFIGURATION: BOARD ASSEMBLY TEST CONFIGURATION AS DEFINED IN  
TEST PROCEDURE 16389 PARA 5.4.1.2

TEST PROCEDURE: PERFORM TEST PROCEDURE 16389 PARA 5.4.1.2, WITH EXCEPTION  
THAT IT IS DONE AT 55°C INSTEAD OF SPECIFIED 50°C

TEST SUCCESSFULLY COMPLETED. DATA ATTACHED.

Product Effectiveness J. Banach 11/17/81

TEST DIRECTOR J. Banach DATE: 11/17/81

SYST. ENGIN. J. Banach DATE: 11/17/81

(USE CONTINUATION SHEETS IF REQUIRED)

58211

ORIGINAL PAGE IS  
OF POOR QUALITY

MONITOR

T12

TEST PROGRAM NO. 12 - - - - > SERIAL MAGNITUDE CMD AUTO DATA TEST -  
SENDS ALTERNATING BIT PATTERN TO SMC R/D, AND  
READS TELEMETRY & ACTUAL OUTPUT FOR VERF.

ENTER OPERATOR DATA, YES OR NO : Y

ASSY. NO.: ----- 50900

CARD NAME: ----- SER MAG CMD REC/DEC (A10)

SERIAL NO.: ----- 202

DATE & TIME: ----- 17 NOV '81 16:00

PRI. OR RDT.: --- PRI

TEST OPERATOR: -- J GUYTON

OTHER TEST

CONDITIONS: ----- SPECIAL TEST REQUEST F-001, PRI SIDE DATA CYCLING AT  
55 DEGREES C. (16389 PAR.5.4.1.2) RETEST.

TO START TEST EXECUTION  
PRESS "G" KEY.

(TO TERMINATE TEST PRESS "ESC" KEY.)  
G

RUN WITH CONSTANT DELAY, YES OR NO : Y  
PRINT VERIFICATION ERRORS, YES OR NO : Y

55 DEGREES C REACHED AT 16:10

CURRENT CYCLE COUNT IS : 0002021729

CURRENT ERROR COUNT IS : 0000000000

- - TESTING COMPLETED - -

DATE & TIME: ----- 17 NOV '81 17:10

PRI. OR RDT.: --- PRI

TEST OPERATOR: -- J GUYTON

OTHER TEST

CONDITIONS: ----- TERMINATE SPECIAL TEST F-001, PRI SIDE DATA CYCLING AT  
55 DEGREES C.

MONITOR

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8312

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER</b>	2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>13:00</b>	5. DATE OBSERVED <b>MO 10 DA 30 YR 81</b>
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM	<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
	EQUIPMENT IDENTIFICATION:				
	7. SUBSYSTEM		PART NUMBER		S/N
	8. UNIT				MANUFACTURER
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<b>VENTILATED REG (AIR)</b>		<b>50948</b>
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				<b>201</b>
	11. OTHER				
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input type="checkbox"/> TEMP AXIS FOR MIN TYPE
14. DESCRIPTION OF FAILURE <b>TEST REG 8 FAILS 'BOARD F OUTPUT - RDT'</b>					
ENGINEERING EVALUATION	15. TEST PROCEDURE <b>16422</b>		16. PARA <b>5.1</b>	17. ORIGINATOR <b>GUPTON</b>	18. ORG <b>22-13</b>
	19. VERIFICATION AND FAILURE ANALYSIS <b>R108 IS SHORT-CIRCUITED BY A FUSE (F108) AT R108. NO OVERSTRESS OCCURRED.</b>		19. FAILED ITEM NAME AND PART NUMBER <b>DEF HS 236-7745 (COPY ATTACHED)</b>		
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE				
	<b>REMOVE FUSE DEFECT (BRIDGE) AT R108. RETEST PER 16422</b>				
	21. AUTHORIZATION <b>GUPTON</b>		22. ORG <b>22-13</b>	23. DATE <b>11/30/81</b>	24. CONTINUATION SHEET USED <input type="checkbox"/>
	25. REWORK/RETEST ACTION TAKEN <b>BRIDGE AT R108 REMOVED</b>		26. CONTINUATION SHEET USED <input type="checkbox"/>		
	<b>RETESTED PER TEST PROCEDURE 16422 PARA 5.1</b>		27. CONTINUATION SHEET USED <input type="checkbox"/>		
	28. LIST ALL PARTS REPLACED PART NUMBER		CXT SYM	PART LOT NUMBER	DATE CODE
	MANUFACTURER		PROBABLE DEFECT		ANALYSIS NUMBER
	MANUFACTURING AND TEST	27. REWORK BY <b>L. TORRES</b>		28. ORG <b>22-13</b>	29. DATE <b>30 OCT 1981</b>
31. CAUSE AND CORRECTIVE ACTION <b>BAD PRINTED WIRE BOARD FABRICATION CAUSED PROBLEM. DE 11/23/81</b>		32. CONTINUATION SHEET USED <input type="checkbox"/>			
33. FAB CLOSURE <b>11/17/81</b>					
34. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>11/17/81 (COPY ATTACHED)</b>					
35. BASIC CAUSE OF VERIFIED FAILURE <input checked="" type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
36. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
37. RESPONSIBLE ENGINEER <b>J. GUYTON</b>		38. ORG <b>22-13</b>	39. DATE <b>4 NOV 1980</b>	40. CONTINUATION SHEET USED <input type="checkbox"/>	
41. RELIABILITY <b>51-41</b>		42. ORG <b>51-41</b>	43. DATE <b>11-17-81</b>	44. CONTINUATION SHEET USED <input type="checkbox"/>	
45. CUSTOMER OR SUPPLIER <b>11/17/81</b>					
46. CONTINUATION SHEET USED <input type="checkbox"/>					

**HUGHES**

HUGHES AIRCRAFT COMPANY

SPACE AND COMMUNICATION GROUP  
EQUIPMENT CHECKOUT  
FAILURE REPORT  
**CONTINUATION SHEET**

ORIGINAL PAGE IS  
OF POOR QUALITY

58312 CONT. SHEET  
FR SERIAL NO. LETTER\*

\* LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED ☐

30 THE QUALITY INSPECTION SUPERVISOR JOYCE M LIPSCOMBE  
WAS CONTACTED BY W D ADAMS TM PROGRAM MANAGER AND  
INFORMED HER OF THE SHORT PROBLEM ON THE CIRCUIT BOARD  
USED ON ASSEMBLY 50940 S/U SOL. SHE HAS CONTACTED  
MANUFACTURING AND QUALITY PERSONNEL AND TOLD THEM TO  
USE MORE CARE DURING INSPECTION AND MANUFACTURING OF  
FUTURE BOARDS TO PREVENT RE-~~PE~~ RECURRENCE  
OF THIS PROBLEM.

W D ADAMS  
12-2-81

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8313

1. PROGRAM NAME AND NUMBER <i>The Metric Mapper HS 236</i>		2. GLA <i>GLA</i>	3. MODEL <i>FLT</i>	4. TIME OBSERVED <i>10:00</i>	5. DATE OBSERVED <i>MG 11 DA 4 YR 81</i>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <i>Failed para 33.2.3 SBRG 16234 (AR-2 &amp; AR-5 HAVE EXCESSIVE OFFSET)</i>					
15. TEST PROCEDURE <i>16234</i>					
16. ORIGINATOR <i>33-23 R. K. L. G. S. S.</i>					
17. CONTINUATION SHEET USED <i>11-4-81</i>					
18. VERIFICATION AND FAILURE ANALYSIS <i>JUMPERS ACROSS DESIGNATED R35, R59, and R77 pads were missing per blueprint 50926 and stressed AR2, AR5, and AR8. (908961-4). A LATER REVIEW OF THE EFFECTS OF MISWIRING DISCREPANCY SHOW THAT NO STRESSER</i>					
19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>Jumpers per blueprint. Remove and replace AR2, AR5 &amp; AR8. RETEST PER 3.3.2.3</i>					
20. AUTHORIZATION <i>J. A. Sanchez</i>					
21. REWORK/RETEST ACTION TAKEN <i>JUMPERS INSTALLED AR2, AR5, AR8 REMOVED AND REPLACED</i>					
22. CONTINUATION SHEET USED <i>172</i>					
23. QA RETEST					
24. LIST ALL PARTS REPLACED					
25. REWORK BY <i>H. Sanchez</i>					
26. RETESTED BY <i>R. K. L. G. S. S.</i>					
27. CONTINUATION SHEET USED <i>22-13 1-6-82</i>					
28. CAUSE AND CORRECTIVE ACTION <i>OPERATOR AND PA ERROR - JUMPERS CLEARLY CALLED OUT ON BIP SHEET 3. SUPERVISORS CAUTIONED.</i>					
29. FRG CLOSURE					
30. CONTINUATION SHEET USED					
31. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
32. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING/LEADOR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR/LOUT <input type="checkbox"/> UNKNOWN					
33. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
34. RESPONSIBLE ENGINEER <i>J. A. Sanchez</i>					
35. DATE <i>1-4-82</i>					
36. SPACECRAFT SYSTEM ENGINEER <i>J. A. Sanchez</i>					
37. DATE <i>2-10-82</i>					
38. SPACECRAFT SYSTEM ENGINEER <i>J. A. Sanchez</i>					
39. DATE <i>2-10-82</i>					



**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT  
CONTINUATION SHEET**

FR SERIAL NO.

**SB313**

CONTINUATION SHEET LETTER

**A**

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

☐ IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN. DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED ☐

18 WERE EXCESSIVE. THE MISSING JUMPER WIRES  
WERE AT THE LM 10B OUTPUTS AND PROVIDED  
A NO LOAD CONDITION TO THE DEVICES. A LABORATORY  
CHECK OF A REMOVED AMPLIFIER (A2B) SHOWED NO  
VARIATION FROM A LABORATORY SAMPLE WHEN TESTED  
ON A CURVE TRACER - UP 2-16-82

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
25, DEQUING, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8314**

1. PROGRAM NAME AND NUMBER <b>THEMATIC ANALYST H5236</b>		2. GLA	3. MODEL <b>RT</b>	4. TIME OBSERVED <b>09:37:01</b>	5. DATE OBSERVED <b>MO 11 DAY 4 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:		NAME	PART NUMBER	S/N	MANUFACTURER
7. SUBSYSTEM					
8. UNIT					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>VERIFICATION RESISTOR 50948</b>				<b>201</b>	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RR <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE					
14. DESCRIPTION OF FAILURE <b>FAILS TO DEVELOP PROPER SIGNAL AT U3-6 JUNE 81</b> <b>BAD SOLDER CONNECTION AT U3-14.</b>					
15. TEST PROCEDURE <b>16422</b>		16. PARA <b>51-64</b>	17. ORIGINATOR <b>GUYTON</b>	18. DATE <b>11/4/81</b>	19. CONTINUATION <input type="checkbox"/> SHEET USED
20. VERIFICATION AND FAILURE ANALYSIS <b>BAD SOLDER JOINT.</b> <b>NO OVERSTRESS OCCURRED.</b>					
21. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>RESOLDER U3-14</b>		22. FAILED ITEM NAME AND PART NUMBER			
23. AUTHORIZATION <b>Base Flight</b>		24. ORG <b>22-13</b>	25. DATE <b>11/4/81</b>	26. CONTINUATION <input type="checkbox"/> SHEET USED	
27. REWORK/RETEST ACTION TAKEN <b>U3 PIN 14 RESOLDED.</b> <b>RETESTED PER TEST PROCEDURE 16422 PARA 5.1</b> <b>(SEE ATTACHED)</b>		28. CONTINUATION <input type="checkbox"/> SHEET USED			
29. LIST ALL PARTS REPLACED PART NUMBER		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
30. PROBABLE DEFECT		ANALYSIS NUMBER			
31. Rework by <b>H. SANCHEZ</b>		ORG <b>22-74</b>	DATE <b>4 NOV 1981</b>	32. Retested by <b>J. GUYTON</b>	ORG <b>22-13</b>
33. Cause and corrective action <b>BAD WORKMANSHIP, missed inspection point on back of popin inspection. The responsible inspector has been notified of this error and contacted to special quality case.</b> <b>Inspector ship [signature]</b>		DATE <b>4 NOV 1981</b>	34. CONTINUATION <input type="checkbox"/> SHEET USED		
35. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>NONE</b>		36. CONTINUATION <input type="checkbox"/> SHEET USED			
37. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		38. UNKNOWN <input type="checkbox"/> DEFECT CODE			
39. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		40. UNKNOWN <input type="checkbox"/> NO FAILURE		41. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
42. RESPONSIBLE ENGINEER <b>Ed Barash</b>		ORG <b>22-13</b>	DATE <b>NOV 4, 1981</b>	43. SPACECRAFT SYSTEM ENGINEER <b>Engel</b>	
44. RELIABILITY <b>Ed Barash</b>		ORG <b>55-41</b>	DATE <b>11-18-1981</b>	45. CUSTOMER OR SUPPLIER <b>Engel</b>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8315**

1. PROGRAM NAME AND NUMBER <b>TM</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>3:00</b>	5. DATE OBSERVED <b>MO 11 DA 6 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT <b>T-1 Sealing - Facelint - Lamp Sequence</b> <b>51402</b> <b>201</b>					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>- Buff 1 (IAP)</b>					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>The All Lamps on LED failed to turn on at the proper time in the call lamp sequence</b>					
15. TEST PROCEDURE <b>162P2</b> PARA <b>4.3.2</b> 16. ORIGINATOR <b>Joe Kleeburg</b> ORG <b>22-13</b> DATE <b>11/6/81</b> 17. CONTINUATION <input type="checkbox"/> SHEET USED					
18. VERIFICATION AND FAILURE ANALYSIS <b>Base lead of Q10 is not making electrical contact with pad on the circuit board.</b>					
19. FAILED ITEM NAME AND PART NUMBER					
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Resolder Q10 Base pad lead to circuit trace per MRCO 29842R</b> <b>Retest per TP 16282 Para 4.3.2</b>					
21. AUTHORIZATION <b>J.A. Bonach</b> ORG <b>22-13</b> DATE <b>11-6-81</b> 22. CONTINUATION <input type="checkbox"/> SHEET USED					
23. REWORK/RETEST ACTION TAKEN <b>Jumper lead soldered per MRCO 29842R</b> <b>Retested per TP 16282 Para 4.3.2 - (SEE ATTACHED)</b>					
24. CONTINUATION <input checked="" type="checkbox"/> SHEET USED					
25. JUST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYST NUMBER					
26. REWORK BY <b>H. SANCHEZ</b> ORG <b>22-74</b> DATE <b>4-9-81</b> 27. RETESTED BY <b>J. KLEEBOURG</b> ORG <b>22-13</b> DATE <b>1-11-81</b> 28. CONTINUATION <input type="checkbox"/> SHEET USED					
29. CAUSE AND CORRECTIVE ACTION <b>IN BONDING Q10 Base pad the trace contact was damaged and intermittent. - NO OTSR COMPONENTS STRESSED</b> <b>Greater care in El Segundo bonding operation is needed.</b> <b>MR OTTO NORDHOFF AND MR MILLER THE SUPERVISOR OF THE QUALITY ASSURANCE HAVE BEEN ADVISED OF THIS DISCREPANCY BY VENDOR AND MR. MILLER WILL BE INSURE THIS DISCREPANCY DOES NOT REPEAT ITSELF TO SAME</b> <b>W.D. [Signature] 11-18-81</b>					
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
31. CONTINUATION <input type="checkbox"/> SHEET USED					
32. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
33. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE 34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
35. RESPONSIBLE ENGINEER <b>J.A. Bonach</b> ORG <b>22-13</b> DATE <b>11-17-81</b> 36. AIRCRAFT SYSTEM ENGINEER <b>William S. [Signature]</b> ORG <b>22-41</b> DATE <b>11/18/81</b>					
37. RELIABILITY <b>Da [Signature]</b> ORG <b>51-41</b> DATE <b>11-18-81</b> 38. CUSTOMER OR SUPPLIER <b>610</b>					

# HUGHES

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

## SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

ORIGINAL PAGE IS  
OF POOR QUALITY

S 8316

1 PROGRAM NAME AND NUMBER <i>Thermal Analyzer</i> <i>HS236</i>		2 GLA	3 MODEL <i>RT</i>	4 TIME OBSERVED <i>14:10</i>	5 DATE OBSERVED <i>MO 11 DA 9 YR 81</i>
6 HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7 SUBSYSTEM		NAME		PART NUMBER	S/N
8 UNIT					
9 <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input checked="" type="checkbox"/> MODULE					
10 <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<i>MACTE DETECTOR</i>		<i>5175</i>	<i>102</i>
11 OTHER					
12 TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13 ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE					
14 DESCRIPTION OF FAILURE <i>'CROSSTALK' AR2-8 TO AR2-10. ON THE AR2 PIN 9 OUTPUT, THE HI LEVEL OF 4V HAS A 25VPP WAVEFORM RIDING AT THE CLOCK FREQUENCY. NOTE THIS TTL HI LEVEL SIGNAL STILL PROVIDES A NOISE MARGIN GREATER THAN 1.5V ABOVE THE MINIMUM 2.0V TTL HI REQUIRED BY RECEIVING IC'S.</i>					
15 TEST PROCEDURE <i>16423</i>		16 PARA <i>5.3.5.4</i>	17 ORIGINATOR <i>GUYTON</i>	18 DATE <i>12-13</i>	19 CONTINUATION SHEET USED <input type="checkbox"/>
10. VERIFICATION AND FAILURE ANALYSIS					
<i>SUSPECT FAULTY CHIP AR-2, DATA LINE REZ (AS7820)</i>					
13. FAILED ITEM NAME AND PART NUMBER <i>AR-2 (909992-1)</i>					
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <i>REMOVE AND REPLACE AR-2</i>					
<i>RETEST PER TP 16423 PARA 5.3.5.4</i>					
21. AUTHORIZATION <i>J.A. Bonach</i>		18 ORG <i>22-13</i>	19 DATE <i>11-9-81</i>	22 CONTINUATION SHEET USED <input type="checkbox"/>	
23. Rework/Retest Action Taken <i>SEE DATA SHEET OF 11-10-81, SORC 16423, &amp; WAVEFORM PHOTOS</i> <i>SEE AHR 5175, SUPPL 13, DP 403, 404 FOR REWORK OF AR-2</i>					
24. LIST ALL PARTS REPLACED		CAT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER
PART NUMBER					
27. Rework By <i>L. TORRES</i>		ORG <i>22-73</i>	DATE <i>11/10/81</i>	28. Retested By <i>J. GUYTON</i>	ORG <i>22-73</i> DATE <i>11/19/81</i>
29. CAUSE AND CORRECTIVE ACTION <i>EVEN THOUGH THE CHIP WAS WITHIN THE ALLOWABLE PARAMETERS, THE REA WAS HOPING TO IMPROVE THIS PARAMETER BY REPLACING THE CHIP.</i> <i>IN ESSENCE THIS F.R. WAS OPEN IN ERROR. THERE WAS NO "FAULTY" CHIP. UNNECESSARY REPLACEMENT OF CHIP.</i>					
		31. CONTINUATION SHEET USED <input type="checkbox"/>			
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT					
35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> SECONDARY <input type="checkbox"/> NO FAILURE <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR					
37. RESPONSIBLE ENGINEER <i>J.A. Bonach</i>		ORG <i>22-13</i>	DATE <i>12-7-81</i>	38. SPECIALIST SYSTEM ENGINEER <i>J.A. Bonach</i>	
39. RELIABILITY <i>See Frank</i>		ORG <i>51-41</i>	DATE <i>12-7-81</i>	40. ESTIMATOR OR SUPPLIER <i>10/2/81</i>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8320**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>T.M. VOII</b>		2. GLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>3:30 p.m.</b>	5. DATE OBSERVED <b>MO 9 DA 24 YR 81</b>			
	3. MINORWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART						
	EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER								
	7. SUBSYSTEM								
	8. UNIT <b>ELECTRONIC MODULE</b>								
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <b>BAND 2 POST AMP</b>								
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD								
	11. OTHER								
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS								
	<input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM								
ENGINEERING EVALUATION	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP <b>15. C</b> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER								
	<input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE								
	14. DESCRIPTION OF FAILURE <b>OUTPUT LOW OF CHANNEL 11 (HYBRID U4) SHORT CIRCUITED (~8 OHMS) TO SIGNAL GROUND.</b>								
	15. TEST PROCEDURE <b>16597</b>		16. PARA <b>4.5</b>	18. ORIGINATOR <b>N. C. JAVISON</b>	19. ORG <b>223</b>	20. DATE <b>9-25-81</b>	17. CONTINUATION SHEET USED <input type="checkbox"/>		
	19. VERIFICATION AND FAILURE ANALYSIS <b>SOLDER SPLASH FOUND BETWEEN PIN 28 (O.L.) OF U4 AND THE CASE (SIGNAL GROUND). SOLDER SPLASH WAS REMOVED AND NORMAL BEHAVIOR WAS OBSERVED.</b>								
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest Not Required Because <b>NO PARTS FAILED</b>								
	21. AUTHORIZATION								
	22. REWORK/RETEST ACTION TAKEN <b>SOLDER SPLASH WAS REMOVED. PART FUNCTIONS PROPERLY. STRESS ANALYSIS HS236-704 SHOWS THAT NO OVERSTRESS OCCURRED.</b>								
	23. LIST ALL PARTS REPLACED PART NUMBER CXT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER								
	<b>NONE</b>								
MANUFACTURING AND TEST	27. REWORK BY		ORG	DATE	28. RETESTED BY		ORG	DATE	29. CONTINUATION SHEET USED <input type="checkbox"/>
	30. CAUSE AND CORRECTIVE ACTION <b>SOLDER SPLASH INTRODUCED WHEN MOVING SELECT RESISTORS FROM STANDOFFS TO BOARD. NO OVERSTRESS OCCURRED. MANUFACTURING PERSONNEL HAVE BEEN REMONSTRATED TO USE CAUTION WHEN SOLDERING COMPONENTS. Inspection personnel will continue to check for this when inspecting subunits and review all adjustment steps.</b>								
	31. FRB CLOSURE								
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>NONE REQ'D</b>								
	33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE								
	<input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING								
	<input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WEAR-OUT								
	34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY								
	35. SIGNATURE OF ENGINEER <b>J. B. B...</b>								
	36. SIGNATURE OF SYSTEM ENGINEER <b>J. B. B...</b>								
ENGINEERING/RELIABILITY	37. RELIABILITY <b>J. Hunter</b>		ORG <b>51-11</b>	DATE <b>11-02-81</b>	38. CUSTOMER OR SUPPLIER <b>4-781</b>		DATE <b>11/4/81</b>	39. CONTINUATION SHEET USED <input type="checkbox"/>	

# HUGHES

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

PER P.N. 50797 LPER -  
SUPP. 2  
SPACE AND COMMUNICATIONS GROUP  
FAILURE REPORT

ORIGINAL PAGE IS  
OF POOR QUALITY

S 8321

1. PROGRAM NAME AND NUMBER T.M. VO11		2. GLA		3. MODEL FLIGHT		4. TIME OBSERVED 3:15		5. DATE OBSERVED MO 10 DA 4 YR 81	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MECAM <input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		BOARD 4 1ST AMP BOARD		50904-4		201		SERC	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MECAM <input type="checkbox"/> CARD									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM		<input type="checkbox"/> LAUNCH OPERATIONS	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED		<input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMP 15°C AUX FOR		<input type="checkbox"/> THERMAL VAC MRS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE		AT 52 KHZ FREQUENCY RESPONSE WAS: -2.24 dB (SHOULD BE -2.50 TO -3.01.) CH. 6 ONLY.							
15. TEST PROCEDURE		16597		PARA 4.6		18. OPERATOR A. L. DANISON		19. DATE 2243 10-5-81	
19. VERIFICATION AND FAILURE ANALYSIS									
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		Since the wideband noise at 2.1 MHz is well within the spec of $\pm 2.4$ dB, it is not considered a failure which affects the receiver. No over-stress of any components.							
21. AUTHORIZATION		22. DATE		23. CONTINUATION SHEET USED					
23. REWORK/RETEST ACTION TAKEN				24. QA REWORK					
25. QA RETEST									
26. LIST ALL PARTS REPLACED		CMT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
27. REWORK BY		OSG		DATE		28. RETESTED BY		OSG	
29. CAUSE AND CORRECTIVE ACTION		Workmanship during selection of board and rollout operators. Must be to operator.		Waiver 10-120 attached.		30. FRG CLOSURE			
31. CONTINUATION: SHEET USED									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		EFFECTIVE - SN 201 FLIGHT UNIT WAIVER - 120 (COPY ATTACHED)							
34. BASIC CAUSE OF VERIFIED FAILURE		<input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP		<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	
35. FAILURE TYPE		<input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION		<input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
37. RESPONSIBLE ENGINEER		ORG		DATE		38. SPACECRAFT SYSTEM ENGINEER		ORG	
39. RELIABILITY		51-21		11/16/81		40. CUSTOMER OR SUPPLIER		DATE	

Program Instruction 010

ORIGINAL PAGE IS  
OF POOR QUALITY 58321REQUEST FOR DEVIATION/WAIVER  
(SEE MIL-STD-883C OR 883D FOR INSTRUCTIONS)

DATE PREPARED

PROCURING ACTIVITY NO.

1. ORIGINATOR NAME AND ADDRESS David M. Randall SBRC, 75 Coromar Dr., Coleta, Ca. 93117				2. <input type="checkbox"/> DEVIATION <input checked="" type="checkbox"/> WAIVER	
				3. <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL	
4. DESIGNATION FOR DEVIATION/WAIVER				5. BASE LINE AFFECTED	
6. MODEL/TYPE F	7. WFR. CODE 11323	8. SYS. DESIG. TM	9. DEV/BAIV. NO. W-120	<input checked="" type="checkbox"/> PLAC- TIONAL	<input type="checkbox"/> ELIG- CATED
				<input type="checkbox"/> PROD- UCT	
11. SPECIFICATIONS AFFECTED-TEST PLAN				12. OTHER SYSTEMS/CONFIG- URATION ITEMS AFFECTED	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
13. DRAWINGS AFFECTED					
14. CONTRACT NO. & LINE ITEM				15. NAS 5-24200	
16. TITLE OF DEVIATION/WAIVER Permission to use Band 4 Postamp SN 201					
17. CONFIGURATION ITEM NOMENCLATURE Radiometer				18. CD NO. II	
19. NAME OF PART OR LARGEST ASSEMBLY AFFECTED Band 4 Postamplifier				20. PART NO. OR TYPE DESIG. 50904-4	
21. LOT NO. 201				22. QTY 1	
23. EFFECT ON COST/PRICE None if approved.				24. EFFECT ON DELIVERY SCHEDULE None if approved.	
25. EFFECT ON INTEGRATED LOGISTIC SUPPORT, INTERFACE, ETC. None				26. REQUIRING DEVIATION/WAIVER <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
27. DESCRIPTION OF DEVIATION/WAIVER					

Permission to use Band 4 Postamp with Ch 6 frequency response -2.24 dB down vs a specification of -2.5 to -3.0 dB down at 52KHZ.

28. NEED FOR DEVIATION/WAIVER

This parameter is in violation of a unit level specification; not a system specification. Rework to the Postamp PWB may result in a lifted pad. The Band 4 Band Level Assy has been bonded into LED bracket and can no longer be cooled to allow reselelection of resistors. Rework is not considered necessary since Wide Band Noise of Channel 6 is 2.1pA.

REA <i>[Signature]</i> 11/14/81	SYS ENGR <i>[Signature]</i> 11/17/81	RE <i>[Signature]</i>
		QA <i>[Signature]</i> 11/18/81
		PE <i>[Signature]</i> 11-18-81
29. PRODUCTION EFFECTIVITY BY SERIAL NUMBER		
30. APPROVAL/DISAPPROVAL		
31. APPROVAL RECOMMENDED <input type="checkbox"/> APPROVED <input checked="" type="checkbox"/> DISAPPROVED <input type="checkbox"/>		
32. GOVERNMENT ACTIVITY		
NASA GSFC		
DD FORM 1694		

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAMAIN AHR 50904-43  
OPN. 1300  
SPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8325**

1. PROGRAM NAME AND NUMBER <b>U011 TM</b>		2. GLA	3. MODEL <b>FLIGHT FIRST SHFT</b>	4. TIME OBSERVED	5. DATE OBSERVED <b>MO 08 DA 25 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT <b>Electronics Module</b>					
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<b>BANB 3 Post-Ann</b>		<b>50904-43</b>	<b>201</b>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					<b>SBRL</b>
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> ENC/R/R		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> EXTENDED AXIS FOR <b>15°C</b> <input type="checkbox"/> THERMAL VAC MIN TYPE <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <b>CH. 1, 7, 8, 13, 15 D.C. OFFSET OUT OF SPEC SHOULD ± 1.0V IS CH. 1 - 1.1V, CH. 7 - 1.2V, CH. 8 + 1.2V, CH. 13 - 1.5V CH. 15 - 1.3V</b>					
15. TEST PROCEDURE <b>16597</b>		16. PARA <b>4.4</b>	17. ORIGINATOR <b>C.R. Lane</b>	18. ORG <b>2243</b>	19. DATE <b>08-25-81</b>
20. VERIFICATION AND FAILURE ANALYSIS <b>Channels 1, 7, 8, 13, 15 apparently out of spec due to post-gain resistors being out during testing</b>					
21. FAILED ITEM NAME AND PART NUMBER <b>N/A</b>					
22. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> Rework/Retest NOT required because <b>Channels 1, 7, 8, 13, 15 actually meet spec as tested with post-gain resistors out. Refer to E.C.R. # TN2512/01R1 of spec 16597 Rev J for allowable D.C. voltage offsets. (See attached for voltage offset calculations.)</b>					
23. AUTHORIZATION ORG <b>2243</b> DATE <b>08-25-81</b>					
24. CONTINUATION <input type="checkbox"/> SHEET USED					
25. Rework/Retest ACTION TAKEN <b>None Required. No over-stressing of components occurred.</b>					
26. QA Rework					
27. QA Retest					
28. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER					
<b>None</b>					
29. Rework by ORG <b>2243</b> DATE <b>08-25-81</b>					
30. Retested by ORG <b>2243</b> DATE <b>08-25-81</b>					
31. CONTINUATION <input type="checkbox"/> SHEET USED					
32. CAUSE AND CORRECTIVE ACTION <b>Spec changed per E.C.R. #2512/01R1 to define role of post-gain resistors in D.C. offset voltage measurements. New spec limits are based on calculations that take gain into consideration.</b>					
33. FRG CLOSURE					
34. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ECR # TN2512/01R1 to spec 16597</b>					
35. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP					
36. FAILURE TYPE <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE					
37. RESPONSIBLE ENGINEER <b>C.R. Lane</b>					
38. FAILURE CLASSIFICATION <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> CRITICAL					
39. SPACECRAFT SYSTEM ENGINEER <b>C.R. Lane</b>					
40. DATE <b>22-61 8/11/81</b>					
41. DATE <b>11/13/81</b>					
42. DATE <b>11/13/81</b>					



**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8326**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>U011 TM</b>		2. GLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>FIRST MIPT</b>	5. DATE OBSERVED <b>MO 10 DA 04 YR 81</b>														
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART														
	EQUIPMENT IDENTIFICATION:																			
	7. SUBSYSTEM		NAME		PART NUMBER	S/N	MANUFACTURER													
ENGINEERING EVALUATION	8. UNIT <b>Electronics Module</b>																			
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<b>BAND 4 Post Amp</b>		<b>50904-34</b>	<b>201</b>	<b>SBRC</b>													
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD																			
	11. OTHER																			
ENGINEERING AND TEST	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS															
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	15. THERM <b>15 °C</b> AXIS FOR MIN TYPE		THERMAL VAC HRS AT <input type="checkbox"/> OTHER														
	14. DESCRIPTION OF FAILURE <b>CH. 6 &amp; 8 OUT OF SPEC OFFSET VOLTAGE SHOULD BE ± 1.0V. IS CH 6 +1.3V, CH. 8 +1.5V</b>																			
	16. TEST PROCEDURE <b>16597</b>		PARA <b>4.4</b>	18. ORIGINATOR <b>C. R. Lee</b>		ORG <b>2213</b>	DATE <b>10-04-81</b>	17. CONTINUATION SHEET USED <input type="checkbox"/>												
MANUFACTURING AND TEST	19. VERIFICATION AND FAILURE ANALYSIS <b>Channels 6, 8 apparently out of spec due to post-gain resistors being out during test.</b>																			
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Channels 6, 8 actually meet spec as tested with post-gain resistors out. Refer to ECR# TM2512/01R1 of spec 16597 Rev J for allowable voltage offsets. (See attached for allowable voltage offset calculations.)</b>																			
	21. REWORK/RETEST ACTION TAKEN <b>None Required. No over-stressing of components occurred.</b>																			
	22. LIST ALL PARTS REPLACED <table border="1"><thead><tr><th>PART NUMBER</th><th>CKT SYM</th><th>PART LOT NUMBER</th><th>DATE CODE</th><th>MANUFACTURER</th><th>PROBABLE DEFECT</th><th>ANALYSIS NUMBER</th></tr></thead><tbody><tr><td colspan="7"><b>None</b></td></tr></tbody></table>							PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER	<b>None</b>					
PART NUMBER	CKT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER														
<b>None</b>																				
27. REWORK BY		ORG	DATE	28. RETESTED BY		ORG	DATE	29. CONTINUATION SHEET USED <input type="checkbox"/>												
ENGINEERING/RELIABILITY	30. CAUSE AND CORRECTIVE ACTION <b>Spec changed per E.C.R. #2512/01R1 to define role of post-gain resistors in D.C. offset voltage measurements. New spec limits are based on calculations that put into consideration.</b>																			
	31. CONTINUATION SHEET USED <input type="checkbox"/>																			
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ECR# TM 2512/01R1, EFFECTIVITY IS 5/1/83 &amp; UP</b>																			
	33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/PAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> DEFECT CODE																			
34. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY		36. RESPONSIBLE ENGINEER <b>W. J. ...</b>												
37. RESPONSIBLE ENGINEER <b>W. J. ...</b>		ORG <b>5174</b>	DATE <b>11/4/81</b>	38. SPACECRAFT SYSTEM ENGINEER <b>W. J. ...</b>		ORG <b>22-61</b>	DATE <b>81/11/86</b>	39. RESPONSIBILITY <b>W. J. ...</b>												
39. RESPONSIBILITY <b>W. J. ...</b>		ORG <b>5174</b>	DATE <b>11/13/81</b>	40. CUSTOMER OR SUPPLIER <b>W. J. ...</b>		DATE <b>11/13/81</b>														

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
FAILURE REPORTORIGINAL PAGE IS  
OF POOR QUALITY**S** 8327

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>1011 TM</b>		2. GLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>FIRST SHFT</b>	5. DATE OBSERVED <b>MO 09 DA 26 YR 81</b>				
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART				
	EQUIPMENT IDENTIFICATION:									
	7. SUBSYSTEM		NAME		PART NUMBER	S/N				
	8. UNIT <b>Electronics Module</b>									
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>Post AMP BAND 4</b>		<b>50904-34</b>		<b>201</b>	<b>SBRL</b>				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD									
	11. OTHER									
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS					
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input checked="" type="checkbox"/> TEMP <b>15</b> °C AXIS FOR	<input type="checkbox"/> THERMAL VAC MIN TYPE					
14. DESCRIPTION OF FAILURE <b>CH. 5, 8, 12, 13 OUT OF SPEC OFFSET VOLTAGE SPANED Be <math>\pm 1.0V</math> IS CH. 5 <math>\pm 1.5V</math>, CH. 8 <math>\pm 2.5V</math>, CH. 12 <math>\pm 1.5V</math>, CH. 13 <math>\pm 1.3V</math>.</b>										
ENGINEERING EVALUATION	15. TEST PROCEDURE <b>16 597</b>		PARA <b>4.4</b>	16. ORIGINATOR <b>C.R. Lee</b>	ORG <b>223</b>	DATE <b>09-26-81</b>				
	17. CONTINUATION <input type="checkbox"/> SHEET USED									
	18. VERIFICATION AND FAILURE ANALYSIS <b>Channels 5, 8, 12, 13 apparently out of spec due to post-gain resistors being lifted during testing.</b>									
	19. FAILED ITEM NAME AND PART NUMBER <b>N/A</b>									
	20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Channels 5, 8, 12, 13 actually meet spec as tested with post-gain resistors out. Refer to ECR #2512/01R1 of spec 16597 Rev J for allowable voltage offsets (See attached for allowable voltage offsets calculations).</b>									
	21. AUTHORIZATION		ORG	DATE	22. CONTINUATION <input type="checkbox"/> SHEET USED					
	23. Rework/Retest ACTION TAKEN		24. QA Rework							
	<b>None Required. No over-stressing of components occurred.</b>		25. QA Retest							
	26. LIST ALL PARTS REPLACED PART NUMBER		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER		
	<b>None</b>									
MANUFACTURING AND TEST	27. Rework BY		ORG	DATE	28. Retested BY		ORG	DATE	29. CONTINUATION <input type="checkbox"/> SHEET USED	
	30. CAUSE AND CORRECTIVE ACTION <b>Spec changed per ECR #2512/01R1 to define role of post-gain resistors in D.C. offset voltage measurements. New spec limits are based on calculations that take gain into consideration. D. Brown 11/19/81</b>		31. FRB CLOSURE							
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ECR #2512/01R1 to spec 16597</b>		33. CONTINUATION <input type="checkbox"/> SHEET USED							
	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	<input type="checkbox"/> UNKNOWN		DEFECT CODE		
	35. FAILURE TYPE <input type="checkbox"/> PRIMARY <input checked="" type="checkbox"/> INDUCED		<input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input checked="" type="checkbox"/> MAJOR		<input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
	37. RESPONSIBLE ENGINEER <b>1112</b>		ORG <b>223</b>	DATE <b>11-18-81</b>	38. SPACECRAFT SYSTEM ENGINEER <b>J. H. Hargis</b>		ORG <b>22-61</b>	DATE <b>01/16/82</b>		
	39. RELIABILITY <b>1112</b>		ORG <b>51-41</b>	DATE <b>11/19/81</b>	40. CUSTOMER OR SUPPLIER <b>FE</b>		DATE <b>11/19/81</b>			
	011873 SC JAN 80									

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8329

1. PROGRAM NAME AND NUMBER <b>17011 TM</b>		2. GLA		3. MODEL <b>FLIGHT FIRST SHFT</b>		4. TIME OBSERVED		5. DATE OBSERVED <b>MO 10 DA 01 YR 81</b>			
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM		<input type="checkbox"/> CARD <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION:											
7. SUBSYSTEM				NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT <b>Electronics Module</b>											
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>BAND 2</b>						<b>50904-2</b>		<b>201</b>		<b>SBRC</b>	
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD											
11. OTHER											
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS											
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RR <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input checked="" type="checkbox"/> TEMP <b>15</b> °C <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER											
14. DESCRIPTION OF FAILURE <b>CH. 3 17.8 OUT OF SPEC ON OFFSET VOLTAGE SHOULD BE <math>\pm 1.0V</math> IS CH. 1 -1.5V, CH. 7 +1.5V, CH. 8 -1.5V</b>											
15. TEST PROCEDURE <b>16597</b>		PARA <b>4.4</b>		16. ORIGINATOR <b>C. R. Lane</b>		ORG <b>2213</b>		DATE <b>10-01-81</b>		17. CONTINUATION SHEET USED <input type="checkbox"/>	
18. VERIFICATION AND FAILURE ANALYSIS <b>Channels 1, 7, 8 apparently out of spec due to the fact that post-gain resistors were out during 16597, Para 4.4 testing.</b>											
19. FAILED ITEM NAME AND PART NUMBER <b>N/A</b>											
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Channels 1, 7, 8 actually meet spec as tested with post-gain resistors out. Refer to E.C.R. #2512/01R1 of spec 16597 Rev J for allowable D.C. voltage offsets. (See attached for voltage offset calculations.)</b>											
21. AUTHORIZATION ORG DATE											
22. CONTINUATION SHEET USED <input type="checkbox"/>											
23. QA REWORK											
24. QA RETEST											
25. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER											
<b>None</b>											
27. REWORK BY ORG DATE											
28. RETESTED BY ORG DATE											
29. CONTINUATION SHEET USED <input type="checkbox"/>											
30. CAUSE AND CORRECTIVE ACTION <b>Spec changed per E.C.R. #2512/01R1 to define role of post-gain resistors in D.C. offset voltage measurements. New spec limits are based on calculations that take gain into consideration. Planned 11/3/81</b>											
31. FRB CLOSURE											
NOTE: REV. J OF SPEC. 16597 INCORPORATES ECR #2512/01R1. EFFECTIVITY IS 5/1/003 & P.											
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ECR #2512/01R1 to spec 16597</b>											
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE											
34. FAILURE TYPE <input type="checkbox"/> PRIMARY INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE											
35. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY											
36. RESPONSIBLE ENGINEER <b>11/3/81</b>											
37. DATE <b>11/1/81</b>											
38. SPACECRAFT SYSTEM ENGINEER <b>11/3/81</b>											
39. CUSTOMER OR SUPPLIER <b>11/3/81</b>											
40. DATE <b>11/11/81</b>											

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8343**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER</b>	2. GLA	3. MODEL <b>PLT</b>	4. TONS OBSERVED	5. DATE OBSERVED <b>MO 2 DA 16 YR 82</b>
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART				
	EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER				
	7. SUBSYSTEM				
	8. UNIT <b>ELECTRONIC MODULE</b>				
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD				
	11. OTHER				
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM				
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION AXIS FOR MIN TYPE <input type="checkbox"/> OTHER				
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE <b>SMA VOLTAGES OUT OF SPEC, 28 VDC <math>\pm 27.5</math>, 7 WDC <math>\pm 6.2</math> SEE ATTACHED DATA SHEET (OPER 1800) CDVU and Radiometer TOLERANCES REVERSED ON HI/LO LINE SPECS - BOTH READINGS OUT OF SPEC</b>				
	15. TEST PROCEDURE <b>16704</b> PARA 4.23.9.26 <b>22-13</b> DATE <b>3-5-82</b> CONTINUATION SHEET USED				
	16. VERIFICATION AND FAILURE ANALYSIS <b>TP 16704 PARA 4.23.9.26 SETS LOW LINE POWER SUPPLY INPUT TO 21 (+5, -0) VDC. SHOULD HAVE BEEN TESTED AT 23 (+5, -0) VDC. CDVU and Radiometer Voltage tolerances should have been reversed.</b>				
	17. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE				
	<b>RETEST PER PARA 4.23.9.26 EO 4180A</b>				
	18. FAILED ITEM NAME AND PART NUMBER				
	21. AUTHORIZATION <b>J.A. Bonach</b> <b>22-13</b> DATE <b>3-5-82</b> CONTINUATION SHEET USED				
	22. REWORK/RETEST ACTION TAKEN <b>PARA 4.23.9.26 PERFORMED SMA +28V READ 30.8VDC SMA -28V READ -30.7VDC BOTH WITHIN SPEC EO 4180A IMPLEMENTED SEE ATTACHED COPY OF TEST DATA SHEET (OPER 1850) EO 4199A CORRECTED NOMENCLATURE AND TOLERANCES - ALL READINGS ARE WITHIN SPEC</b>				
	23. LIST ALL PARTS REPLACED PART NUMBER CXT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER				
	27. REWORK BY ORG DATE 28. RETESTED BY ORG DATE <b>22-13</b> <b>3/5/82</b> CONTINUATION SHEET USED				
MANUFACTURING AND TEST	29. CAUSE AND CORRECTIVE ACTION <b>CAUSE: ELECTRONIC MODULE UNIT TEST PROCEDURE CALLED OUT IMPROPER VOLTAGE SETTINGS PLUS THE CDVU AND Radiometer TOLERANCES WERE REVERSED. C/A: EO 4180A AND 4199A CORRECT THE ELECTRONIC MODULE TEST PROCEDURE. 3/10/82 COPIES OF EO 4180A &amp; 4199A ARE ATTACHED.</b>				
	30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>EO 4180A EO 4199A - EFFECTIVITY 1-10-83</b>				
	31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN				
	32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE <input type="checkbox"/> CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MINOR <input type="checkbox"/> INDUCED <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY				
	33. RESPONSIBLE ENGINEER <b>J.A. Bonach</b> ORG <b>22-13</b> DATE <b>3-9-82</b> <b>J.H. Engel</b> ORG <b>22-41</b> DATE <b>3/10/82</b>				
	34. RELIABILITY <b>51-41</b> DATE <b>3-10-82</b>				
	35. FAILURE CLOSURE				
	36. CONTINUATION SHEET USED				
	37. CONTINUATION SHEET USED				
	38. CONTINUATION SHEET USED				

# HUGHES

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

## SPACE AND COMMUNICATIONS GROUP FAILURE REPORT

ORIGINAL PAGE IS  
OF POOR QUALITY

S 8363

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER</b>		2. GLA		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>10:00</b>		5. DATE OBSERVED <b>MO 1 DA 13 YR 82</b>		
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART										
	EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER										
	7. SUBSYSTEM										
ENGINEERING EVALUATION	8. UNIT										
	9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY										
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <b>BAND 3 Post Amplifier</b> <b>50904-3</b> <b>201</b>										
	11. OTHER										
ENGINEERING EVALUATION	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS										
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER										
	14. DESCRIPTION OF FAILURE <b>NOMINAL GAIN <math>\approx 2.0</math> V.S. SPECIFICATION <math>\approx 3.4</math> FOR EACH CHANNEL. R81 thru R96 ARE <math>\geq 10K</math> OHMS HOWEVER THE 12.1K R21 thru R96 SELECT RESISTORS ARE VALID. THE TEST SPECIFICATION WAS NOT CONSISTENT WITH THE R81 to R96 SELECT RANGE.</b>										
	15. TEST PROCEDURE <b>16704</b> <b>4.19.3</b> <b>BUYER</b> <b>22-13</b> <b>1/13/82</b> 17. CONTINUATION <input type="checkbox"/> SHEET USED										
ENGINEERING EVALUATION	18. VERIFICATION AND FAILURE ANALYSIS <b>Page 50904 SPECIFICATION FOR R81 thru R96 is NOMINAL 3.63K</b> <b>THE TP 16704 PARA 4.19.1 thru 4.19.4 Spec Limits derived from the range of Post Amplifier gains are not consistent with the range of R81 thru R96 pre gain resistors</b>										
	19. FAILED ITEM NAME AND PART NUMBER										
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Correct TP 16704 Para 4.19.1 thru 4.19.4 Spec Limits to conform to pre gain resistor select range.</b>										
	21. AUTHORIZATION <b>JA Bonach</b> <b>22-13</b> <b>1-22-82</b> 22. CONTINUATION <input type="checkbox"/> SHEET USED										
MANUFACTURING AND TEST	23. REWORK/RETEST ACTION TAKEN <b>EO 4059A written to correct spec limits</b> <b>Test data falls within spec limits no retest required.</b>										
	24. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER										
	25. Rework by <b>JA Bonach</b> <b>22-13</b> <b>1-22-82</b> 26. RETESTED BY <b>ORG</b> <b>DATE</b> 27. CONTINUATION <input type="checkbox"/> SHEET USED										
	28. CAUSE AND CORRECTIVE ACTION <b>Cause: PARAGRAPH 4.19.1 THRU 4.19.4 OF TEST PROCEDURE 16704</b> <b>HAD INCORRECT SPEC. LIMITS</b> <b>C/A: EO 4059A CORRECTS SPEC. LIMITS OF TP 16704.</b>										
ENGINEERING/RELIABILITY	29. CONTINUATION <input type="checkbox"/> SHEET USED										
	30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>EO 4059A (COPY ATTACHED)</b>										
	31. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE										
	32. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE 33. FAILURE CLASSIFICATION <input type="checkbox"/> SPACECRAFT SYSTEMS ENGINEER <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY										
ENGINEERING/RELIABILITY	34. RESPONSIBLE ENGINEER <b>JA Bonach</b> <b>22-13</b> <b>1/28/82</b> <b>35. CUSTOMER OR SUPPLIER</b> <b>57-41</b> <b>2/1/82</b> <b>36. DATE</b> <b>2/2/82</b>										
	37. DATE										

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8364

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>11:30 A.M.</b>	5. DATE OBSERVED <b>MO 1 DA 28 YR 82</b>
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input checked="" type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
	EQUIPMENT IDENTIFICATION:					
	7. SUBSYSTEM		NAME		PART NUMBER	S/N
	8. UNIT		NAME		PART NUMBER	S/N
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		NAME		PART NUMBER	S/N
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		NAME		PART NUMBER	S/N
	11. OTHER		NAME		PART NUMBER	S/N
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER <input type="checkbox"/> EMC/RFI <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> JUMP TYPE					
14. DESCRIPTION OF FAILURE <b>WHEN MAIN SHUTTER ON (CMD 13) ISSUED, THE REDUNDANT SHUTTER DRIVER WAS NOT COMMANDED OFF</b>						
ENGINEERING EVALUATION	15. TEST PROCEDURE <b>16704</b>		16. PARA <b>4.12.4.2</b>	18. ORIGINATOR <b>J.A. Bonach</b>	19. CHG <b>22-13</b>	17. CONTINUATION <input type="checkbox"/> SKETCH USED <input type="checkbox"/> DATE <b>1/28/82</b>
	18. VERIFICATION AND FAILURE ANALYSIS <b>THE REDUNDANT SHUTTER DRIVER (51398) COMMAND RELAY'S COIL IS NOT WIRED TO "ORING" DIODES PER 51398 BLUEPRINT. P1-103/104 IS TO CR42-A; P1-107/108 IS TO CR42-C. VOLTAGE ACROSS RELAY COIL DID NOT EXCEED NORMAL OPERATING VOLTAGES. NO OVERSTRESS WAS POSSIBLE.</b>					
	19. FAILED ITEM NAME AND PART NUMBER					
	20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REWORK PER 51398 JUMPER LIST ITEMS 6 AND 9 S/B P1-103/104 TO CR42-C P1-107/108 TO CR42-A</b>					
	21. AUTHORIZATION <b>J.A. Bonach</b>					
	22. CONTINUATION <input type="checkbox"/> SHEET USED <input checked="" type="checkbox"/> DATE <b>1/28/82</b>					
	23. REWORK/RETEST ACTION TAKEN <b>51398 PWB P1-103/104 MOVED TO CR42-C P1-107, 108 MOVED TO CR42-A</b>					
	24. RETESTED PER <b>PARAM 4.12.4.2 CORRECTLY</b>					
	25. LIST ALL PARTS REPLACED					
	26. CONTINUATION <input type="checkbox"/> SHEET USED <input checked="" type="checkbox"/> DATE <b>1/28/82</b>					
MANUFACTURING AND TEST	27. REWORK BY <b>Antonia Sack</b>		28. ORG <b>22-74</b>	29. DATE <b>1/28/82</b>	30. RETESTED BY <b>J.A. Bonach</b>	31. ORG <b>22-13</b>
	32. CAUSE AND CORRECTIVE ACTION <b>CAUSE: Rework planning to remove &amp; resolder connector incomplete. Jumper wires 2 places had to be disconnected &amp; resoldered to do this rework &amp; was not in planning. Inspection not alerted to the need to reverify termination of jumper wires. CORRECTIVE ACTION: Mfg. Eng. Supervisor informed of the error &amp; he has agreed to exercise greater care during future planning operations.</b>		33. FRB CLOSURE			
	34. CONTINUATION <input type="checkbox"/> SHEET USED <input checked="" type="checkbox"/> DATE <b>2/4/82</b>					
	35. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
	36. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN					
	37. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
	38. RESPONSIBLE ENGINEER <b>J.A. Bonach</b>					
	39. RELIABILITY <b>22-13</b>					
	40. DATE <b>1/28/82</b>					
	41. DATE <b>2/4/82</b>					

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
66, SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8365**

1. PROGRAM NAME AND NUMBER <b>THOMAS MAPPER</b>		2. GLA		3. MODEL <b>ET</b>		4. TIME OBSERVED <b>4:00 PM</b>		5. DATE OBSERVED <b>MO 2 DA 3 YR 82</b>	
HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <input type="checkbox"/> PART									
EQUIPMENT IDENTIFICATION		NAME		PART NUMBER		S/N		MANUFACTURER	
7. SUBSYSTEM									
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<b>B4 POSTAMP</b>		<b>50904-4</b>		<b>201</b>			
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE <b>KLERSBURG, CHS 1, 9, 10.</b>									
15. TEST PROCEDURE <b>16368</b>		16. PARA <b>4.12</b>		17. ORIGINATOR <b>Stoneman</b>		18. ORG <b>22-13</b>		19. DATE <b>2-4-82</b>	
20. VERIFICATION AND FAILURE ANALYSIS <b>APPEARS KLERSBURG CAPS NOT ACTUALLY CONNECTED INTO CIRCUIT. MORE INVESTIGATION REQUIRED.</b>		21. FAILED ITEM NAME AND PART NUMBER <b>B4 POSTAMP 50904</b>		22. CONTINUATION SHEET USED <input type="checkbox"/>					
23. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REWORK BY CORRECTING LEAD B, C57, C61, C65, C69.</b>		24. RETEST PER <b>16368 P 4.3.1, 4.3.5, 4.3.7, 4.3.10, 4.3.11, AS NUMBERED IN REV C.</b>		25. AUTHORIZATION <b>Stoneman</b>		26. ORG <b>22-13</b>		27. DATE <b>2-4-82</b>	
28. REWORK/RETEST ACTION TAKEN <b>AS ABOVE. LEAD B OF C57, C61, C65, C69 WAS CORRECTLY PLACED. RETEST WAS DONE. TESTED OK.</b>		29. CONTINUATION SHEET USED <input type="checkbox"/>							
30. LIST ALL PARTS REPLACED PART NUMBER <b>NONE</b>		CKT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
31. PROBABLE DEFECT		ANALYSIS NUMBER							
32. REWORK BY <b>DUNCAN</b>		33. ORG <b>22-13</b>		34. DATE <b>2-4-82</b>		35. TESTED BY <b>Stoneman</b>		36. ORG <b>22-13</b>	
37. CAUSE AND CORRECTIVE ACTION <b>POOR WORKMANSHIP</b>		38. DATE <b>2-4-82</b>		39. CONTINUATION SHEET USED <input type="checkbox"/>					
40. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>ASSEMBLY TECHNICIAN WAS ADVISED OF DISCREPANCY AND CAUTIONED TO CHECK ALL WIRING AND CONNECTIONS THOROUGHLY.</b>		41. FRB CLOSURE							
42. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN		43. DEFECT CODE							
44. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		45. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY							
46. RESPONSIBLE ENGINEER <b>J. J. Bland</b>		47. ORG <b>22-13</b>		48. DATE <b>2/9/82</b>		49. SPACECRAFT SYSTEM ENGINEER <b>Stoneman</b>		50. ORG <b>22-41</b>	
51. RELIABILITY <b>Stoneman</b>		52. ORG <b>57-41</b>		53. DATE <b>2-8-82</b>		54. CUSTOMER OR SUPPLIER <b>Stoneman</b>		55. DATE <b>2/11/82</b>	

# HUGHES

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

## FAILURE REPORT

ORIGINAL PAGE IS  
OF POOR QUALITY

S 8367

1. PROGRAM NAME AND NUMBER <b>TM PL 1162</b>		2. GLA <b>V411</b>		3. MODEL <b>FLT</b>		4. TIME OBSERVED <b>5:30</b>		5. DATE OBSERVED <b>MO 1 DA 19 YR 82</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input checked="" type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM		<input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT									
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD <b>Calibration Station</b> <b>50916</b> <b>201</b> <b>SBR C</b>									
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP <b>0°C</b> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE <b>Shutter Tops Stop on turn on at 0°C Ref. Per 139.5 ms</b>									
15. TEST PROCEDURE <b>16238</b> <b>PARA 3.5.3</b> 16. ORIGINATOR <b>R Evans</b> <b>ORG 2213</b> <b>DATE 1/19/82</b> 17. CONTINUATION SHEET USED <input type="checkbox"/>									
18. VERIFICATION AND FAILURE ANALYSIS <b>Found Saturation Time of AR6-6 gets longer with Cold Temp.</b> <b>Retuned R98 and R90 to correct problem. No Stress To Components</b>									
19. FAILED ITEM NAME AND PART NUMBER									
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Change R98 To 1005K<math>\Omega</math>, Change R90 To 205K<math>\Omega</math></b> <b>ReTest Per 16238 Para 3.5.1, 3.5.2, 3.5.3, 3.5.4, 3.6.1, 3.6.2,</b>									
21. AUTHORIZATION <b>R Evans</b> <b>ORG 2213</b> <b>DATE 1/23/82</b> 22. CONTINUATION SHEET USED <input type="checkbox"/>									
23. REWORK/RETEST ACTION TAKEN <b>Removed and Replaced R98</b> <b>" " " R90</b> <b>ReTest per TP 16238 Para 3.5.1, 3.5.2, 3.5.3, 3.5.4, 3.6.1, 3.6.2,</b>									
24. LIST ALL PARTS REPLACED									
PART NUMBER		CMT SYM		PART LOT NUMBER		DATE CODE		MANUFACTURER	
27. REWORK BY <b>M. Camacho gwh</b> <b>ORG</b> <b>DATE 1/23/82</b> 28. RETESTED BY <b>Joe Alabang KRC</b> <b>ORG 2213</b> <b>DATE 1/26/82</b> 29. CONTINUATION SHEET USED <input type="checkbox"/>									
30. CAUSE AND CORRECTIVE ACTION <b>At Cold Temp. it was found that optimum values had not been selected, therefore we retuned circuit.</b>									
31. FRB CLOSURE									
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION									
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input checked="" type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT									
34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE									
35. RESPONSIBLE ENGINEER <b>J. A. Sanchez</b> <b>ORG 22-13</b> <b>DATE 1/28/82</b> 36. FAILURE CLASSIFICATION <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> SAFETY <input type="checkbox"/> CRITICAL									
37. AIRCRAFT SYSTEM ENGINEER <b>J. A. Sanchez</b> <b>ORG 22-13</b> <b>DATE 1/28/82</b> 38. CUSTOMER OR SUPPLIER <b>5144</b> <b>DATE 2/1/82</b>									



**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8384**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>1700</b>	5. DATE OBSERVED <b>MO 1 OA 26 YR 82</b>		
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART							
	EQUIPMENT IDENTIFICATION: NAME		PART NUMBER	S/N	MANUFACTURER			
	7. SUBSYSTEM							
	8. UNIT <b>ELECTRONICS MODULE</b>		<b>52347</b>	<b>201</b>				
	9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>REDUNDANT SHUTTER DRIVER</b>		<b>51398</b>	<b>201</b>				
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD							
	11. OTHER							
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM							
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER							
ENGINEERING EVALUATION	14. DESCRIPTION OF FAILURE <b>REDUNDANT SHUTTER PHASE LOCK TELEMETRY WORD 6 BIT 6 READS INCORRECTLY "HI" WHEN THE REDUNDANT SHUTTER FUNCTION IS COMMANDED OFF (CMD "OF")</b>							
	15. TEST PROCEDURE <b>TP16704</b>		16. PARA <b>4.12.4.2</b>	18. ORIGINATOR <b>J.A. Banach</b>	19. ORG <b>22-13</b>	17. DATE <b>1-27-82</b>		
	18. VERIFICATION AND FAILURE ANALYSIS <b>REDUNDANT SHUTTER DRIVER (51398) PHASE LOCK SIGNAL U24 PIN 14 DOES NOT HAVE "PULL DOWN" RESISTOR TO ALLOW EXTERNAL RECEIVING TTL I.C. TO READ SIGNAL CORRECTLY WHEN 51398 IS POWERED OFF. "PULL DOWN" RESISTOR R168-B INCORRECTLY WIRED TO U12 PIN 10. SHOULD BE R168-B WIRED TO U12 PIN 11</b>							
	19. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest Not Required Because <b>MOVE R168-B CONNECTED WIRE FROM U12 PIN 10 TO U12 PIN 11</b>		19. FAILED ITEM NAME AND PART NUMBER <b>NONE</b>					
	RETEST PER TP16704 PARA 4.12.4							
	21. AUTHORIZATION <b>J.A. Banach</b>		22. ORG <b>22-13</b>	23. DATE <b>1-27-82</b>	22. CONTINUATION <input checked="" type="checkbox"/> SHEET USED			
	21. REWORK/RETEST ACTION TAKEN <b>REWORKED TO BLUEPRINT AS IN LINE 30</b>		24. REWORK <input checked="" type="checkbox"/>					
	RETESTED PER PARA 4.12.4.2 CORRECTLY		25. CORRECT <input checked="" type="checkbox"/>					
	23. LIST ALL PARTS REPLACED PART NUMBER		CXT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT	ANALYSIS NUMBER
	27. REWORKED BY <b>J.A. Banach</b>		28. ORG <b>22-14</b>	29. DATE <b>1/27/82</b>	28. RETESTED BY <b>J.A. Banach</b>	29. ORG <b>22-13</b>	30. DATE <b>1/28/82</b>	29. CONTINUATION <input type="checkbox"/> SHEET USED
ENGINEERING/RELIABILITY	30. CAUSE AND CORRECTIVE ACTION <b>CAUSE: Incorrect wiring of U12 Pin 11 by assembly personnel and missed during inspection. CORRECTIVE ACTION: 1) Assembly Supervisor was informed of the error and has instructed his assemblers to exercise greater care in the future. 2) Inspection Supervisor also informed of error and has instructed inspectors to exercise greater care in future inspections. (RJR)</b>							
	31. FRB CLOSURE <b>[Signature]</b> <b>2/4/82</b>							
	32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION							
	34. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		35. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE		36. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT		37. DEFECT CODE <input type="checkbox"/> UNKNOWN <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> SAFETY	
	35. FAILURE TYPE		36. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR		37. RESPONSIBLE ENGINEER <b>J.A. Banach</b>		38. DATE <b>22-14 1/28/82</b>	
	37. RESPONSIBLE ENGINEER		38. SPACECRAFT SYSTEM ENGINEER <b>[Signature]</b>		39. ORG <b>55RC</b>		40. DATE <b>2/4/82</b>	
	39. RELIABILITY		40. CUSTOMER OR SUPPLIER					

**HUGHES**

HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

**SPACE AND COMMUNICATIONS GROUP**

**FAILURE REPORT  
CONTINUATION SHEET**

FR SERIAL NO.
58384
COORDINATION EXIST LETTER
A

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED

☐

IDENTIFY ENTRIES BY REFERENCING FR CLOCK NUMBER IN COLUMN DATE EACH ENTRY.

18 MISWIRING REDUCED LOAD ON U24 D. EFFECTIVELY  
R 168 WAS NOT CONNECTED TO GROUND AND DID  
NOT DRAW CURRENT THROUGH U24 D. NO OVERSTRESS  
OCCURRED UP

ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8390**

1. PROGRAM NAME AND NUMBER <b>THEMATIC MAPPER</b>		2. GLA		3. MODEL <b>PLT</b>		4. TIME OBSERVED <b>11 PM</b>		5. DATE OBSERVED <b>MO 2 DA 14 YR 82</b>	
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM <input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <input checked="" type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART									
EQUIPMENT IDENTIFICATION:									
7. SUBSYSTEM		NAME		PART NUMBER		S/N		MANUFACTURER	
8. UNIT		<b>ELECTRONICS MODULE</b>		<b>52347</b>		<b>201</b>			
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY									
10. <input checked="" type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		<b>ELECTRONICS MODULE</b>							
11. OTHER									
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS									
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> HRS AT <input type="checkbox"/> OTHER									
14. DESCRIPTION OF FAILURE		<b>SMA +28V MEASURED 30.8V, SPEC IS 28V TO 30.5VDC</b> <b>SMA -28V MEASURED -30.8V, SPEC IS -28V TO -30.5VDC</b>							
15. TEST PROCEDURE		<b>16704</b>		<b>4239.2</b>		<b>18. ORIGINATOR</b> <b>160420N</b>		<b>19. DATE</b> <b>17 FEB 82</b>	
16. VERIFICATION AND FAILURE ANALYSIS		<b>THE SMA +28V OUTPUTS UNDER FULL LOAD CONDITIONS READ 300 MV OUT OF SPECIFICATIONS AS PREVIOUSLY DEFINED IN POWER SUPPLY DESIGN SPEC. THE POWER SUPPLY BGA DEFINES TS16603 REV B AS CORRECT</b>							
20. <input type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE		<b>MODIFY TEST PROCEDURE TO SPECIFY 28 TO 31 VDC FOR SMA +28V</b> <b>MODIFY TEST PROCEDURE TO SPECIFY -28 TO -31.5 VDC FOR SMA -28V</b> <b>VIA E.O. TO CONFORM TO POWER SUPPLY TEST SPEC 16603 REV B</b>							
21. AUTHORIZATION		<b>J.A. Branch</b>		<b>22. CONTINUATION SHEET USED</b> <input type="checkbox"/>		<b>23. CONTINUATION SHEET USED</b> <input type="checkbox"/>		<b>24. QA Rework</b>	
25. QA RETEST									
26. LIST ALL PARTS REPLACED		PART NUMBER		CKT SYM		PART LOT NUMBER		DATE CODE	
27. REWORK BY		ORG		DATE		28. RETESTED BY		ORG	
29. CAUSE AND CORRECTIVE ACTION		TEST SPECIFICATION INCONSISTENCIES CORRECTED. TOLERANCE INCREASED TO $\pm 28V \pm 3V^{DC}$ TO $28V < V < 31V^{DC}$ AND $-28V < V < -31V^{DC}$		30. CONTINUATION SHEET USED		31. CONTINUATION SHEET USED		32. CONTINUATION SHEET USED	
33. DOCUMENT IMPLEMENTING CORRECTIVE ACTION		<b>EO 4059 A EFFECTIVITY 3/1/82 4059 A (10/7/82)</b>							
34. BASIC CAUSE OF VERIFIED FAILURE		DESIGN <input checked="" type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> DEFECTIVE PARTS		TEST EQUIPMENT <input checked="" type="checkbox"/> TEST PROCEDURE <input checked="" type="checkbox"/> TEST SET-UP		MFG. PROCEDURE <input checked="" type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP		WIRING ERROR <input checked="" type="checkbox"/> ROUGH HANDLING <input checked="" type="checkbox"/> WEAR-OUT	
35. FAILURE TYPE		PRIMARY <input type="checkbox"/> INDUCED		UNKNOWN <input checked="" type="checkbox"/> NO FAILURE		FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR		SAFETY <input checked="" type="checkbox"/>	
36. RESPONSIBLE ENGINEER		<b>J.A. Branch</b>		<b>22-13</b>		<b>DATE</b> <b>2-24-82</b>		<b>37. SPACECRAFT SYSTEM ENGINEER</b> <b>J.A. Branch</b>	
38. APPROVED BY		<b>J.A. Branch</b>		<b>5141</b>		<b>DATE</b> <b>2-25-82</b>		<b>39. DATE</b> <b>2-25-82</b>	

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S 8407**

1. PROGRAM NAME AND NUMBER <b>TM 4011</b>		2. GLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>0930</b>	5. DATE OBSERVED <b>MO 07 DA 15 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input checked="" type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT <b>ELECTRONICS MODULE</b>				<b>52347</b>	<b>3</b>
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY				<b>50904-X</b>	<b>201</b>
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					<b>5326</b>
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input checked="" type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RF		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMP <b>15 °C</b> <input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <b>CH. 5 R 83 IS 60.4K<math>\Omega</math>, SHOULD BE 10.0K<math>\Omega</math>. R 67 IS 10.0K<math>\Omega</math>, SHOULD BE 60.4K<math>\Omega</math>. CH. 14, R 95 IS 20.5K<math>\Omega</math>, SHOULD BE 17.4K<math>\Omega</math>, R 31 IS 17.4K<math>\Omega</math>, SHOULD BE 20.5K<math>\Omega</math></b>					
15. TEST PROCEDURE <b>16597</b>		16. PARA <b>4.5</b>	17. ORIGINATOR <b>C. R. Lane</b>	18. ORG <b>2213</b>	19. DATE <b>07-15-81</b>
20. VERIFICATION AND FAILURE ANALYSIS <b>VISUAL ANALYSIS SHOWS R83 &amp; R67 REVERSED; R31 &amp; R95 REVERSED. R95(PREGAIN) SHOULD HAVE BEEN 17.4K<math>\Omega</math>. R83(PREGAIN) SHOULD HAVE BEEN 10.0K<math>\Omega</math>; R67(ROLLOFF) SHOULD HAVE BEEN 60.4K<math>\Omega</math>. R31(OFFSET) SHOULD HAVE BEEN 20.5K<math>\Omega</math></b>					
21. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REWORK TO PRINT &amp; CONTINUE TEST.</b>					
22. CONTINUATION SHEET USED <input type="checkbox"/>					
23. REWORK/RETEST ACTION TAKEN <b>RESISTORS WERE REINSTALLED PROPERLY. NO OVERSTRESS FOR H5236-7694 AND H5236-7556</b>					
24. QA REVIEW <input checked="" type="checkbox"/>					
25. QA RETEST <input checked="" type="checkbox"/>					
26. ANALYSIS NUMBER					
27. Rework by					
28. RETESTED BY					
29. CONTINUATION SHEET USED <input type="checkbox"/>					
30. CAUSE AND CORRECTIVE ACTION <b>WORKMANSHIP ERROR WHEN MOVING SELECT RESISTORS FROM STANDOFFS TO THE BOARD. MANUFACTURING PERSONNEL HAVE BEEN READVISED TO USE CARE WHEN REMOVING AND REINSTALLING SELECT RESISTORS. INSPECTION PERSONNEL HAVE BEEN INSTRUCTED TO EXERCISE GREATER CARE IN INSPECTING SELECT INSTALLATIONS AND SURROUNDING AREAS.</b>					
31. FRB CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>NONE REQ'D</b>					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input checked="" type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT <input type="checkbox"/> UNKNOWN					
34. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
35. RESPONSIBLE ENGINEER <b>Randall</b>					
36. RESPONSIBLE ENGINEER <b>Randall</b>					
37. RELIABILITY <b>Huber</b>					
38. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR <input type="checkbox"/> SAFETY					
39. DATE <b>11-3-81</b>					
40. DATE <b>11-03-81</b>					
41. DATE <b>11/5/81</b>					

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

MAIN AHR-OP#1300

SPACE AND COMMUNICATIONS GROUP

ORIGINAL PAGE IS  
OF POOR QUALITY**FAILURE REPORT****S 8446**

1. PROGRAM NAME AND NUMBER <b>VC11 T.M.</b>		2. GLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>3:30 P.M.</b>	5. DATE OBSERVED <b>MO 8 DA 6 YR 81</b>
8. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION: NAME PART NUMBER S/N MANUFACTURER					
7. SUBSYSTEM					
8. UNIT <b>ELECTRONICS MODULE 4 DTR 52347</b>					
9. ASSEMBLY <input type="checkbox"/> SUBASSEMBLY <b>BAND 3 POSTAMP SD904A 201 SBRC.</b>					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> INTEGRATION <input type="checkbox"/> LAUNCH OPERATIONS <input checked="" type="checkbox"/> IN-PROCESS <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> SYSTEM					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input checked="" type="checkbox"/> TEMP <b>15. C.</b> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> MRS AT <input type="checkbox"/> EMC/RF <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>CHANNEL 8 prged.</b>					
15. TEST PROCEDURE <b>16597</b> PARA <b>4.5</b> 16. ORIGINATOR <b>N. C. DAVISON</b> ORG <b>2213</b> DATE <b>8-7-81</b> 17. CONTINUATION SHEET USED <input type="checkbox"/>					
18. VERIFICATION AND FAILURE ANALYSIS <b>RESISTORS R28 AND R12 INTERCHANGED</b> <b>R28 (OFFSET ADJ) SHOULD HAVE BEEN 22.5K</b> <b>R12 (BOOST) SHOULD HAVE BEEN 3.65K</b>					
19. FAILED ITEM NAME AND PART NUMBER <b>BAND 3 POST AMP PWB</b>					
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REVERSE R28 AND R12 AND CONTINUE TEST/SELECTION PROCESS.</b>					
21. AUTHORIZATION <b>N. C. DAVISON</b> ORG <b>2213</b> DATE <b>8-7-81</b> 22. CONTINUATION SHEET USED <input type="checkbox"/>					
23. REWORK/RETEST ACTION TAKEN <b>RESISTORS WERE REINSTALLED PROPERLY.</b> <b>NO OVERSTRESS PER HS 236-7691.</b>					
24. QA REVIEW <input type="checkbox"/>					
25. QA REVIEW <input type="checkbox"/>					
26. LIST ALL PARTS REPLACED PART NUMBER CKT SYM PART LOT NUMBER DATE CODE MANUFACTURER PROBABLE DEFECT ANALYSIS NUMBER					
<b>NONE</b>					
27. REWORK BY ORG DATE 28. RETESTED BY ORG DATE 29. CONTINUATION SHEET USED <input type="checkbox"/>					
30. CAUSE AND CORRECTIVE ACTION <b>WORKMANSHIP ERROR WHEN MOVING SELECT RESISTORS FROM STANDOFFS TO BOARD. MANUFACTURING PERSONNEL HAVE BEEN READVISED TO USE CARE WHEN REMOVING AND REINSTALLING SELECT RESISTORS. INSPECTION PERSONNEL HAVE BEEN INSTRUCTED TO EXERCISE GREATER CARE IN INSPECTING SELECT INSTALLATIONS AND SURROUNDING AREAS.</b> <b>J. B. Smith</b>					
31. FAB CLOSURE					
32. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>NONE REQ'D</b>					
33. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST PROCEDURE <input checked="" type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT					
34. FAILURE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> SECONDARY <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
35. FAILURE CLASSIFICATION <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> CRITICAL					
36. SPACECRAFT SYSTEM ENGINEER <b>2261</b> DATE <b>8/11/81</b>					
37. RELIABILITY <b>Q. Huber</b> ORG <b>SI-11</b> DATE <b>11-03-81</b>					



ORIGINAL PAGE IS  
OF POOR QUALITY

58446

SANTA BARBARA RESEARCH CENTER  
*A Subsidiary of Hughes Aircraft Company*

INTERNAL MEMORANDUM

TO: L. O'Connell	CC: Altman, L. Barnett, G.C. Davison, N.C. Randall, D.M. Rangel, J. Wilkerson, R.J. Data Bank (8)	DATE: 26 October 1981 REF: HS 236-7691 REAR 81/53 FROM: A. Huber BLDG. B-11 MAIL STA. 102 EXT. 6246
SUBJECT: FR: S8446 (Band 4 Postamplifier Board, 50904, Flight)		

FR: S8446, dated August 6, 1981

The failure was encountered when retesting Band 4, channel 8, after select resistors were removed from standoffs and placed directly onto the 50904 post-amplifier board. It was found that in moving the resistors to the board, two resistors were interchanged. The resistors were R28 (22.5K, offset) and R12 (3.65K, boost). The resistors were subsequently moved to their proper locations. Figure 1 illustrates the offset and boost circuits which resulted from the interchange of resistors. No overstress occurred.

Andrew E. Huber  
A.E. Huber

AEH:jc

58446





ORIGINAL PAGE IS  
OF POOR QUALITYWASSHOULD HAVE BEEN

FIGURE 1 : OFFSET AND BOOST CIRCUITS RESULTING FROM  
INTERCHANGE OF  $R_{28}$  AND  $R_{12}$ .



**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIAORIGINAL PAGE IS  
OF POOR QUALITY  
SPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**AHR 50904-3  
OPERATION 1300**S 8447**

1. PROGRAM NAME AND NUMBER <b>TM V011</b>		2. GLA	3. MODEL <b>FLIGHT</b>	4. TIME OBSERVED <b>4:30 p.m.</b>	5. DATE OBSERVED <b>MO 7 DA 23 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD <input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MICAM <input type="checkbox"/> PART					
EQUIPMENT IDENTIFICATION:					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT		4			401
9. <input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		BAND 3 POST AMP		50904	SBRC
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD					
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input checked="" type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> RADIATION <input type="checkbox"/> TEMP <b>15. C</b> <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> VIBRATION <input type="checkbox"/> AXIS FOR <input type="checkbox"/> MIN TYPE <input type="checkbox"/> OTHER					
14. DESCRIPTION OF FAILURE <b>CHANNELS 2,3,4,5,6,7,8,10,11,12,14,15 &amp; 16 FAIL TO MEET TRANSIENT AND/OR FREQUENCY RESPONSE REQUIREMENTS</b>					
15. TEST PROCEDURE <b>16597</b>		16. PARA <b>4.6</b>	18. ORIGINATOR <b>A. C. JAYSON</b>	17. CONTINUATION SHEET USED <input type="checkbox"/>	
19. VERIFICATION AND FAILURE ANALYSIS					
20. <input checked="" type="checkbox"/> FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>PLACE THE FOLLOWING RESISTORS ON STANDOFFS AND RESPECT: R2,3,4,6,8,9,10,11,12,13,14,15,16, 66, 67, 68, 70, 72, 73, 74, 75, 76, 77, 78, 79 AND R80.</b>					
21. AUTHORIZATION					
22. CONTINUATION SHEET USED <input type="checkbox"/>					
23. QA Rework					
24. QA RETEST					
25. LIST ALL PARTS REPLACED					
26. Rework by					
27. RETESTED BY					
28. CONTINUATION SHEET USED <input type="checkbox"/>					
29. CAUSE AND CORRECTIVE ACTION <b>Moisture was condensing on the FPA during select testing due to inadequate N2 gas flow onto the FPA. N2 flow has been increased and is now directed to FPA.</b>					
30. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>CO-TTT (Copy ATTACHED), DE 12-23-81</b>					
31. CONTINUATION SHEET USED <input type="checkbox"/>					
32. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN ENVIRONMENTAL DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE ASSY/FAB ERROR WORKMANSHIP <input type="checkbox"/> WIRING ERROR ROUGH HANDLING WEAR-OUT <input type="checkbox"/> UNKNOWN					
33. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY INDUCED <input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE					
34. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input checked="" type="checkbox"/> MINOR SAFETY					
35. SPACECRAFT SYSTEM ENGINEER <b>12/18/81</b>					
36. CUSTOMER OR SUPPLIER <b>12/23/81</b>					

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY**S** 8456

1. PROGRAM NAME AND NUMBER <b>Thermocouple Adapter</b>		2. GLA	3. MODEL <b>FL1</b>	4. TIME OBSERVED <b>16:30</b>	5. DATE OBSERVED <b>MO 11 DA 11 YR 81</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT		<input checked="" type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY		<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD <input type="checkbox"/> PART	
EQUIPMENT IDENTIFICATION:		NAME		PART NUMBER	S/N
7. SUBSYSTEM					
8. UNIT					
9. <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> SUBASSEMBLY					
10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input checked="" type="checkbox"/> CARD		<b>Verification Register</b>		<b>50948</b>	<b>201</b>
11. OTHER					
12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input checked="" type="checkbox"/> ACCEPTANCE		<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS			
13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION		<input checked="" type="checkbox"/> TEMPERATURE <b>0°C</b> MIN TYPE		<input type="checkbox"/> THERMAL VAC HRS AT <input type="checkbox"/> OTHER	
14. DESCRIPTION OF FAILURE <b>WORD G FAILED ONCE DURING DATA CYCLING AT 0°C (6x10<sup>6</sup> CYCLES)</b> <b>PRIMARY WORD G OUTPUT IS X'BD' SHOULD BE X'AD'.</b>					
15. TEST PROCEDURE <b>16422</b>		16. PARA <b>5.4.13</b>	17. ORIGINATOR <b>16422</b>	18. LOG <b>22-13</b>	19. DATE <b>11/11/81</b>
20. VERIFICATION AND FAILURE ANALYSIS <b>NOTE FR 8309 AND SUBSEQUENT AMBIENT TESTING DEALT WITH U31 PIN 7 (G OUTPUT) SHORT TO GROUND BY SOLDER SPLASH ACROSS TRACES, ITS REMOVAL, AND PROPER FUNCTIONING. THE FAILURE OF 1 OF 8 BITS IN WORD G ONCE IN 6x10<sup>6</sup> CYCLES AT 0°C REQUIRES REMOVAL &amp; REPLACEMENT OF U31</b>		21. CONTINUATION <input type="checkbox"/> SHEET USED			
22. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>REMOVE &amp; REPLACE U31 (909940-1)</b>		23. FAILED ITEM NAME AND PART NUMBER <b>U31-546165 = 909940-1</b>			
24. RETEST PER TP 16422 PARA 5.4.3					
25. AUTHORIZATION <b>J.A. Barach</b>		26. ORG <b>22-13</b>	27. DATE <b>11/12/81</b>	28. CONTINUATION <input type="checkbox"/> SHEET USED	
29. REWORK/RETEST ACTION TAKEN <b>U31 REPLACED BY SUPPL. B &amp; RETEST PER 5.4.3 PERFORMED AND NO FAILURES OCCURRED</b>		30. CONTINUATION <input type="checkbox"/> SHEET USED			
31. LIST ALL PARTS REPLACED <b>909940-1</b>		32. CRT SYM <b>U31</b>	33. PART LOT NUMBER	34. DATE CODE	35. MANUFACTURER
36. PROBABLE DEFECT		37. ANALYSIS NUMBER			
38. REWORK BY <b>M. GUERRA</b>		39. ORG <b>22-74</b>	40. DATE <b>12 NOV '81</b>	41. RETESTED BY <b>GUYTON</b>	42. ORG <b>22-13</b>
43. CAUSE AND CORRECTIVE ACTION <b>POSSIBLE U31 MARGINAL FAILURE DUE TO U31-7 TO U31-8 SHORT; OR DUE TO HEATING TRACES AS PREVIOUSLY NOTED SOLDER SPLASH WAS REMOVED.</b> <b>PROBABLE ACTUAL CAUSE OF U31 FAILURE NOT CLEARLY KNOWN.</b> <b>PER FAILURE ANALYSIS REPORT ATTACHED THE U31 DEVICE WAS A RANDOM FAILURE WHICH MADE IT IMPOSSIBLE TO DETERMINE THE CAUSE. REF FR 8309 COPY ATTACHED. NO OVERSTRESS OCCURRED.</b>		44. CONTINUATION <input type="checkbox"/> SHEET USED			
45. DOCUMENT IMPLEMENTING CORRECTIVE ACTION <b>FAILURE ANALYST REPORT #9242 (COPY ATTACHED)</b>		46. FRB CLOSURE <b>11/6/82</b>			
47. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input checked="" type="checkbox"/> DEFECTIVE PARTS		48. TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP		49. MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	
50. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED		51. UNKNOWN <input type="checkbox"/> NO FAILURE		52. CRITICAL CLASSIFICATION <input checked="" type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY	
53. RESPONSIBLE ENGINEER <b>J.A. Barach</b>		54. ORG <b>22-13</b>	55. DATE <b>11-17-81</b>	56. SPACECRAFT SYSTEM ENGINEER <b>J.A. Barach</b>	
57. RELIABILITY <b>EL SEGUNDO</b>		58. ORG <b>51-41</b>	59. DATE <b>1-6-81</b>	60. CUSTOMER OR SUPPLIER <b>11/182</b>	

30 May Dec.  
ORIGINAL PAGE IS  
OF POOR QUALITY

**HUGHES**

HUGHES AIRCRAFT COMPANY  
TECHNOLOGY SUPPORT  
DIVISION

**FAILURE ANALYSIS  
REPORT**

58456

FAR No. 9242  
Program T.M.  
Page 1 of 2

DATE OF RECEIPT <u>12-9-81</u>	TSD PROJECT ENGINEER <u>W. Gettys</u>
REQUESTER <u>F. Carle</u>	PHONE _____ BLDG./MS <u>STD/C346</u>
ORG <u>44-29</u> PHONE <u>80248</u> BLDG./MS <u>S13/D329</u>	GLA/CMER <u>40838</u>
REA _____ PHONE _____	
COMPONENT <u>I.C.</u>	FAILURE REFERENCE <u>FA81-281/FR 58456</u>
FUNCTION/TYPE <u>8-Bit Shift Register</u>	DATE OF FAILURE <u>11-11-81</u>
GENERIC P/N <u>54L165</u>	FAILURE LEVEL <u>Assembly</u>
HUGHES P/N <u>909940-1</u>	LOT NUMBER _____
MFG. <u>National</u> P/N <u>RD30371</u>	CIRCUIT SYMBOL <u>U31</u>
DATE CODE <u>7827</u> S/N <u>1092</u>	MODULE <u>50948</u> S/N <u>201</u>

**ABSTRACT**

The reported failure, wrong output once in  $6 \times 10^6$  cycles and again once in  $1.5 \times 10^6$  cycles, was not confirmed. The device was found to be within all specified d.c. parametric limits. The rareness of the failure reported made it impossible to determine its cause.

TECHNICAL  
COMMENTARY

☒ NOT REQUIRED

☐ APPENDED

M. J. Ditz

FAILURE ANALYST

K2127

JOURNAL

O. E. Limbacher

APPROVAL

12-22-81

DATE

ORIGINAL PAGE IS  
OF POOR QUALITY

FAR. NO. 9242  
PAGE 2 of 2

50456

#### Reported Failure:

"Word G failed once during data cycling at 0°C ( $6 \times 10^6$  cycles). Primary word G is X 'BD' [hexadecimal coded output], should be X 'AD'.

#### Background Information:

"Note FR 8309 and subsequent ambient testing delt with U31 pin 7 ( $\bar{Q}$  output) short to ground by solder splash across traces, its removal, and proper functioning. The failure of 1 of 8 bits in word G once in  $6 \times 10^6$  cycles at 0°C requires removal and replacement of U31."

#### Additional Information:

The device was retested the next day (after the one failure in  $6 \times 10^6$  cycles) for  $1.5 \times 10^6$  cycles. The same failure mode (output X 'BD' instead of X 'AD') was noted again once in the  $1.5 \times 10^6$  cycles.

#### Outline of Analysis:

1. External Visual Examination
2. Electrical Testing
3. Internal Examination

#### Results of Analysis:

1. External Visual Examination.
  - a) Markings: (National Logo) 7827  
RD30371  
-1092
  - b) Case Examination:

The leads were formed and solder tipped and there was orange transparent tape on the bottom of the package. No anomalies were noted externally.

2. Electrical Testing.

The device was tested for d.c. parameters on the Tektronix S-3260 automated I.C. tester per the 909940 specification at +125°C, +25°C, 0°C and -55°C. It was found to be within the specified limits for all of the parameters tested.

3. Internal Examination.

The device was opened and examined internally. No anomalies were noted.

#### Conclusion:

The reported failure was improper output once in  $6 \times 10^6$  cycles and again once in  $1.5 \times 10^6$  cycles. The device was tested for all specified d.c. parameters and passed. No anomalies were noted externally or internally. The extreme rareness of the observed failure made it impossible to determine its cause.

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIASPACE AND COMMUNICATIONS GROUP  
**FAILURE REPORT**ORIGINAL PAGE IS  
OF POOR QUALITY  
**S 8460**

ORIGINATOR	1. PROGRAM NAME AND NUMBER <b>TM</b>		2. GLA	3. MODEL <b>FLT</b>	4. TIME OBSERVED <b>6:00</b>	5. DATE OBSERVED <b>MO 10 DA 2 YR 81</b>	
	6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input type="checkbox"/> SPACECRAFT <input type="checkbox"/> SYSTEM		<input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> UNIT	<input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY	<input type="checkbox"/> MODULE <input type="checkbox"/> MICAM	<input type="checkbox"/> CARD <input type="checkbox"/> PART	
	EQUIPMENT IDENTIFICATION						
	7. SUBSYSTEM		NAME		PART NUMBER	S/N	
	8. UNIT		NAME		PART NUMBER	S/N	
	9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY		NAME		PART NUMBER	S/N	
	10. <input type="checkbox"/> MODULE <input type="checkbox"/> MICAM <input type="checkbox"/> CARD		NAME		PART NUMBER	S/N	
	11. OTHER		NAME		PART NUMBER	S/N	
	12. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS		<input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE	<input type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM	<input type="checkbox"/> LAUNCH OPERATIONS		
	13. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RR		<input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION	<input type="checkbox"/> TEMP AXIS FOR	<input type="checkbox"/> THERMAL VAC HRS AT		
14. DESCRIPTION OF FAILURE <b>Signal was intermittent at pins 177, 178, 175, 176, 179, 180, 173, and 174. No signal was present at pins 77, 78, 79, 80, 75, 76, 81, 82.</b>							
ENGINEERING EVALUATION	15. TEST PROCEDURE <b>16596</b>		PARA <b>5.3</b>	10. ORIGINATOR <b>Joe Kleeberg</b>	ORG <b>22-13</b>	DATE <b>10/3/81</b>	
	16. VERIFICATION AND FAILURE ANALYSIS <b>INTEGRATED CIRCUITS AR1 and AR2 assembled and installed upside down. No overstress to other board components. Japanese "11/1/81".</b>						
	17. FOLLOWING REWORK/RETEST REQUIRED <input type="checkbox"/> Rework/Retest Not Required Because <b>Remove and Replace correctly AR1 and AR2. Perform test procedure 16596 Rev A para 5.2 and 5.3.</b>						
	18. AUTHORIZATION <b>J. A. Barach</b>						
	19. FAILED ITEM NAME AND PART NUMBER <b>AR1, AR2 909992-1</b>						
	20. REWORK/RETEST ACTION TAKEN <b>AR1 and AR2 removed and replaced per D/P. Retested per test procedure 16596 Rev A para 5.2 and 5.3.</b>						
	21. LIST ALL PARTS REPLACED PART NUMBER <b>909992-1</b>						
	22. REWORK BY <b>L. TORRES</b>						
	23. CAUSE AND CORRECTIVE ACTION <b>AR1 and AR2 installed incorrectly. More cautious initial visual check would identify problem prior to powering board. MEETINGS WERE HELD WITH MFG AND QA IMPORTANT TO REVIEW THIS PROBLEM TO PREVENT REOCCURRENCE.</b>						
	24. DOCUMENT IMPLEMENTING CORRECTIVE ACTION						
MANUFACTURING AND TEST	25. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS		<input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP	<input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP	<input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR-OUT	<input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE	
	26. FAILURE TYPE <input checked="" type="checkbox"/> PRIMARY <input type="checkbox"/> NOUCED		<input type="checkbox"/> UNKNOWN <input type="checkbox"/> NO FAILURE	27. FAILURE CLASSIFICATION <input type="checkbox"/> CRITICAL <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR <input type="checkbox"/> SAFETY			
	28. RESPONSIBLE ENGINEER <b>J. A. Barach</b>		ORG <b>22-73</b>	DATE <b>10-7-81</b>	29. SPACECRAFT SYSTEM ENGINEER <b>J. A. Barach</b>		
	30. RELIABILITY <b>57-44</b>		ORG <b>11-3-81</b>	DATE <b>11-3-81</b>	31. CONTINUATION <input type="checkbox"/> SHEET USED		
	32. CONTINUATION <input type="checkbox"/> SHEET USED						
	33. CONTINUATION <input type="checkbox"/> SHEET USED						
	34. CONTINUATION <input type="checkbox"/> SHEET USED						
	35. CONTINUATION <input type="checkbox"/> SHEET USED						
	36. CONTINUATION <input type="checkbox"/> SHEET USED						
	37. CONTINUATION <input type="checkbox"/> SHEET USED						
ENGINEERING/RELIABILITY	38. CONTINUATION <input type="checkbox"/> SHEET USED						
	39. CONTINUATION <input type="checkbox"/> SHEET USED						
	40. CONTINUATION <input type="checkbox"/> SHEET USED						
	41. CONTINUATION <input type="checkbox"/> SHEET USED						
	42. CONTINUATION <input type="checkbox"/> SHEET USED						
	43. CONTINUATION <input type="checkbox"/> SHEET USED						
	44. CONTINUATION <input type="checkbox"/> SHEET USED						
	45. CONTINUATION <input type="checkbox"/> SHEET USED						
	46. CONTINUATION <input type="checkbox"/> SHEET USED						
	47. CONTINUATION <input type="checkbox"/> SHEET USED						

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

**FAILURE REPORT****S 8464**ORIGINAL PAGE IS  
OF POOR QUALITY

1. PROGRAM NAME AND NUMBER <b>TM PL 1162</b>		2. GLA	3. MODEL <b>F1</b>	4. TIME OBSERVED <b>1615</b>	5. DATE OBSERVED <b>MO 6 DA 27 YR 82</b>
6. HARDWARE LEVEL WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> SPACECRAFT <input type="checkbox"/> SUBSYSTEM <input type="checkbox"/> ASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> CARD		<input type="checkbox"/> SYSTEM <input type="checkbox"/> UNIT <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> WICAM <input type="checkbox"/> PART			
EQUIPMENT IDENTIFICATION					
7. SUBSYSTEM		NAME		PART NUMBER	S/N
8. UNIT		NAME		PART NUMBER	S/N
9. <input type="checkbox"/> ASSEMBLY <input checked="" type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MODULE <input type="checkbox"/> WICAM <input checked="" type="checkbox"/> CARD		NAME		PART NUMBER	S/N
10. OTHER		NAME		PART NUMBER	S/N
11. TEST WHEN FAILURE WAS OBSERVED <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> IN-PROCESS <input type="checkbox"/> QUALIFICATION <input type="checkbox"/> ACCEPTANCE <input checked="" type="checkbox"/> INTEGRATION <input type="checkbox"/> SYSTEM <input type="checkbox"/> LAUNCH OPERATIONS					
12. ENVIRONMENT WHEN FAILURE WAS OBSERVED <input checked="" type="checkbox"/> AMBIENT <input type="checkbox"/> EMC/RFI <input type="checkbox"/> RADIATION <input type="checkbox"/> VIBRATION <input type="checkbox"/> TEMP <input type="checkbox"/> THERMAL VAC <input type="checkbox"/> IRS AT <input type="checkbox"/> OTHER					
13. DESCRIPTION OF FAILURE <b>RI offset out of spec. Should be -4.00 ± 0.20V DC. Act. Ch: 3 4 6 10 14 15 V: -4.26V -4.46 -4.34 -7.17 -4.23 -4.55.</b>					
14. TEST PROCEDURE <b>32015 512 Current 22-17-82-06-27</b>					
15. VERIFICATION AND FAILURE ANALYSIS <b>No overstress was induced. No parts failed. All components were within Spec. limits. Unit was in test configuration.</b>					
16. FOLLOWING REWORK/RETEST REQUIRED <input checked="" type="checkbox"/> REWORK/RETEST NOT REQUIRED BECAUSE <b>Repeat Resistor selection process and retest.</b>					
17. AUTHORIZATION <b>For N Current 22-13 6/28/82</b>					
18. REWORK/RETEST ACTION TAKEN <b>New select resistors were installed. Retested successfully ON 6-28-82</b>					
19. LIST ALL PARTS REPLACED					
PART NUMBER	CYT SYM	PART LOT NUMBER	DATE CODE	MANUFACTURER	PROBABLE DEFECT
908600-256	R-18				None
908600-88	R-98				"
908600-253	R-24				"
20. REWORK BY <b>L.C. TAMEL (GPO)</b>					
21. CAUSE AND CORRECTIVE ACTION <b>INITIAL RESISTOR SELECTION ALLOWED A BUILDUP OF TOLERANCE TO DRIVE OFFSETS OUT OF SPEC. FOR CH 3, 4, 6, 14, &amp; 15. CH 10 WAS APPARENTLY A POOR CHOICE OF INITIAL RESISTOR, ALTHOUGH STILL WITHIN RANGE. NEW VALUES RESELECTED FOR R 18, 98, 24, 104, 26, 106, 27, 107, 29, 109, 31, AND 111.</b>					
22. DOCUMENT IMPLEMENTING CORRECTIVE ACTION					
23. BASIC CAUSE OF VERIFIED FAILURE <input type="checkbox"/> DESIGN <input type="checkbox"/> ENVIRONMENTAL <input type="checkbox"/> DEFECTIVE PARTS <input type="checkbox"/> TEST EQUIPMENT <input type="checkbox"/> TEST PROCEDURE <input type="checkbox"/> TEST SET-UP <input type="checkbox"/> MFG. PROCEDURE <input type="checkbox"/> ASSY/FAB ERROR <input type="checkbox"/> WORKMANSHIP <input type="checkbox"/> WIRING ERROR <input type="checkbox"/> ROUGH HANDLING <input type="checkbox"/> WEAR OUT <input type="checkbox"/> UNKNOWN <input type="checkbox"/> DEFECT CODE					
24. FAILURE TYPE <input type="checkbox"/> PRIMARY <input type="checkbox"/> INDUCED <input type="checkbox"/> UNKNOWN <input checked="" type="checkbox"/> NO FAILURE					
25. RESPONSIBLE ENGINEER <b>L.C. TAMEL</b>					
26. SPECIALIST ENGINEER <b>L.C. TAMEL</b>					
27. RELIABILITY <b>51 41 6-29-82</b>					

ORIGINAL PAGE IS  
OF POOR QUALITY

58464

TEST DATA RECORD

DATE 6/23/82 (7) \$MS  
SCANNER F1 BAND 1

NOTE: VALUES ARE FROM  
LISTS 52732-22(R17→R32)  
#52732-85(R97→R112)

4.2 SELECT RESISTOR VALUES

			VALUE	DESIRED VALUE	ACHIEVED TOTAL
	Band ①	908 #		(k $\Omega$ )	(k $\Omega$ )
✓ R 17	908600	-252 ✓	20.5K	20.9K	20902
✓ R 97		-88 ✓	402		
✓ R 18		-256 ✓	22.6K	23.1	23099
✓ R 98		-07 ✓	499		
✓ R 19		-258 ✓	23.7K	23.8	23300
✓ R 99		-30 ✓	100		
✓ R 20		-250 ✓	19.6K	19.8	19510
✓ R 100		-59 ✓	200		
✓ R 21		-251 ✓	20.0K	20.1	20100
✓ R 101		-30 ✓	100		
✓ R 22		-254 ✓	21.5K	21.5	21500
R 102		SHORT ✓	0		
✓ R 23		-258 ✓	23.7K	24.2	24199
✓ R 103		-97 ✓	499		
✓ R 24		-254 ✓	21.5K	21.5	215
R 104		SHORT ✓	0		
✓ R 25		-258 ✓	23.7K	24.0	24001
✓ R 105		-76 ✓	301		
✓ R 26		-256 ✓	22.6K	22.7	22700
✓ R 106		-30 ✓	100		
✓ R 27		-258 ✓	23.7K	23.8	23300
✓ R 107		-30 ✓	100		
✓ R 28		-256 ✓	22.6K	22.7	22700
✓ R 108		-30 ✓	100		
✓ R 29		-254 ✓	21.5K	21.8	21801
✓ R 109		-76 ✓	301		
✓ R 30		-253 ✓	21.0K	21.1	21100
✓ R 110		-30 ✓	100		
✓ R 31		-255 ✓	22.1K	22.5	22502
✓ R 111		-88 ✓	402		
✓ R 32		-253 ✓	21.0K	21.1	21100
✓ R 112		-30 ✓	100		

OK *LSR*

SIZE A	CODE IDENT NO 11323	NUMBER 17010
SCALE	REV <i>A</i>	SHEET 4 OF 5

58464

REF. F/R # 8464

RE-SELECTS. operation 300 of Supp 15 (5804-1).

TEST DATA RECORD

DATE

6/28/82

ORIGINAL PAGE IS  
OF POOR QUALITY

SCANNER

51065 S/N003 (50904-1 s/n 101)

## 4.2 SELECT RESISTOR VALUES

Band	908600 -	1	2	3	4
R 17					
R 97					
R 18 - 256		22.6 K			
R 98 - 88		402 $\Omega$			
R 19					
R 99					
R 20					
R100					
R 21					
R101					
R 22					
R102					
R 23					
R103					
R 24 - 253		21.0 K			
R104 - 98		402 $\Omega$			
R 25					
R105					
R 26 - 256		22.6 K			
R106 - 30		100 $\Omega$			
R 27 - 258		23.7 K			
R107 - 30		100 $\Omega$			
R 28					
R108					
R 29 - 251		20.0 K			
R109 - 97		499 $\Omega$			
R 30					
R110					
R 31 - 255		22.1 K			
R111 - 3076		301 $\Omega$			

Shonaker  
6-28-82C. R. Lane  
06-28-82  
T. C. Lane  
06-28-82

SIZE A	CODE IDENT NO. 11323	NUMBER 17010
SCALE	REV A	SHEET 4 of 5



58464

ORIGINAL PAGE IS  
OF POOR QUALITY

4.2 Offset Voltage Measurements after Select Resistors  
Installed.

Band	1	2	3	4
Ch				
1	—	—	—	—
2	—	—	—	—
3	-4.16	—	—	—
4	-4.01	—	—	—
5	—	—	—	—
6	-3.99	—	—	—
7	—	—	—	—
8	—	—	—	—
9	—	—	—	—
10	-3.99	—	—	—
11	—	—	—	—
12	—	—	—	—
13	—	—	—	—
14	-4.12	—	—	—
15	-4.06	—	—	—
16	—	—	—	—

Technician.

CPL 00-2587  
Slusher

Date

6-28-82

QA

M. V. [Signature]

Date

6-28-82

52

REA

Slusher

Date

6-28-82

REF R#8464  
Test Verification Supp#15 operation #900 (52)

SIZE	CODE IDENT NO.	NUMBER
A	11323	17010
SCALE	REV A	SHEET 5 OF 5

**HUGHES**HUGHES AIRCRAFT COMPANY  
SPACE AND COMMUNICATIONS GROUP  
EL SEGUNDO, CALIFORNIA

SPACE AND COMMUNICATIONS GROUP

FAILURE REPORT  
CONTINUATION SHEET

FR SERIAL NO.

58464

CONTINUATION SHEET LETTER

A

\*LABEL FIRST CONTINUATION SHEET USED 'A', SECOND 'B', AND SO ON

IDENTIFY ENTRIES BY REFERENCING FR BLOCK NUMBER IN COLUMN, DATE EACH ENTRY.

ADDITIONAL FR  
CONTINUATION  
SHEET(S) USED

26	PT. NO.	CIRCUIT SYMBOL	PROBABLE DEFECT
	908600-88	R 104	None
	908600-256	R 26	"
	908600-30	R 106	"
	908600-258	R 27	"
	908600-30	R 107	"
	908600-251	R 29	"
	908600-97	R 109	"
	908600-255	R 31	"
	908600-111	R-76	"

ORIGINAL PAGE IS  
OF POOR QUALITY

ORIGINAL PAGE IS  
OF POOR QUALITY

58464

TEST DATA RECORD

DATE

6/23/82 (7) & MS

SCANNER

F1 BAND 1

NOTE: VALUES ARE FROM  
LISTS 52732-22(R17-R32)  
# 52732-85 (R97-R112)

4.2 SELECT RESISTOR VALUES

Band ① 908 #

		VALUE	DESIRED VALUE	ACHIEVED TOTAL
			(k $\Omega$ )	(k $\Omega$ )
R 17	908600	-252 ✓	20.9K	20902
R 97		-88 ✓	402	
R 18		-256 ✓	22.6K	23099
R 98		-97 ✓	499	
R 19		-258 ✓	23.7K	23900
R 99		-30 ✓	100	
R 20		-250 ✓	19.6K	19810
R100		-59 ✓	200	
R 21		-251 ✓	20.0K	20100
R101		-30 ✓	100	
R 22		-254 ✓	21.5K	21500
R102		SHORT ✓	0	
R 23		-258 ✓	23.7K	24199
R103		-97 ✓	499	
R 24		-254 ✓	21.5K	215
R104		SHORT ✓	0	
R 25		-258 ✓	23.7K	24001
R105		-76 ✓	301	
R 26		-256 ✓	22.6K	22700
R106		-30 ✓	100	
R 27		-258 ✓	23.7K	23500
R107		-30 ✓	100	
R 28		-256 ✓	22.6K	22700
R108		-30 ✓	100	
R 29		-254 ✓	21.5K	21801
R109		-76 ✓	301	
R 30		-253 ✓	21.0K	21100
R110		-30 ✓	100	
R 31		-255 ✓	22.1K	22512
R111		-88 ✓	402	
R 32		-253 ✓	21.0K	21100
R 112		-30 ✓	100	

OK LSP

SIZE A	CODE IDENT NO 11323	NUMBER 17010
SCALE	REV A	SHEET 4 OF 5

58464

REF. F/R # 8464

RE-SUBS. operation 300 of Supp 15 (58464-1)

TEST DATA RECORD

ORIGINAL PAGE IS  
OF POOR QUALITY

DATE

6/28/82

SCANNER

51065 S/N 003 (50904-1 sh 101)

## 4.2 SELECT RESISTOR VALUES

Band

908600-

1

2

3

4

R 17

R 97

R 18

R 98

R 19

R 99

R 20

R 100

R 21

R 101

R 22

R 102

R 23

R 103

R 24

R 104

R 25

R 105

R 26

R 106

R 27

R 107

R 28

R 108

R 29

R 109

R 30

R 110

R 31

R 32

R 33

R 34

R 35

R 36

R 37

R 38

R 39

R 40

R 41

R 42

R 43

R 44

R 45

R 46

R 47

R 48

R 49

Stonaker  
6-28-82C. P. Lane  
06-28-82  
06-28-82

SIZE	CODE IDENT NO.	NUMBER
A	11323	17010
SCALE	REV	SHEET
	4	4 of 5

58464

ORIGINAL PAGE IS  
OF POOR QUALITY

4.2 Offset Voltage Measurements after Select Resistors  
Installed.

Band	1	2	3	4
Ch				
1	-			
2	-			
3	-4.16			
4	-4.01			
5				
6	-3.99			
7	-			
8	-			
9	-			
10	-3.99			
11	-			
12	-			
13	-			
14	-4.12			
15	-4.06			
16	-			

Technician CH 06-28-82 Date 6-28-82  
 QA [Signature] Date 6-28-82 52  
 REA [Signature] Date 6-28-82

REF FR#8464  
 Test Verification Supp# 15 operation #900 52

SIZE A	CODE IDENT NO. 11323	NUMBER 17010
SCALE	REV A	SHEET 5 OF 5

2.13

ORIGINAL PAGE IS  
OF POOR QUALITY

SECTION 2.13  
CABLE HARNESS

2.13.1

ORIGINAL PAGE IS  
OF POOR QUALITY

2.13.1 Cable Harness

2.13.1.1

No performance data was taken at the subsystem level on this  
subsystem.

2.13.2

ORIGINAL PAGE IS  
OF POOR QUALITY

2.13.2

Acceptance Data



2.13.2.1

ORIGINAL PAGE IS  
OF POOR QUALITY

2.13.2.1  
Configuration Lists

# AS-BUILT CONFIGURATION LIST

R=RECORD CHANGE

CABLE ROUTING ASSY  
52348(3569647)S/N005

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEP. REVISION	AS-BUILT REVISION	SERIAL NUMBER
01	52348	CABLE ROUTING ASSY	F 3844A	F 3844A	F 3844A	005
01	3569647	WIRING HARNESS INSTALLATION	C 27724 70534 70538 70543 70550 70561	C 27724 70534 70538 70543 70550 70561	C 27724 70534 70538 70543 70550 70561	005
02	3569641	WIRING HARNESS	E 27722 27723 D042 REV1 D057 D060 D062 D063	E 27722 27723 D042 REV1 D057 D060 D062 D063	E 27722 27723 D042 REV1 D057 D060 D062 D063	005
03	DP50326	DPS ASSY OF AMP CONNECTORS	B SCN 1 2 3 4	B SCN 1 2 3 4	B SCN 1 2 3 4	ORIGINAL PAGE IS OF POOR QUALITY
02	3569642	WIRE, JUMPER	9494	9494	9494	
02	3569643	CONNECTOR	- D064	- D064	- D064	

52348(3569647) S/N005

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
02	3569646	WIRING DIAGRAM	B 27727 27732 R70552 70557 70564 70567	B 27727 27732 70557 70564 70567	B 27727 27732 70552 70557 70564 70567	
02	3569649	RF BACKSHELL	-	-	-	
02	3449442	EYELET	-	-	-	
02	ICL3569638-1	INTERCONNECT LIST	A 27721 27726 27735 27737	A 27721 27726 27735 27737	A 27721 27726 27735 27737	
02	TP32015-036-1	TP OF ELECTRICAL WIRING HARNESS	A SCN 1 27738	A SCN 1 27738	A SCN 1 27738	
02	16232	CABLE, SHIELDED	A	A		
02	52349	STRUCTURE ASSY-ELECT.	C 1987A	C 1987A	C 1987A	
02	52361	GASKET, CONNECTOR	A 8151	A 8151	A 8151	
02	52365	PLATE, CONNECTOR-RIU	A 1961A 3275A	A 1961A 3275A	A 1961A 3275A	
02	52366	PLATE CONNECTOR	A 8065	A 8065	A 8065	
02	52753	THERMISTOR BLOCK	D 3794A	D 3794A	D 3794A	301

ORIGINAL PAGE IS  
OF POOR QUALITY

52348(3569647) S/N005

IND LVL	PART NO.	NOMENCLATURE	CURRENT REVISION	ACCEPT. REVISION	AS-BUILT REVISION	SERIAL NUMBER
02	52839	CONNECTOR, RECEPTACLE	D 2087A 2748A	D 2087A 2748A	D 2087A 2748A	
02	52930	CAP & RELAY BD ASSY	E 2977A 3807A	E 2977A 3807A	E 2977A 3807A	202
02	53160	TERMINAL BD ASSY	B	B	B	201
02	53653	PLATE, FILTER MOUNT	A	A	A	
02	53710	TERMINAL BD POWER	C 3255A	C 3255A	C 3255A	
02	53711	PLATE, POWER SUPPLY	A	A	A	
02	53927	GROMMET, PLASTIC EDGE	A	A	A	
02	52923	TERMINAL BD ASSY	B 9369	B 9369	B 9369	201
02	54012	HEATER ASSY	A 2398A	A 2398A	A 2398A	201
02	54185	RETAINER, CABLE	A 1886A	A 1886A	A 1886A	
02	54233-1	SW THERMOSTAT ASSY	A 3504A	A 3504A	A 3504A	202
02	54257	+/-2 SMA CONTROL RES	A 2925A	A 2925A	A 2925A	203
02	653307	TERMINAL LUG, SOLDER	-	-	-	
02	16268	PS FOR SURFACE MOUNTED COMPONENTS	A 2216A 2940A 3080A 3283A	A 2216A 2940A 3080A 3283A	A 2216A 2940A 3080A 3283A	

ORIGINAL PAGE IS  
OF POOR QUALITY

ORIGINAL PAGE IS  
OF POOR QUALITY

HARNES

P/N 52348

FLIGHT

Failure Reports Number

Open	Closed

Deviation

Waivers

--	--

**P/N 52348**

FLIGHT  
Failure Report  
No. \_\_\_\_\_

PROTOFLIGHT  
Failure Report  
No.

ENGINEER  
Failure Report  
No. \_\_\_\_\_

Open	Closed	Open	Closed	Open	Closed
			F3022 F3023 F3024 F5190 F8022		

ORIGINAL PAGE IS  
OF POOR QUALITY

.Listing of Liens

There were no liens recorded against the  
Harness Assembly.



**END  
DATE  
FILMED**

AUG 5 1983